

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5297S**AAD2001-055***Not Authorised**11 Rmp & 8050h*

Vehicle No.:

Chassis No.:

08 JAN 2020

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5297S

VF1ABL15AUC276744

RENAULT

LATITUDE

6.1.2020

AIG

21-03-14

		PART
1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	BUMPER BLOCK LH REAR
14	1	BUMPER BLOCK RH REAR
15	1	BUMPER HARNESS REAR
16	1	BOOT REAR
17	1	BOOT FINISHER
18	1	BOOT WHEATERSTRIP
19	1	BOOT REFLECTOR LAMP LH
20	1	BOOT REFLECTOR LAMP RH
21	1	BOOT BADGE 'RENAULT'
22	1	BOOT BADGE
23	1	BOOT STRUT LH
24	1	BOOT STRUT RH
25	1	BOOT HINGE LH
26	1	BOOT HINGE RH
27	1	BOOT TRIM BOARD

		LIST
\$	Bu	561.70 ✓
\$	Da	411.90 ✓
\$	Sn	98.10 X
\$	Sn	82.10 X
\$	Sn	59.80 X
\$	Sn	16.60 X
\$	Di	80.80 —
\$	Di	54.20 —
\$	CM	16.60 —
\$	B	547.80 ✓
\$	B	114.50 —
\$	R	100.90 X
\$	Sn	75.70 X
\$	Sn	76.50 X
\$	Sn	301.10 X
\$	B	1,677.20 ✓
\$	Sn	344.70 X
\$	Di	178.20 502.20 89.00 Sn
\$	CM	277.70 ✓
\$	Sn	277.70 X
\$	Sn	82.40 —
\$	Sn	95.80 —
\$	Sn	145.10 X
\$	Sn	145.10 X
\$	R	254.20 X
\$	R	253.80 X
\$	Sn	611.00 X

Trans-cab Auto Services Pte Ltd**AAD2001-055**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5297S

28	1	BOOT SWITCH	\$	<i>SL</i>	113.00	}	X
29	1	BOOT LOCK	\$	<i>R</i>	246.60		
30	1	BOOT LOCK CATCH	\$	<i>R</i>	41.70		
31	2	LICENCE PLATE LAMP	\$	<i>SL</i>	26.30		
32	2	BOOT RUBBER PLUG	\$	<i>SL</i>	139.30		
33	1	BOOT LOCK LINKAGE	\$	<i>SL</i>	20.60		
34	1	BOOT LOCK LINKAGE HOLDER	\$	<i>SL</i>	99.50		
35	1	TAILLAMP RH	\$	<i>R</i>	313.10		
36	1	TAILLAMP PANEL RH	\$	<i>R</i>	401.40	}	
37	1	TAILLAMP LH	\$	<i>CM</i>	401.40		
38	1	TAILLAMP PANEL LH	\$	<i>R</i>	401.40	X	
39	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i>	745.80		
40	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i>	404.56	}	X
41	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i>	1,229.40		
42	1	SPARE WHEEL PANEL TRIM	\$	<i>SL</i>	612.21		
43	1	SPARE TYRE BOARD	\$	<i>SL</i>	680.90		
44	1	EXHAUST REAR	\$	<i>R</i>	5,263.60		
45	1	EXHAUST CAP REAR	\$	<i>R</i>	125.40		

TOTAL	\$	18,207.37
10%	\$	1,820.74
	\$	16,386.63

Special Nett

1	1SET	PARKING AID	\$	<i>SL</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>NC</i>	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>NC</i>	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>NC</i>	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>NC</i>	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>NC</i>	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>NC</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>NC</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>NC</i>	66.00	—
10	1	EXHAUST MOUNTING REAR	\$	<i>NC</i>	16.00	X
11	1	EXHAUST BRACKET REAR	\$	<i>NC</i>	24.80	X
12	1SET	BOOT FINISHER CLIP	\$	<i>NC</i>	24.20	X

Trans-cab Auto Services Pte Ltd**AAD2001-055**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 52975

13	1	BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	—
14	1	BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	—
15	1	BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i>	385.00	X
17	1	SPARE TYRE	\$	<i>sn</i>	330.00	X
18	1	TAILLAMP CLIP RH	\$	<i>na</i>	5.00	X
19	2	REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00	X
20	1	WINDSCREEN MOULDING	\$	<i>na</i>	100.00	—
21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	3000
22	1	TAILLAMP CLIP LH	\$	<i>na</i>	5.00	—
23	1	Rear Bumper Protector	\$	<i>na</i>	100.00	4000
24	1SET	Rear licence plate with holder	\$	<i>sn</i>	80.00	X
25	1	REAR RENAULT TYRE 215/60/16	\$	<i>sn</i>	300.00	X
26	1	REAR RENAULT TYRE RIM	\$	<i>sn</i>	380.00	X

TOTAL \$ 2,982.00**TOTAL PARTS \$ 19,368.63****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	<i>8801</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	<i>12001</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>901</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 52975**AAD2001-055**

To repair and realign rear exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 100%
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	120%
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	60%
To Check Electrical Lighting Concerned.	\$	170.00	20%
Towing Fees	\$	~ 150.00	X

TOTAL \$ 18,380.00**Over All Total \$ 37,748.63****(LUMP SUM) Repair Days****25 DAYS**
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: