

**CAS GARAGE PTE LTD**

(Reg No: 20182806/M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATEInsurance Company: INDIA INTERNATIONAL INSURANCE PTE LTD
(MOTOR CLAIMS DEPARTMENT)Address: 64, CEDDIL STREET, #04-05
IOB BUILDING, S(049711)

Cecilia

Telephone: 63476100

Fax: 62244174

Email motorclaim@iii.com.sg

Make/ Model : VOLKSWAGEN JETTA

Date: 10.01.2020

Chassis No : WVWZZZ16ZDM040082

Vehicle No: SKH9770D

Date/Time of Accide 08.01.2020/1700

Date of Reg: 31.01.2013

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	REAR FENDER <i>Dented</i>	1	\$ 1,759.30	\$ 1,759.30
2	REAR FENDER INNER SHIELD <i>new</i>	1	\$ 178.60	\$ 178.60
3	REAR WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 80.00	\$ 80.00
4	REAR TAILAMP LH <i>new</i>	1	\$ 685.20	\$ 685.20
5	REAR BUMPER <i>Dented</i>	1	\$ 1,392.50	\$ 1,392.50
6	REAR BUMPER SIDE RETAINER <i>new</i>	1	\$ 105.20	\$ 105.20
7	REAR BUMPER ATTACHMENT RETAINER <i>new</i>	1	\$ 105.60	\$ 105.60
8	FRONT DOOR LH <i>new</i>	1	\$ 1,963.50	\$ 1,963.50
9	REAR DOOR LH <i>Dented</i>	1	\$ 1,562.30	\$ 1,562.30
10	REAR DOOR INNER TRIM LH <i>Repaired</i>	1	\$ 987.60	\$ 987.60
11	REAR DOOR SPEAKER LH <i>new</i>	1	\$ 180.00	\$ 180.00
12	REAR DOOR INNER TRIM LH <i>new</i>	1	\$ 558.20	\$ 558.20
13	REAR DOOR WEATHERSTRIP (DOOR) LH <i>new</i>	1	\$ 168.50	\$ 168.50
14	REAR DOOR WEATHERSTRIP (FRAME) LH <i>new</i>	1	\$ 245.60	\$ 245.60
15	REAR DOOR INNER LOCK LH <i>new</i>	1	\$ 375.60	\$ 375.60
16	REAR DOOR CATCH LH <i>new</i>	1	\$ 56.30	\$ 56.30
17	REAR DOOR OUTER MOLDING LH <i>new</i>	1	\$ 154.20	\$ 154.20
18	REAR DOOR OUTER HANDLE LH <i>new</i>	1	\$ 125.30	\$ 125.30
19	REAR DOOR OUTER HANDLE COVER LH <i>new</i>	1	\$ 54.20	\$ 54.20
20	SIDE ROCKER PANEL LH <i>new</i>	1	\$ 985.60	\$ 985.60
21	REAR RIM LH <i>new</i>	1	\$ 850.20	\$ 850.20
22	REAR UPPER ARM LH <i>new</i>	1	\$ 305.80	\$ 305.80
23	REAR LOWER ARM LH <i>new</i>	1	\$ 480.50	\$ 480.50
24	REAR CONTROL ARM LH <i>new</i>	1	\$ 437.80	\$ 437.80
25	REAR KNUCKLE ARM LH <i>new</i>	1	\$ 818.10	\$ 818.10
26	REAR WHEEL HUB BEARING LH <i>new</i>	1	\$ 425.60	\$ 425.60
27	REAR ABSORBER LH <i>new</i>	1	\$ 548.90	\$ 548.90
28	REAR WHEEL SPEED SENSOR LH <i>new</i>	1	\$ 195.80	\$ 195.80
Total List Price Cost				\$ 15,786.00
PARTS DISCOUNT 10%				\$ 1,420.74

883280

7949.52

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR WINDSCREEN SEALANT <i>per</i>	1SET	\$ 80.00	\$ 80.00
2	REAR TYRE LH <i>per</i>	1	\$ 220.00	\$ 220.00
3	REAR FENDER INNER SHIELD CLIPS <i>per</i>	1SET	\$ 50.00	\$ 50.00
4	REAR BUMPER CLIPS <i>per</i>	1 SET	\$ 30.00	\$ 30.00
5	REAR DOOR INNER TRIM CLIPS <i>per</i>	1 SET	\$ 30.00	\$ 30.00
6	REAR DOOR CUSTOMIZED STICKER <i>per</i>	1 SET	\$ 200.00	\$ 200.00
Total Special Nett Items				\$ 610.00

240

Labour Works/ Panel Beating Related Works		Quotation
Job Scope		
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE AL		\$ 1,800.00
Spray Painting		Quotation
Job Scope		
TO RESPRAY AFFECTED AREAS		\$ 1,800.00
Others Cost (Accident Repair Related Expenses)		Quotation
Job Scope		
TO TUFFCOAT AFFECTED AREA		\$ 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY		\$ 150.00
TO APPLY SEALANT TO THE AFFECTED AREAS		\$ 150.00
TO REMOVE/ REFIT WIRING CHECKS ON REAR TAILAMP		\$ 120.00
TO CONDUCT WATER LEAKAGE TEST		\$ 150.00
TO REMOVE/ REPLACE /REFIT REAR UNDERCARRIAGE		\$ 180.00
TO REMOVE /REFIT REAR WINDSCREEN		\$ 120.00
TO PERFORM COMPUTERISED WHEEL ALIGNMENT (BEFORE & AFTER)		\$ 160.00
TO REMOVE /REPLACE TRANSFER REAR DOOR MECHANISM		\$ 120.00
Total Others Cost		\$ 1,350.00
GRAND TOTAL		\$ 19,767.40

GAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7171

Email: allan@casgarage.sg

Fax: +65 6509 9501

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 of 2

Adrian Lj
w/s 10/01/20

08 Days

total 111952

w/s: 8.9K

(8.9K)