

Kh

Date: 08.01.2020
Vehicle No: SMD8410Y
Model: TOYOTA SIENNA HYBRID 1.5G
Chassis: NHP1707109698 - 2017
Reg.Year: 2018

Third Party Insurer: AIG
Third Party Veh No: SMN1909U
Date of Accident: 07.01.2020

① 4270-35

NOT Authorized
Personnel By paint

6 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>1088</i>	1		<i>Pr</i> \$1,186.50 ✓
2	REAR TAILGATE "HYBRID" EMBLEM	1		<i>Ne</i> \$65.60 ✓
3	REAR TAILGATE INNER LOCK <i>430</i>	1		<i>Ne</i> \$452.70 ✓
4	REAR TAILGATE RUBBER	1		<i>Pr/Ne</i> \$356.60 ✓
5	REAR TAILGATE INNER TRIM CLIPS	8	\$6.20	<i>Ne</i> \$49.60 X
6	REAR WINDSCREEN RUBBER	1		<i>Ne</i> \$112.00 ✓
7	REAR TAILGATE PULL HANDLE	1		<i>Ne</i> \$58.40 ✓
8	REAR END PANEL UPPER COVERING <i>207</i>	1		<i>Pr</i> \$376.80 ✓
9	REAR END PANEL UPPER COVERING CLIPS	6	\$6.20	<i>Ne</i> \$37.20 ✓
10	REAR BUMPER <i>485.00</i>	1		<i>Pr</i> \$1,178.60 ✓
11	REAR BUMPER SIDE COVER LH	1		<i>Pr</i> \$67.20 X
12	REAR BUMPER CLIPS	8	\$5.50	<i>Ne</i> \$44.00 ✓
13	REAR FLOOR PANEL TRAY BOX			<i>Free</i> \$674.40 X
14	REAR FLOOR PANEL TRAY BOX UPPER BOARD <i>321.00</i>			<i>Ne</i> \$472.40 ✓
15	REAR BUMPER COVER <i>171.00</i>			<i>Pr</i> \$396.20 ✓
16	REAR END PANEL			REPAIR
SUB TOTAL				\$5,528.20
LESS 25%				-\$1,382.05
PARTS TOTAL				\$4,146.15

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>Ne</i> \$60.00 <i>40.50</i>
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>Pr</i> \$30.00 X
3	REAR BUMPER REVERSE SENSOR LH	1		<i>Ne</i> \$350.00 <i>200.50</i>
S/N TOTAL				\$440.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 08.01.2020
 Vehicle No: SMD8410Y
 Model: TOYOTA SIENTA HYBRID 1.5G
 Chassis: NHP1707109698 - 2017
 Reg.Year: 2018

Third Party Insurer: AIG
 Third Party Veh No: SMN1909U
 Date of Accident: 07.01.2020

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE , REPLACE , REPAIR, READJUST REAR ACCIDENT AREAS & ETC	\$500.00 ✓
LABOUR CHARGES TO REMOVE, REPLACE, READJUST, REAR BUMPER REVERSE SENSOR & ETC	\$80.00 <i>50</i>
LABOUR CHARGES TO REMOVE & REFIX, REPLACE REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE & ETC	\$150.00 <i>120</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC	\$800.00 <i>750</i>
LABOUR CHARGES TO CHECK WIRING & ELECTRICAL WIRING SYSTEMS & ETC	\$80.00 <i>20</i>
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATION	\$150.00 <i>60</i>
LABOUR TOTAL	\$1,760.00
<hr/> ONG	<hr/> TOTAL
	\$6,346.15

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

