

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/s Thl Building Construction Pte Ltd 49 Kaki Bukit View
Survey on 10-10-30 am 15/1/20		Document No 0	Singapore 415973 Attn: Mr Teo Hee Lai
Summer CLK 67418434		Document Date 09/01/2020	Mobile: 98483188

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEUGH	L1	GSF50R	30/01/2018	SLW0977T	0	18103 4UL/SLW0977T/28121!
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB4LFF705000959	8GR9508717	60	Wally Tan G H	30/12/2019	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPCSN3004231900 ACC DATE:28.12.19 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50. 80.00
2	B	BP-LAB3 REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR. (NETT)				✓ 866.00
3	S	BP-SUBLET INSTALLING SOLAR FILM FOR REAR WINDSHIELD. (NETT)				✓ 420.00
4	B	BP-LAB3 REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR. (NETT)				✓ 433.00
5	B	BP-LAB3 REMOVE/REFIX INTERIOR UPHOLSTERY, ROOF LINING, REAR SPEAKER BOARD, TRIMMINGS, GARNISHS, FRONT AND REAR SEATS, SEAT BELTS, FLOOR CARPETS IN ORDER TO FACILITATE REPAIR. (NETT)				✓ 866.00
6	B	BP-LAB3 CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)				✓ 216.50

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Tanpin 97495749 Not Authorise 15/1/20 @ 10.30. Less Ex \$2000. Reserving before paint.
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 09/01/2020
TIME 12:51

VEHICLE NO SLW0977T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motor**

Inchcape

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/s Thi Building Construction Pte Ltd 49 Kaki Bukit View Singapore 415973 Attn: Mr Teo Hee Lai Mobile: 98483188
	Document No 0	
	Document Date 09/01/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEUGH	L1	GSF50R	30/01/2018	SLW0977T	0	18103 4UL/SLW0977T/28121

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHB4LFF705000959	8GR9508717	60	Wally Tan G H	30/12/2019 0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
7	B	BP-LAB3 REMOVE/REFIX REVERSE SENSORS. (NETT)				216.50
8	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN L/R BODY PANEL, CUT AND WELD PANEL AND FIT NEW PARTS. 866			3464	4330.00
9	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. 742			1484	1855.00
10	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)				216.50
11	1	L64801-50900 GLASS SUB-ASSY, BACK	1.00	2047.50	nei	2047.50
12	2	L75571-50080 MOULDING, BACK	1.00	79.10	nei	79.10
13	3	L56119-50100 SEAL, WINDSHIELD	1.00	37.50	nei	37.50
14	4	L56117-24070 DAM, WINDOW GLASS	6.00	4.40	nei	26.40
15	5	L56118-50070 DAM, WINDOW GLASS	1.00	22.50	nei	22.50
16	6	T04562-12010 W/SCREEN DAM KIT,	1.00	121.00	nei	121.00
17	7	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00	nei	216.00
18	8	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00	nei	200.00
19	9	L61602-50110 PANEL SUB-ASSY,	1.00	1596.60	bt	1596.60
20	0	T62940-12170 L/R QUARTER AIR DUCT,	1.00	136.20	Xnn	136.20
21	1	L81561-50311 LENS & BODY, RR	1.00	1342.10	One	1342.10
22	2	L81498-50040 COVER, RR	1.00	58.90	nei	58.90

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 09/01/2020
TIME 12:51

VEHICLE NO SLW0977T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motor



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/s Thl Building Construction Pte Ltd 49 Kaki Bukit View Singapore 415973 Attn: Mr Teo Hee Lai Mobile: 98483188
	Document No 0	
	Document Date 09/01/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEUGH	L1	GSF50R	30/01/2018	SLW0977T	0	18103 4UL/SLW0977T/28121

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHB4LFF705000959	8GR9508717	60	Wally Tan G H	30/12/2019	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
23	3	T81536-52C80 LED, RR COMBINATION	1.00	152.10	? Xnn	152.10
24	4	L76817-26040 CLIP, BACK DOOR	1.00	3.50	nec	3.50
25	5	L81496-60010 GUIDE, RR	1.00	3.50	nec	3.50
26	6	L81496-52020 GUIDE, RR	1.00	2.50	nec	2.50
27	7	L52156-50080 SUPPORT, RR BUMPER	1.00	114.90	nec	114.90
28	8	L52563-50060 RETAINER, RR BUMPER,	1.00	115.60	nec	115.60
29	9	L52568-50060 RETAINER, RR BUMPER	1.00	64.60	nec	64.60
30	0	L52566-50080 RETAINER, RR BUMPER,	1.00	302.00	nec	302.00
31	1	L52159-50938 COVER, RR BUMPER	1.00	1108.60	de	1108.60
32	2	L75895-28010 TAPE, MOULDING, NO.1	2.00	50.40	nec	100.80
33	3	L52181-50030 ARM, RR BUMPER	4.00	24.60	? nec	98.40
34	4	L52162-50907 PIECE, RR BUMPER, LH	1.00	25.90	? nec	25.90
35	5	L52753-50010 MOULDING, RR BUMPER	1.00	277.40	cut	277.40
36	6	L52169-50070 COVER, RR BUMPER,	1.00	518.50	? de	518.50
37	7	L75392-35220 RETAINER OUTSIDE	18.00	-3.90	nec	70.20
38	8	S52161-0K040 BUMPER CLIPS	8.00	-4.10	nec	32.80
39	9	T90467-07215 CLIP	8.00	-2.50	nec	20.00
40	0	L89348-50130 RETAINER, ULTRASONIC	4.00	-19.20	nec	76.80
41	1	L89348-58130 CLIP, ULTRASONIC	2.00	12.30	nec	24.60
42	2	L81920-50020 REFLECTOR ASSY,	1.00	48.80	? Xnn	48.80

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 09/01/2020
TIME 12:51

VEHICLE NO SLW0977T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motor

**TAX INVOICE**Co Reg No : 196700086Z
GST R No : MR 8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/s Thi Building Construction Pte Ltd 49 Kaki Bukit View Singapore 415973 Attn: Mr Teo Hee Lai Mobile: 98483188
	Document No 0	
	Document Date 09/01/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEUGH	L1	GSF50R	30/01/2018	SLW0977T	0	18103 4UL/SLW0977T/28121

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHB4LFF705000959	8GR9508717	60	Wally Tan G H	30/12/2019	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
43	3	L88162-50041 SENSOR, BLIND SPOT	1.00	2001.40	7 Xnn	2001.40
44	4	L88173-50010 COVER, BLIND SPOT	1.00	81.50	7 X nn	81.50
45	5	T08826-08115 PANEL BONDING AD	1.00	267.20	nei	267.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 11,395.40	20,894.90
		Labour 9,079.50	GST 7.00% 1,462.64
		Materials 420.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 22,357.54

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 09/01/2020
TIME 12:51

VEHICLE NO SLW0977T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motor