

22/03/2002

ASS. REC. BY:

REF: CS/CT1 20000638 / uqf3ⁿ²

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Ivan Tay Hui Ping of CT1 Date/Time: 9.20.20 17.31p.m

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 2422m Insured: PC 2022T

at Workshop m/s Lin's Brother Tel: 67411730

of BIK 1 Kaki Bukit Ave 6 #01-01 Autobay

Policy No: DMBISN 19137919000 Claim No: SVM 190205912008

Sum Insured: Excess:

Make of Veh: D.O.A. 15/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.1.20 9.44a.m Person Contacted: Susan Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 2422m - CCB / AIG 160187931429397 RM - 05/04/2016
	PC 2022T - X

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CT11

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LYA 5227

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBC 2422M

Yr Regn:

9 / 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hilux

C.C.

2982

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

268760

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P000076961

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Austone

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

15/11/19

D.O.I.

10/11/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/1/20

L/S 2200 confirmed with Suban. (Red 3777, 63%)

RECEIVED 13 JAN 2020

Date/Time, File Pass to?

☐

Preli. Report

1) 13/1/2020

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS. \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format:

MER 7P

Lump Sum / I.B.I. (\$

2200

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2020		09 Jan 2020 17:31 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	GOLDBELL LEASING PTE LTD		
Vehicle Reg. No.:	GBC2422M	Date of Loss:	15/11/2019 17:00 - :59
Claim Type:	TP / SNM19D205912C02	Policy/Cover Note No.:	DMB1SN19137919000
Vehicle Reg. No. (Insured):	PC2022T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/01/2020]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 9 January 2020 5:16 PM
To: liusbro@ymail.com
Cc: assignments; Admin A
Subject: FW: OUR REF: SNM19D205912/PC2022T/IRENE - Request for 3rd party claims survey GBC2422M Claims against PC2022T
Attachments: GBC2422M191115.pdf; IMG_0004.pdf

Dear Sir (LKK),

We refer to the above matter.

Please get your surveyor to liaise with LIU'S BROTHER to conduct survey.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Thursday, January 9, 2020 3:36 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; liusbro@ymail.com
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OUR REF: SNM19D205912/PC2022T/IRENE - Request for 3rd party claims survey GBC2422M Claims against PC2022T

Dear Irene,

Please conduct PRS for GBC2422M.

Note : officer in charge - Irene Tay 63896192

***** Kindly quote our reference number when replying.**

Thank You.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Susan Low [mailto:liusbro@gmail.com]
Sent: Thursday, 9 January, 2020 2:52 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Request for 3rd party claims survey GBC2422M Claims against PC2022T

Accident on 15/11/2019 Along MCE / KPE

Involving GBC2422M and PC2022T

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:- _____
Name of Authorise Surveyor:- _____
Surveyor Email: _____
Remark :- _____



Pirelli P Zero
255/45/R19
Performance
Tyre



To Enhance
The Interior
Look Of Your
Car



Re-Usable &
Washable
Performance
Filter



DVD Player
8" Monitor
Screen with
GPS

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

1933 Ford Hot Rod, Flathead V8.



1933 Ford Tudor Hot Rod,
Original Henry Ford Steel,
Second Owner, Very Reliable.
Direct Owner StarAd

• Free VICOM evaluation
 • Free grooming and 6 months maintenance
 • In-house workshop ensures quality service
 • Member of SVTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

15 vehicles

Toyota Hiace

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Hiace		Any	Any	2011	Any	Any	Any	Available
	Toyota Hiace	Commuter 3.0A High Roof	\$25,800	\$13,770 /yr	25-Nov-2011	2,982 cc	-	Bus	Available
Fuel Type: Diesel One Owner Only, Low Mileage, High Roof Commuter Bus, Auto Gear, Auto Sliding Door, Excellent Condition, Well Maintained By Previous... SG Motor Link Pte Ltd Posted: 10-Jan-2020 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace	Commuter 3.0A GL	\$23,000	\$12,330 /yr	22-Nov-2011	2,982 cc	-	Bus	Available
Fuel Type: Diesel 14 Seaters High Roof Bus. New Original Seater, New Print Work Is Done. Posted: 08-Jan-2020 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace	3.0M (New 5-yr COE)	\$31,800	\$6,350 /yr	24-Jun-2011	2,982 cc	-	Van	Available
Fuel Type: Diesel One Owner, New Paintwork, Low Mileage Engine Gearbox Tip Top Condition. High Loan Available. Trade In Welcome. See To Believe, C... Net Link Partners Pte Ltd Posted: 08-Jan-2020 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace	Commuter 3.0A High Roof (New 5-yr COE)	\$35,800	\$7,150 /yr	08-Jun-2011	2,982 cc	-	Bus	Available
Fuel Type: Diesel Price With New 5 Years COE. New Paint. Recently Serviced. New Road Tax. Highest Offer Secures. Posted: 07-Jan-2020 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Hiace 3.0A \$26,000 \$22,760 /yr 03-Mar-2011 2,982 cc - Bus Available

Fuel Type: Diesel
 Consignment Unit, Loan Available. Bank And In House Loan Available. Very Good Condition. Well Known For Its Durability And Low Main...
 Prem Roy Motoring

Posted: 07-Jan-2020 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0M \$23,800 \$16,390 /yr 24-Jun-2011 2,982 cc - Van Available

Fuel Type: Diesel
 Condition Tip-Top. Don't Feel Like 9 Years Vehicle. Previous 1 Owner Taken Care Well. Strong Engine, Cold Air-con. View To Believe. Sp...
 Car (S) Pte Ltd

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 196N

Vehicle Details

Vehicle No.: GBC2422M
Vehicle to be Exported: No
Intended Deregistration Date: 23 Nov 2019
Vehicle Make: TOYOTA
Vehicle Model: HIACE MANUAL
Primary Colour: White
Manufacturing Year: 2011
Engine No.: 1KD2108015
Chassis No.: JTFHT02P000076961
Maximum Power Output: -
Open Market Value: \$25,820.00
Original Registration Date: 12 Sep 2011
First Registration Date: 12 Sep 2011
Transfer Count: 1
Actual ARF Paid: \$1,291.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 Sep 2021
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$29,006.00
COE Rebate Amount: \$5,227.00
Total Rebate Amount: \$5,227.00

The information contained herein is correct as at 23 Nov 2019

OK

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBC2422M19115

Estimate

Customer

Name: China Taiping Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Date:

09-01-20

Vehicle No:

GBC2422M

Model/Make:

Toyota Hiace

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate	\$ 1,456.00	
2	Tailgate Weatherstrip	\$ 395.10	X
3	Tailgate Inner Lock	\$ 359.00	X
4	Tailgate Number Plate Lamp Outer Garnish	\$ 346.50	X
5	Tailgate "70 KM/H" Sticker	\$ 15.00	SN 10 S.N
6	Tailgate "8 Pax" Sticker	\$ 15.00	SN 10 S.N
7	Tailgate Number Plate "Metal"	\$ 28.00	SN X
8	Bumper	\$ 599.30	X
9	Bumper Clips 1 set	\$ 48.00	X
10	Bumper Reverse Sensor	\$ 220.00	SN X
11	End Panel Outer	\$ 566.10	X
12	Tailgate Windscreen Moulding	\$ 219.00	X
13	Tailgate Windscreen Sealant	\$ 50.00	SN 40 S.N
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	520
	To putty & spray painting & including touch up paint on accident area	\$ 600.00	400
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 60.00	30
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 5,977.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

Liu's Auto Consultants hence notify the Repairer of the following:

- To respray before/after spray painting
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party claim is on a "Without Prejudice" basis
- No claim discount is allowed
- Supplementary parts must be resubmitted and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
2/5 2200/
Take photo After repair
3 day.
10/1/20

P-2103.30
254
P-1577.47
S.N-60.00
L-1130.00
2767.47
202
2213.97

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20000638/UQF3N2
Date: 15/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN19137919000
Claimant Vehicle No: GBC2422M Insured Vehicle No: PC2022T
Date of Loss: 15/11/2019 Nature of Claim: TP Claim No: SNM19D205912C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC2422M Engine No: 1KD2108015
Make & Model: TOYOTA HIACE, 3.0 D (M) Chassis No: JTFHT02P000076961
Reg. Date: 12/09/2011 (Man. Year: 2011) Odometer: 268760 km
Colour: Silver
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15 Rear Tyre Size: 195R15
Front Left Side: Austone 6 mm Rear Left Side: Austone 6 mm
Front Right Side: Austone 6 mm Rear Right Side: Austone 6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,317.00	1,637.47	2,679.53	62.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,130.00	530.00	31.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,977.00	2,767.47	3,209.53	53.70
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	5,977.00	2,200.00	3,777.00	63.19

INSPECTION

Date of Assignment: 09/01/2020
Date Inspected: 10/01/2020 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)
Estimated Period of Repair: 3.0 days KAKI BUKIT
Singapore 417883

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Jan 2020)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC2422M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,456.00 F	*1,456.00 FL
2	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	395.10 F	*- FL
3	1		*REAR TAILGATE INNER LOCK	Not Necessary	359.00 F	*- FL
4	1		*REAR TAILGATE NUMBER PLATE LAMP OUTER GARNISH	Not Necessary	346.50 F	*- FL
5	1		*REAR BUMPER	Deformed	599.30 F	*599.30 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
7	1		*REAR END PANEL OUTER	Repair	566.10 F	*- FL
8	1		*REAR TAILGATE WINDSCREEN MOULDING	No such part	219.00 F	*- FL
9	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
10	1		*REAR TAILGATE 8 PAX STICKER	Necessary	15.00 FS	*10.00 FS
11	1		*REAR TAILGATE NUMBER PLATE METAL	Not Necessary	28.00 FS	*- FS
12	1		*REAR BUMPER REVERSE SENSOR	Serviceable	220.00 FS	*- FS
13	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
				Sub Total (S\$)	4,317.00	2,163.30
				- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	525.83
				Total Parts (S\$)	4,317.00	1,637.47

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00
2	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETC	New	800.00	520.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AREA	New	600.00	400.00
4	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	30.00
5	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS	New	120.00	120.00
Gross Labour Cost (\$\$)			1,660.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >