



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD

Ref : CS/SGK20000649/Gvd3s2

C/O : SEDGWICK SINGAPORE PTE LTD 30 CECIL STREET, LEVEL 12 PRUDENTIAL TOWER SINGAPORE 049712

Date : 20-01-2020



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLL 4299Z
Policy No.	G2000186	Coverage (\$)	0.00
Claim No.	IA2020-50251/TWC	Excess (\$)	0.00
Assign From	WEE CHIAU TAN	Assign Date	09/01/2020

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER 2.0XT	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JF1SJGK85EG039648	Colour	BLACK
Odometer	119568	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/12/2019	Inspection Date	10/01/2020
Survey held at	160 SIN MING DRIVE# 04-06		
Repairer	CARPLUS AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-----------------------