

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

TP Budget Direct.
 Xino Chen

ESTIMATE

Repair Code : CLM15932

Date in : 09/01/2020

Vehicle Num. : SLS4186D

Model : TOYOTA PRIUS ALPHA 1.8S CVT

Chassis/Eng# : ZVW400026189/2ZR1990727

Contact : 88215151 96558663

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR <i>Repair</i>	1	1218.20	X 1,218.20
FRONT LH DOOR FRAME BLACK STICKER	1	121.10	✓ 121.10
FRONT LH DOOR INNER PLASTIC SEAL COVER <i>} new</i>	1	68.20	✓ 68.20
FRONT LH DOOR VERTICAL GARNISH <i>Not new</i>	1	151.30	X 151.30
LH SIDE ROCKER PANEL GARNISH <i>cauled.</i>	1	722.50	✓ 722.50
REAR BUMPER <i>Rebond</i>	1	523.00	✓ 523.00
REAR BUMPER SIDE RETAINER L/R <i>LH new</i>	2	98.00	98 X 98.00
REAR LH BUMPER END SEAL COVER <i>new</i>	1	92.30	X 92.30
REAR LH DOOR <i>Dented.</i>	1	1279.10	✓ 1,279.10
REAR LH DOOR FRAME BLACK STICKER <i>new</i>	1	171.45	✓ 171.45
REAR LH DOOR INNER TRIM BOARD <i>cauled.</i>	1	737.90	✓ 737.90
REAR LH DOOR PLASTIC SEAL COVER <i>new</i>	1	68.20	✓ 68.20
REAR LH DOOR VERTICAL GARNISH <i>Not new</i>	1	172.45	X 172.45
REAR LH DOOR WEATHER STRIP <i>Not new</i>	1	274.40	X 274.40
REAR LH SPORT RIM <i>bt.</i>	1	1555.00	600(SW) 1,555.00
REAR LH WHEEL CAP <i>Missing</i>	1	378.30	✓ 378.30
REAR LH WHEEL HUB BEARING <i>Dented.</i>	1	781.90	✓ 781.90

*** This is a computer-generated document which requires no signature.***

4949.65

3712.23 S.N. 600.

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 88215151 96558663

ESTIMATE

Repair Code : CLM15932

Date in : 09/01/2020

Vehicle Num. : SLS4186D

Model : TOYOTA PRIUS ALPHA 1.8S CVT

Chassis/Eng# : ZVW400026189/ZZR1990727

			Subtotal before discount	8,511.30
				2,127.83
Percentage discount	25%			
			Sub-total 1	6,383.48
LH SIDE ROLLER PANEL GARNISH CLIPS - SET	Neu	1	50.00	30 50.00
REAR BUMPER CLIPS - SET	Neu	1	50.00	1 50.00
REAR LH BUMPER END SEAL COVER CLIPS - SET	Neu	1	20.00	1 20.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET	Neu	1	50.00	30 50.00
REAR LH TYRE	Not price	1	380.00	X 380.00
			Subtotal before discount	550.00
				0.00
Percentage discount	0%			
			Sub-total 2	550.00
			Parts-total	6,933.48

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor. ✓ 50.00

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc. 60 150.00

To road test driving, check and resetting wheel alignments system. 770 80 100.00

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle. 80 200.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. 1000 1,300.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. 500 800.00

To apply anti-rust chemical on repaired and replaced panel. X 80.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature.***

Labour Total

2,680.00

Parts & Labour Total

9,613.48

total 6142.23

4/5 4.91K OS Dmg

Acknowledged by Repairer

Signature:

Date: