

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000661/KDS3Q2

Date: 28/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBH2737D **Insured Vehicle No :** SMJ6001B

Date of Loss: 08/01/2020 **Nature of Claim:** TP **Claim No:** 4401519713SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH2737D		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2791889
Reg. Date:	09/04/2018 (Man. Year: 2018)	Chassis No:	JTFAT35Y30K210082
Colour:	Silver	Odometer:	108898 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	155R12X8 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Falken 5/5 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Falken 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,544.30	2,544.30	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,260.00	340.00	21.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,144.30	3,804.30	340.00	8.20
+ GST 7.00/7.00% (S\$)	290.10	266.30	23.80	8.20
Nett Amount (S\$)	4,434.40	4,070.60	363.80	8.20
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		4,478.60		
Global Sum Settlement (S\$)		4,450.00		

INSPECTION

Date of Assignment: 09/01/2020

Date Inspected: 10/01/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,161.70 FL	*1,161.70 FL
2	1		*TAILGATE STICKER TOYOTA	Necessary	215.67 FL	*215.67 FL
3	1		*TAILGATE STICKER DYNA	Necessary	39.80 FL	*39.80 FL
4	1		*TAILGATE RH SAFETY LOCK	Distorted	110.20 FL	*110.20 FL
5	1		*TAILGATE RH LOCK HANDLE	Bent	89.90 FL	*89.90 FL
6	1		*TAILGATE STOPPER	Dented / Cut	33.80 FL	*33.80 FL
7	2		*TAILLAMP	Cracked	445.40 FL	*445.40 FL
8	2		*TAILLAMP PANEL	Bent	203.60 FL	*203.60 FL
9	1		*REAR NUMBER PLATE PANEL	Bent	180.70 FL	*180.70 FL
10	1		*REAR EXHAUST PIPE	Bent	598.30 FL	*598.30 FL
11	1		*STICKER 70KM/HR	Necessary	10.00 FS	*10.00 FS
12	1		*REAR NUMBER PLATE	Bent	25.00 FS	*25.00 FS
13	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,314.07	3,314.07
- List Item Discount on L Items 25.00/25.00% (\$)	769.77	769.77
Total Parts (\$)	2,544.30	2,544.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX TAILGATE ASSY ,TAILLAMPS & PANEL ,REAR NO PLATE LAMP & PANEL ,TO STRAIGHTEN ,KNOCKING & REPAIR REAR END PANEL ,REAR STEP BAR ,REAR TRUNK END FLOORBOARD & REALIGN POSITION	New	800.00	600.00
2	PUTTY & RESPRAY ON TAILGATE ,REAR TRUNK END PANEL ,FLOORBOARD PANEL ,NUMBER PLATE PANEL TAILLAMP PANEL,LOCK HANDLE & ALL AFFECTED AREAS	New	700.00	600.00
3	REMOVE & REFIX REAR EXHAUST ASSY ,STRAIGHTEN CENTRE PIPE & CHECK SYSTEM	New	100.00	60.00
Gross Labour Cost (\$)			1,600.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >