

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBH2737D
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 ES2090014/YISHUN
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 08/01/2020
 TP Veh Reg No: SMJ6001B

Estimate No: ES2090014
 Date: 09 Jan 2020
 Policy No: DMCPhQ19-001385
 Veh Reg No: GBH2737D
 Make/Model: TOYOTA DYNA 150
 Chassis No: JTFAT35Y30K210082
 Engine No: 1KD2791889
 Reg. Date: 09/04/2018

Not with hold
 1.B.I, U/R 8?
 4 days

Estimate Repair Cost to Vehicle No :GBH2737D

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR TAILGATE	1,161.70	1 PC	1,161.70	✓
2 TAILGATE STICKER 'TOYOTA'	215.67	1 PC	215.67	✓
3 TAILGATE STICKER 'DYNA'	39.80	1 PC	39.80	✓
4 TAILGATE RH SAFETY LOCK	110.20	1 PC	110.20	✓
5 TAILGATE RH LOCK HANDLE	89.90	1 PC	89.90	✓
6 TAILGATE STOPPER	33.80	1 PC	33.80	✓
7 TAILLAMP	222.70	2 PC	445.40	✓
8 TAILLAMP PANEL	101.80	2 PC	203.60	✓
9 REAR NUMBER PLATE PANEL	180.70	1 PC	180.70	✓
10 REAR EXHAUST PIPE	598.30	1 PC	598.30	✓
			3,079.07	
	Less 25%		769.77	2,309.30
Special Net				
11 STICKER 70KM/HR	10.00	1 PC	10.00	✓
12 REAR NUMBER PLATE	25.00	1 PC	25.00	✓
13 REVERSE SENSOR	200.00	1 SET	200.00	✓
			235.00	235.00
Labour				
14 REMOVE & REFIX TAILGATE ASSY, TAILLAMPS & PANEL, REAR NO PLATE LAMP & PANEL, TO STRAIGHTEN, KNOCKING & REPAIR REAR END PANEL, REAR STEP BAR, REAR TRUNK END FLOORBOARD & REALIGN POSITION	800.00	1 LA	800.00	600
15 PUTTY & RESPRAY ON TAILGATE, REAR TRUNK END PANEL, FLOORBOARD PANEL, NUMBER PLATE PANEL, TAILLAMP PANEL, LOCK HANDLE & ALL AFFECTED AREAS	700.00	1 LA	700.00	600
16 REMOVE & REFIX REAR EXHAUST ASSY, STRAIGHTEN CENTRE PIPE & CHECK SYSTEM	100.00	1 LA	100.00	60
			1,600.00	1,600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total S\$ 4,144.30
 Add GST @ 7% 290.10
 Total Amount Payable S\$ 4,434.40

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE