

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 14 Jan 2020

## **Preliminary Advice**

|                    |                                                                                                                 |                         |              |
|--------------------|-----------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SKU129Y                                                                                                       |                         |              |
| TP Vehicle No      | : SHA4313X                                                                                                      | Accident Date           | : 06/01/2020 |
| Make               | : TOYOTA PRIUS                                                                                                  | Assignment Date         | : 13/01/2020 |
| Date of Inspection | : 13/01/2020                                                                                                    | Est. Duration of Repair | : 7 days     |
| Inspection At      | : Bifrost Auto Pte Ltd (sin Ming) (HQ)<br>Blk 9 Sector C, #01-42 Sin Ming Industrial Estate<br>Singapore 575644 |                         |              |

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 32,466.42 |
| Revised Amount              | :S\$ | 12,367.25 |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 12,367.25 |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.