

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9935C**AAD2001-051***Not Authorised
11 Sep @ 480dp*

Vehicle No.:

Chassis No.:

09 JAN 2020

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9935C

VF1ABL15AUC277894

RENAULT

LATITUDE

6.1.2020

Alt

5/6/2014

		PART			LIST
1	1	BUMPER COVER REAR	\$	<i>Bulim</i>	561.70 ✓
2	1	BUMPER LOWER REAR	\$	<i>no</i>	411.90 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i>	98.10 X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i>	82.10 X
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i>	59.80 X
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i>	16.60 X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i>	80.80 X
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i>	54.20 X
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i>	16.60 X
10	1	BUMPER BEAM REAR	\$	<i>Bz</i>	547.80 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i>	114.50 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Bz</i>	100.90 ✓
13	1	OUTER PANEL REAR (End Panel)	\$	<i>Bz</i>	745.80 ✓
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>no</i>	404.56 ✓
15	1	TAILLAMP RH	\$	<i>SL</i>	313.10 X
16	1	TAILLAMP PANEL RH	\$	<i>R</i>	401.40 X
17	1	TAILLAMP LH	\$	<i>SL</i>	401.40 X
18	1	TAILLAMP PANEL LH	\$	<i>R</i>	401.40 X
19	1	BOOT REAR	\$	<i>Bz</i>	1,677.20 ✓
20	1	BOOT FINISHER	\$	<i>SL</i>	344.70 X
21	1	BOOT WHEATERSTRIP	\$	<i>89.10 SL</i>	<i>SL</i> 178.20 <i>50 SL</i>
22	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i>	277.70 X
23	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i>	277.70 X
24	1	BOOT BADGE 'RENAULT'	\$	<i>no</i>	82.40 ✓
25	1	BOOT BADGE	\$	<i>no</i>	95.80 ✓
26	1	BOOT STRUT LH	\$	<i>SL</i>	145.10 X
27	1	BOOT STRUT RH	\$	<i>SL</i>	145.10 X

Trans-cab Auto Services Pte Ltd**AAD2001-051**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9935C

28	1	BOOT HINGE LH	\$	254.20	}
29	1	BOOT HINGE RH	\$	253.80	
30	2	BOOT RUBBER PLUG	\$	139.90	
31	1	BOOT LOCK LINKAGE	\$	20.60	
32	1	BOOT LOCK LINKAGE HOLDER	\$	99.50	
33	1	BOOT INNER TRIM BOARD	\$	611.00	
34	1	BOOT SWITCH	\$	113.00	
35	1	BOOT LOCK	\$	246.60	
36	1	BOOT LOCK CATCH	\$	41.70	
37	1	EXHAUST CAP REAR	\$	125.40	
38	1	EXHAUST REAR	\$	5,263.60	}
39	1	SPARE WHEEL PANEL	\$	1,229.40	
40	1	SPARE TYRE BOARD	\$	680.90	
41	1	SPARE WHEEL PANEL TRIM	\$	612.21	

TOTAL	\$	17,728.37
10%	\$	1,772.84
	\$	15,955.53

Special Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	30.00	—
11	1	BOOT STICKER "6555-3333"	\$	30.00	—
12	2	REAR WINDSCREEN SEALANT	\$	80.00	X
13	1	WINDSCREEN MOULDING	\$	100.00	X
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	X
15	1	BOOT INNER TRIM CLIP	\$	45.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9935C**AAD2001-051**

16	1SET	BOOT FINISHER CLIP	\$	nn	24.20	} X
17	1	TAILLAMP CLIP LH	\$	nn	5.00	
18	1	TAILLAMP CLIP RH	\$	nn	5.00	
19	1	Rear Bumper Protector	\$	nn	100.00	
20	1	EXHAUST MOUNTING REAR	\$	nn	16.00	
21	1	EXHAUST BRACKET REAR	\$	nn	24.80	}
22	1SET	Rear licence plate with holder	\$	nn	80.00	
TOTAL			\$		1,587.00	

TOTAL PARTS \$ 17,542.53**LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	bol
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	bol
To Rust-Proofing Of The Affected Areas.	\$	170.00	bol
To Check Electrical Lighting Concerned.	\$	170.00	2ol
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	bol
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9935C**AAD2001-051**

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
Putty and spray painting of the affected portion.	\$	7,500.00	6601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
TOTAL	\$	18,230.00	
Over All Total	\$	35,772.53	

LUMP SUM (REPAIR DAY)**25 DAYS****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: