menmen	Steve	ASSIGN	MENT (Office			
From (Person	iii winnie Fan	CE	AIG	Date/	Time: 10/01/2020	3-46p
Estimated Co			Bill to:			
To Inspect Ve	S/TP RES / OD RI				0.000	
			8331E	Inswed:	SLB GOIRM	
at Workshop	10/11	Wee the A		Tel:	CE 58 0019	
of		19 Kim	chuan temu	ce		
Policy No:			Claim No	160083	3972556	
Sum Insured:			Excens			
Make of Velo (Client's Record					A 7/0/2020	
ate I. I because	REP. / REV 241	TRS.		H.C	D.D. Endossement:	
CA / REV	THE PART OF LAND	4.4.40.7				
Date/Times	3.50pm@10/11	2020 Person Contact	d Kiat	Vehick	INDET	
CA / REV Date/Time: Date/Time	3.50pm@10/11	2020 Person Contact	kiat.	Vehicl	INDAUT	
Date/Time:	Action/Justruction	Person Contact		,		as toni
Date/Time:	Action/Justruction SLR 833)	E - CC4 /JCR		,	Day 22/	03 /201
Oste/Time:	Action/Justruction SLR 833)	Person Contacts Lightmald L E - CCA / JCR	1800544/	,		03 /201
Date/Time:	Action/Justruction SLR 833)	E - CC4 /JCR	1800544/	,		03 /201
Date/Time:	Action/Justruction SLR 833)	Person Contacts Lightmald L E - CCA / JCR	1800544/	,		03 /201

Birmin Stave REF:		
	ASSIGNMENT	
From: Date:	Ven No: SLR 83	715 nalcli7
Estimated Cost:		
OD/TP/WS/TP-RES/ OD RES / EVA/ INV / MV		/ Van / Lorry / Taxi / Prime Mover /
To Inspect Vehicle No:	Make: - Handa	rezel 149K
ut Workshop m/s		c.c // /()
of	Colour Clut	TAC: Insured Std NI
Insured .	Sp.Reading 1043:73	T/Radio: Insured / Std / NI /
Policy No.	Eng/No:	100 - 127
Claims No.		-1253177
No. 10 August 19	Gen. Cond: Cope / Fair / Poo	
(Client's Record)	Steering: Inorder / Jammed /	
Make of Veh:	Brake: Inorder / Jammed /	Leaked / Burnt or
	Modi: NII / SIRIM / STO A	VRIm or
- 	Tyre Size: F:	215/69R16
(Policy Condition)	R:	4
Remark: The veh had columnicad its repair at the time of inspection.	BS I DUN I EXNOVA I GY I FS	/ LIZA / MIC / OHTSU / PIR / SUMI /
repear at the time of inspection.	Τογοίγοκο α	
Bal. or Market Value:	Eroni	Pane
IDAC Accident Rport; Consistent? : Yes or No	R/Bal. 5 mm	ROBAL S.
GIA / PR Seen: Consistent? : Yes or No	UBal. C mm	L/Bal. 5 mr
Est. Repairs: days Res.: Yes or No	D.O.A. 7/1/20	0.01. 10/1/20
Lum Sum: % 3 Val.: Yes or No	Survey held at W	e Hoe Auto
CA / REV / REP. / 24 HRS	0-1-	I O/S I N/S I U/C I Rooftop or
Vehicle: I		Old I Mid I UIC I Koollop or
Date: Person Contocted:		Body Structure affected due to collision
Dela / Time Action / Instruction		·
1911/19 I No GIA (egral (Perching))	* H + H	
MV-73K		tate de ses e
Repor range 7-8K		
9 days		
	ECEIVED 8 0 JAN 2020	9 199
, K	ECEIVED 9 9 31511 2020	
A many		
property of the second April		
Data/Time, File Plass to? : Proll. Report	Days Of Repair:	*
1301 Typist T: Final Report	Resurvey No. of Trip:	. In 10 -
Dala/Timo, File Return to?	nesarray no. or rrip.	Survey Fee: 180
2) Add	Fee: Site Insp (\$	II (preportation:
	× == 1);\$ + R\$\$I
Report Format: TP-DAR) Bate
Lump Sum / I.B.I: (\$	Tech Inva (\$) Ottors
1	: Weekend.: (\$	-) - ites vine
8 X		10144 1011

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case N	OLDER TRA	Est Supmitted	Adi Assigned	Adl Ros	Adl Sub	mirrad	Init ALITY ed	Status		
Main 0	7 Jan 2020 Edit Reg	ELSC SHAROTECTION	10 Jan 2020 00:00 Edit Adj Rpt					Pending for Su Report Cancel Case	rvey	
М	ain	Re	ference		Claim Details		Documer	nts	Show All	
CLAIM SUB	FOLDER DE	TAILS				[Created	by adjuster]			
Insured:	SOH KON	G BOON, ID: SO	109563C							
Main Claimant:	-									
Vehicle Reg. No.:	SLR833	1E			Date of Loss:	0.0000000	020 00:00 - :59			
Claim Type:	TP / 160	00839725SG			Policy/Cover Note No.:	(Compreh Coverage	iensive) : 26/04/2019 - 2	5/04/2020		
Vehicle Reg. No. (Insured):	5LB9018	SLB9018M								
ATTACK STATE					Excess:					
Repairer:	Wee Hoe	(HQ) 19 KIM CH	JAN TERRACE, 5	37041 Tai S	eng - Tel:	417-1-12-1		4 401		
Handling Insurer:	Bornardli	Pacific Insurance							/20201	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel	6256-3561	[Handled by	CHEN TSU	E YEE] [Fina	I Rpt due 21/01	/2020]	
ASSOCIATE	D MAIL RE	CEIVED						View All Compo	se Case Mai	
• AIG_SG (13/01/2020)	: Request to upl	oad TP GIA Re	port						
ALL ASSOC	IATED TA	sks⊟				View All	Search Tasks	Create New Task	Complet	
Due Date	Priority	Type Task	Group Sub	ject. Ha	ndier Assign	ned By	Completed 0	m Created Or	Done	
ALL ASSOC	IATED TA	sks ⁼			ndler Assign	-	-		• -	

Nivitha (LKK Auto)

From:

AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>

Sent:

Friday, 10 January 2020 3:46 PM

To:

Admin A; assignments

Cc:

Fong, Andy-SY

Subject:

Aigencypt Scan Image

Attachments:

2213_001.pdf

Hi LKK.

Kindly assist to survey, car in.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: ct-admin@visionlawllc.com <ct-admin@visionlawllc.com>

Sent: Friday, January 10, 2020 3:37 PM

To: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>

Subject: [EXTERNAL] Scan Image

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID: Vehicle Details	326K	
Vehicle No.:	SLR8331E	
Vehicle to be Exported:	No	
Intended Deregistration Date:	22 Jan 2020	
Vehicle Make:	HONDA	
Vehicle Model:	VEZEL HYBRID 1.5X AUTO	
Primary Colour:	Blue	
Manufacturing Year:	2017	
Engine No.:	LEB5953194	
Chassis No.:	RU31253177	
Maximum Power Output:	112.0 kW (150 bhp)	
Open Market Value:	\$25,209.00	
Original Registration Date:	29 Aug 2017	
First Registration Date:	29 Aug 2017	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$5,000.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	28 Aug 2027	
PARF Rebate Amount: Intended COE Rebate Details	\$3,750.00	
COE Expiry Date:	28 Aug 2027	
COE Category:	E - Open - all except motorcycle	
COE Period(Years):	10	
QP Paid:	\$52,751.00	
COE Rebate Amount:	\$40,087.00	
Total Rebate Amount:	\$43,837.00	

The information contained herein is correct as at 22 Jan 2020

OK

VISION LAW LLC

Advocates & Solicitors (Incorporated with limited liability)

ERIC NO CHING BOON WONG KENG LEONG RAYNEY AUDREY WONG SU-HEIEN PAUL YAP TAI SAN ANJALLI DIO MUNIANDY ANG KIM NOT DIANK RAVENDRA KRISHNASAMY CHEONO YUNHUI, CLANISSA SONIA LIM WEI LEI

Unique Entity Number: 200721148H

133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Main : (65) 6534 2811 (Hunting) FAX : (65) 6535 6802 E-MAIL : annatan@@visioniawiic.com

Conveyancing & Family Law Practices TEL: (65) 6358 0703 : (65) 6358 0703

Fax (65) 6358 0448

BY FAX 6835-7416 ONLY

AIGSGP ClaimsSurvey@aig.com

WHEN REPLYING, PLEASE QUOTE OUR REFERENCE.

OUR REF: AW1-atv-INS-W30-SLR8331E-2020 - please reply to: annatan@visionlawlic.com YOUR REF: SLB9018M

10 January 2020

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS Building 78 Shenton Way #07-16 Singapore 079120

Attn: Motor Claims Department

Dear Sirs

NAME OF CLAIMANT: CARZ ASIA PTE LTD

VEHICLE NUMBER: **SLR 8331 E**

YOUR INSURED VEHICLE NUMBER: SLB 9018 M

ACCIDENT AOWARDS GOING KPE/ECP (KALLANG RIVER) ON 7 JAN 2020 AT ABOUT

0625HOURS

We refer to your email dated 10 January 2020 wherein there is no agreement to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

WEE HOE AUTO SERVICE 19 KIM CHUAN TERRACE SINGAPORE 537041

Contact Person:

TEL: 6858-0019 (KIAT)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

Audrey Wong / (Head Office)

SLR 8331 E- By fax 6858-0195 only CC.

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor (Name & Signature)

Date & Time of Inspection :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	07/01/2020 15:55
Date Of Accident	07/01/2020 06:25
Exact Location Of Accident	TOWARDS GOING IN KPE/ECP (KALLANG RIVER)
Country/State of Loss	SINGAPORE
Market Indian Indian	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLR8331E
Insured/Policyholder	
Name Of Registered Owner	CARS ASIA PTE LTD
Co Reg No	2XXXXX326K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98335667
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL HYBRID
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No. Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094243790-02
Cover Note Number	
Driver	
Name of Driver	DEVANDRAN S/O SUNDRAGIE @DEV
NRIC No	SXXXX040I
Date Of Birth	25/12/1980
Occupation	OUTDOOR
Date Of Driving Pass	21/03/2002
Driving Experience	17 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96483284
Fax Number	

STRIVE_EXCEL@HOTMAIL.COM

Address

BLK 571B WOODLANDS AVENUE

#07-910 SINGAPORE

Postcode

732571

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

AFTER-RAIN

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

3

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: NA

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station.

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO FOOTAGE WITH DRIVER

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLB9018M

Vehicle Make/Model/Colour Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

SOH HONG BOON

NRIC/Passport Number

SXXXX563C

Contact Number

98567121

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

NA

Vehicle Make/Model/Colour

Details Of Properties

REFER ATTACHED

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

DEVANDRAN S/O SUNDRAGIE @DEV

Approximate Age

Injuries Sustain

NECK STRAIN (2DAYS MC)

Injured person in which vehicle?

SLR8331E

Were seat belts worn?

YES


Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

	THE VEHICE IN FRONT OF ME STOPPED SUDDENL
_	(E-BRAKE) SO I HAD TO STOP ACCORDINGL
_	BUT THE VEHICLE BEHIND ME DIO NOT JUN
	DOWN AND HIT MY REAR.
	I WENT TO SEE DOCTOR FOR MY NECK STRA
	CSLIGHT DISCOMFORT) AND I WAS ISSUSED
	WITH OIDAYS MC. IF PAIN INCREASELY,
	DOCTOR ADVISE TO REPORT BACK
	The second series of the second series and the second series and the second series are series are series are series are series and the second series are s
_	
_	
_	
_	
ī	
_	

DECLARATION

I/We deplare the sygoing seviculars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

GIRANC SHAGHLAFOUR, VA

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

for complete with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:























	r.Pertion	The United to (1985) on 11 december protection (1985) on 11 december 11 pro-		1.9		JKC (CAR	Fri)		### makes U.	119.30	0.10	C112
IAL										0.0	077	11	50
001	31.110	Hem 6 Frithmher Pine	Ico	ella	don		1000	-		1 sture to DR	000	IL	
000	-1-66	2 Backs	TE	12	Secon		MA	1	INC	Tecata		164	
003	90122	7 Pri Finniber Plate Base	100	1	1		107	7	72205	Piese Bios		200	1
1001	991.10	9 En Humber Plate Gamish 9 En Bumper	10	12			107	2 0	PHOTI	Relay Doc		- 1	- 1
Our	11 11 11 11 11 11 11 11	A Fee D	100	15			107	1 0	25053	Wiper Washer Link		-1	-1
OOL	99117	Fri Bumper Clips	107.0	10	1		107	4 95	12025	Wiper Washer Tank More		-	-
007	991.46	5 Frt Bumper Bricker		1			107	97	MITSA	Alternator Assy		-	-
000	901.43	2 Fri Bumper Side Retainer	TIR	10	10		107		0160		-	-	4
don	00111	Fri Bumper Reinforcement	100	T/S	1		107	7 95	12081	Power Stoering Pump	-	-	-
010		STEEL LIGHTER TOWN	100	1	+		107	0 1 95	/2n69	Power Steering Itels	-	-	- -
011	00147	Fit Dumper Sponge		+	+		107	9 99	4431	Power Steening Cooler Page		-	-
012	99142	Fit Bumper Protector		+	-		*108	0 39	5635	Power Steermit Hose		-	-
013	001363	Frt Bumper Pad		1	-		108	1.20	0010	ABS Pump Control University	1		-
014	99130	Fri Bumper Grille		1	+		108	6 39	0427	Brake Master Purpos Acres	-	+	-
015	991 403	15t Bumper Mondding		1	\vdash		102	1.1.22	0403	Brake Bouster Pages Account		+	-1-
316	991411	Frt Humper Lower Sporler					1000	1 39	1005	Engine Top Cover			
117	995100	Fit Bumper Seggor					1085	99	1011	Engine Under Cover			-
HE	001155	Frt LH Dumper Fog Lump Cover					1000	99	P246	Engine Mounting		1	-
119	1-00-00-00	14-11 St. 8.6 Hittinger Lines I.			-		1087	990	0.045	Engine Mounting Lit	10		
20	DESCRIPTION OF THE PARTY OF THE	LUCAL C. LA PERSONNE LINE T WALLES					1000	994	9950	Engine Mounting Ltt	-	1	1
21	77.00.011.0944	Fit BH Damper Fog Lamp Fit Grille					1029	. 1994	1952	Engine: Mountiere 1117			1
22	991 175	Presente:	TE	12			1020	3994	1951	Engine Mounture Press			
21	991200	Ert Grille Emblem	NEC	1			1091	997	1234	Gear Box Mountme		1	1
24	991222	Frt Grille Chrome Mendding		-			1092	990	520	Fit LH Chassis Member		1	1
25	201000	PH Apron Panel					1093	991	520	Get RH Chassis Member	1	-1-	-
26	002024	Fit Support Panel		\vdash	-		1094	990	1728	Frt Vertical Cross Member		-	-
27	992025	Fit Support Panel Top Garnish Cover			-		1095	991	90.7	Pit Lower Cross Mendier	1 .	-	+
211	11.00	1110111			-		1096	995	0701	Frt LH Fender	-	-	F
19	995157	Frt Brace Panel				CS.	1097	995	072	Frt LH Fender Inner Panel	-	-	+
10	993133	Fri LH Headlamp Assy	-				1098	399	147	Fit LH Funder Laure	-	+-	-
17.	995000	Frt RU Headlamp Assy					1000	995	148	Fet LH Fender Protective		+-	-
12	995/190	Fr: LH Side Lump					1100	391	740 [Fit L.H. Fender Inner Chiefel	1	-	-
_	990248	Fit RH Side Lamp		-			1101	97/3	13.77	Fit LH Mudflag		+	-
14	991128	Dowet Emblem	00	7			1102	995	170	Frt LH Wheel Itim	1-	1-	-
15	990227	Bonnet Lock					1104	994	025	Fit LH Ran Cover			+
16	990235	Bonnet Insulator					1105	995	063 1	Fit LH Tyre			
17	990273	Bonnet Huge		1			1106	999	770	Fet RH Femilia		1	1
8	990261	Bonnet Damper		×	4		1107	2/2/1	739	et RH Fender finer Panel		1	1
9	990305	Bonnet Rubber	- 20		X		1108	-	750 1	rt RH Fender Lamp			1
0	990252	Bonnet Cable	Len		1		1109	991	the same of the	rt RH Fender Protector			1
1	990311	Bonnet Stand			1	1	1110	991	294	rt RM Femilier Inner, Shield			
3	990119	Air Con Condenser		~	30	~	1111	-	-	et RH Mentillap			
3	990122	Air Con Fan Assy	VIX	1	2/2		1112	9921	10 7 P	HRH Wheel First			
4	990134	Air Con Tuni	200	11	1		1113	9950		rt RH Rim Cover			
5	311000	Air Con Suction Pipe (Low Pressure) Air Con Suction Hose	3	1			T114			rt RH Tyre			
6 1	090133	Air Con Disease					1115	9921	12.3	et Windscreen rales			
7 1	990114	Air Cen Discharge Pipe (High Pressure)					1116	992	17	rt Windscreen Enblog			
_		Air Con Discharge Hose Air Con Liquid Pipe					1117	997	100	rt Windseren Monlding			
1	993066	Air Con Estativer Drice					1115	1911	1741	rt Windscreen Sedant			-
1 1	290111	Mr. Court		1			1119	0011	10.0	KI' Binckei			
1	95294	Mr Con Congressor Assy Ar Con Belt					-	20011	10 15	RP Dan		3	12
	95074	hadran.					1120	9921	40 1	rt Wiper Arm			
1	19.11.19	Section 1					1121	2971	42 1	rt Wiger Wade			
	937111	admin Cowling			-		1122	9950		Ager Panel Garneli			
1	93745	adiator Fan Assy					1123	9911	240	nerwall Panel		119	
1,	077500	adiates Fan Clutch					1124	9917	Maria Contract	Gibboard Assy			
-	FE 2 7 7 1 1	adiador Hose Top			-1		1125	19/9/201	95 11	love Dr. Cover			
15	92244	adiator Hera: Dattings						9922		love Box Compartment			
10	2011	arliates Expossion Cost.		-			1127	9944	83 [34	receing Wheel Autor			-
111	W1 11 14	tr Duci						9944	57 51	corner Wheel Airborg Sensor			
1	40070 7	or Cleaner copy	-		-			9907	45 10	ashlroard a ulaar			10-11
1.7	90056 A	it Cleaner Hear			-		1130	2907	50 15	exhibiting Arthur Service			
14	William V	ir Clemer Eesmalm					1111	9900	175	rding Coulint Unit			
1.0	ALC ES IN	I Show I Manufold		-	-		1112	00000	A 1.	Direction			
L	4171 LH-	t Labour Stanfold Commi				- 1	1111	0019	11	PH Sea Belt Assay			
100	2111/04/12/	T.T. Joseph J. B. Disson L. A. J.				- 1	1134	99125	P3 15	Passinger Sear			
		Trees to a supplemental to the supplemental to			3	1	1135	19011	2 15	OLD Control			
100	ACCUSATE:	Het.			1	1		2002	_	rder			
	VIII THE	Hit a pre-point		1		1	or attitude	STORY STATE	2 1 -0				

 994611 Tailgate Hinge

994594 Tailgate Damper

MOTORCAR (Rear)

ACTION (ACTION (4)Not Consistent (4C)

SIP & 331F

Rear Portion		-			NAC	INC	Vehicle No: SLK 85	CON	AC	Q
NAC INC. I	110111	CON	ACIO	20	1202	0037	84 Spare Tyre Board			
1137 993626	Rear Number Plate		-	-	1202	0043	28 Spare Tyre Panel			
1138 993627	Rear Number Plate Base		-	_	1203	-	065 Spare Tyre			
1139 993630	Rear Number Plate Garnish						326 Spare Tyre Lock Screw			
1140 993632	Rear Number Plate Lamp				1205	-	787 Spare Tyre Cover			Γ
1141 992958	Rear Bumper	00	V		1206	993	323 Triangle Breakdown Sign			T
1142 993085	Rear Bumper Upper				1207	995.	323 Triangle Dieakdown Sign	1		t
1143 993017	Renr Bumper Lower				1208		507 CD Changer Assy	1	+	T
1144 993054	Rear Bumper Side				1209	990	164 Antenna	-	+	t
1145 993103	Rear Bumper Tow Cover				1210	_	534 Centre Exhaust Pipe Assy	-	+	+
1146 992341	Rear Bumper Clips	NEC	V		121	-	532 Centre Exhaust Mounting	-	+	7
1140 992341	Rear Bumper Bracket				1213		3364 Rear Exhaust Pipe	_	+	7
	Rear Bumper Side Retainer	TUK	V	2	121	3 993	3357 Rear Exhaust Chrome Pipe	-	+	1
THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO I	3045 Rear Bumper Reinforcement 1215 993358 Rear Exhaust Heat Shield				-	+	7			
	993045 Rear Bumper Reinforcement 1215 993358 Rear Exhaust Heat Shield				-	+	-			
	Rear Bumper Sponge	1		T	121	6 99	5223 Rear LH Chassis Member	_	-	-
The second secon	Rear Bumper Damper	_	1	1	121	7 99	3165 Rear RH Chassis Member	-	+	-
The second second second second second	Rear Bumper Damper	+	+	1	121	8 99	3436 Rear LH Fender	+	+	-
THE RESERVE AND THE PERSON NAMED IN COLUMN 2 IS NOT THE PERSON NAM	Rear Bumper Protector	1	1	1	121	9 99	3449 Rear LH Fender Protector	-	-	-
	Rear Bumper Pad	1	1	1	123	20 99	3420 Rear LH Fender Inner Panel	_	-	_
	6 Rear Bumper Moulding	-	-	+	12:	21 00	3431 Rear LH Fender Inner Trim	-	-	_
THE RESERVE AND ADDRESS OF THE PERSON NAMED IN	4 Rear Bumper Reflector	-	-	+	12	22 00	3415 Rear LH Fender Inner Garnish	+	-	_
Commence of the Park of the Pa	3 Rear Bumper Lower Spoiler	ZE	1	1	12	23 99	3425 Rear LH Fender Inner Shield		-	_
The second second second second	3 Reverse Sensor	100	1	1		24 99	93621 Rear LH Mudflap		-	_
1159 99332	7 Rear End Panel	10		-		25 9	93933 Rear LH Wheel Rim	_	_	_
1160 99333	9 Rear End Panel Top Garnish	1.5		+	100000	26 9	94025 Rear LH Rim Cover		_	_
1161 99333	3 Rear End Panel Inner Trim	-	+	+	-		95065 Rear LH Tyre			_
1162 99033	33 Boot Compartment Inner Trim	-	-	+		28 9	93456 Rear RH Fender			_
1163 99383	SI Rear LH Taillamp	-	-	+		29 9	93450 Rear RH Fender Protector			
1164 99383	53 Rear LH Taillamp Garnish	-	-	+		230 9	93420 Rear RH Fender Inner Panel			_
1165 9938	59 Rear LH Taillamp Punel		-	+		231 9	993431 Rear RH Fender Inner Trim			
1166 9951	16 Rear RH Taillamp	_	-	-		232 5	993415 Rear RH Fender Inner Garni	sh		L
1167 9938	53 Rear RH Taillamp Garnish		-	-		233	993425 Rear RH Fender Inner Shield			
1168 9938	59 Rear RH Taillamp Panel	_	-	-		234	993622 Rear RH Mudflap			
1169 9935	54 Rear Apron Panel	_	_	-		235	993934 Rear RH Wheel Rim			
	95 Bootlid		-	_		233	994025 Renr RH Rim Cover			T
1171 9913	328 Bootlid Emblem		_	_			995065 Rear RH Tyre			T
1172 9903	356 Bootlid Handle				-	237	995162 Rear Fender Extension Pane	HLI		T
1173 9953	250 Bootlid Moulding				-	238	993401 Rear Fender Extension Pane	IRH		T
1174 990	376 Bootlid Reflector					239	993430 Rear Fender Inner Top Gan	rish		7
1175 995	222 Bootlid Lamp LH				1 1-	-	The state of the s			7
1176 992	899 Bootlid Lamp RH				1	1241	993452 Rear Fender 1/4 Glass Rub	ber		7
1177 995	243 Bootlid Lock							ant		
1178 990	377 Bootlid Rubber				1	1243				
1179 990	382 Bootlid Hinge				1	1244	The black			7
1180 993	877 Bootlid Spoiler		,			1245	of the second se	,		_
1181 994	1543 Tailgate		Ø	V		1246	993961 Rear Windscreen Negarant	-	100	7
1182 99	1328 Tailgate Emblem		NEC	W	1 1	1247	993955 Rear Windscreen Scalant			_
Company of the last of the las	4643 Tailgate Outer Handle				1 1	1248	994729 Third Brake Light		-	-
The second second second	4640 Tailgate Moulding			1	1 1	1249	993385 Renr Fender Air Grille		1	-
	4640 Tangate Moditing			†	1 1	1250	992167 Fuel Lid		-	-
Company of the Parket of the P	4545 Tailgate Garnish			1	1 1	1251	992168 Fuel Neck		-	_
The second secon	4648 Tailgate Reflector		_	+	1	1252	992179 Fuel Tank		+	_
	4549 Tailgate Lamp		-	+	-1	1253	992184 Fuel Tank Bracket		+-	_
The second second second	94646 Tailgate Protector	_	-	-	-	1254	and the second s		-	_
	14676 Tailgate Wiper Arm		-	+	-	*1936	and the same of th		-	
The second second second second	74677 Tailgate Wiper Blade		-	-	-		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1	
1191 99	94679 Tailgate Wiper Nozzle	- 4	-	-	-	2	13.			
1192 9	94555 Tailgate Wiper Motor		-	-	-	1	de la company			
1193 9	94602 Tailgate Glass		-	1	10	m		10		
1194 9	94606 Tailgate Glass Rubber		ME	1	-1/	X1.	1/1			
1195 9	94604 Tailgate Glass Moulding					1	V 10			
1196 9	94607 Tailgate Glass Sealant		ME			1+	21/2020			
1197 5	94629 Tailgate Lock		111		- 1	1	3			
	94651 Tailgate Rubber		CR	4	-	V.	21/			
	204611 Tailante Hinne				1	1			-	_

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	il profesoroto de reconociono de la constanta									
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Si	ubmitted	Ins Auth'ed		Status	
Main	07 Jan 2020 Edit Reg		10 Jan 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estim	4	S\$0.0	v Rpt			ending for eport Cancel Case	4
	Main	R	eference	Cla	im Deta	ils		Docume	ents		Show All
CLAIM SU	BFOLDER DE	ETAILS					[Created	by adjuster)			
insured:	SOH KON	G BOON, 10: 50	109563C								
Main Claimant:	-	•									
Vehicle Reg No.:	SLR833	1E		0	ate of L			0 00:00 - :59 s and 9 Days F	rom LTA	Reg Date (M	tan Yr)]
Claim Type	TP / 160	00839725SG	10.70	alicy/Co late Na.:		(Comprehe Coverage:	nensive) : 26/04/2019 - 25/04/2020				
Vehicle Reg No. (Insured):	SLB9018M				olicy No Claiman						
				E	xcess:						
Repairer:	Wee Hoe	(HQ) 19 KIM CHI	JAN TERRACE, 5370	41 Tai Seng -	Tel:						
Handling Insurer:		Pacific Insuranc Qian.Ler@aig.com	e Pte. Ltd. (Expre	ss) - Tel: 65-	6419-30	000	[Handled b	y Ler, Bernar	[QL-br		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handled	by CH	EN TSUE	YEE] [Fina	al Rpt d	ue 21/01/	2020]
ASSOCIAT	ED MAIL RE	CEIVED						3.5 1	View All	Compos	e Case Mail
 AIG_SG 	(13/01/2020)	: Request to upl	oad TP GIA Repor	t							
ALL ASSO	CIATED TAS	sks⊟				v	ew All	Search Tasks	Create	New Task	Complete
Due Date	e Priority	Type Task	Group Subject	t Handle	As	ssigne	nd By	Completed (On I	Created On	Done

Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20000667/ETD3E2

Date: 03/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Alo Asia Facilic Ilisurance Fie. Liu.

Claimant Vehicle SLR8331E

SLR8331E Insured Vehicle No : SLB9018M

Date of Loss: 07/01/2020 Nature of Claim: TP Claim No: 1600839725SG

Policy No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR8331E

 Make & Model:
 HONDA VEZEL, 1.5 HYBRID X (A)
 Engine No:
 LEB5953194

 Reg. Date:
 29/08/2017 (Man. Year: 2017)
 Chassis No:
 RU31253177

 Colour:
 Blue
 Odometer:
 104373 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

 Front Tyre Size:
 215/60 R16
 Rear Tyre Size:
 215/60 R16

 Front Left Side:
 Dunlop 5 mm
 Rear Left Side:
 Dunlop 5 mm

 Front Right Side:
 Dunlop 5 mm
 Rear Right Side:
 Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/01/2020

Date Inspected: 10/01/2020 Inspected At: Wee Hoe (HQ)

19 KIM CHUAN TERRACE

Singapore 537041

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT NUMBER PLATE	Broken	0.00F	*-F
2	1	*FRT NUMBER PLATE GARNISH	Cut	0.00 F	*-F
3	1	*FRT BUMPER	Dented	0.00 F	*-F
4	1	*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2	*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
6	1	*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*-F
7	1	*FRT GRILLE	Broken	0.00 F	*- F
8	1	*FRT GRILLE EMBLEM	Necessary	0.00 F	*-F
9	1	*BONNET	Dented	0.00 F	*-F
10	1	*REAR BUMPER	Dented	0.00 F	*- F
11	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
12	2	*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
13	1	*REVERSE SENSOR	Broken	0.00 F	*- F
14	1	*REAR END PANEL	Dented	0.00 F	*- F
15	1	*REAR END PANEL TOP GARNISH	Crushed	0.00 F	*- F
16	1	*TAILGATE	Dented	0.00 F	*- F
17	2	*TAILGATE EMBLEM	Necessary	0.00 F	*-F
18	1	*TAILGATE GLASS RUBBER	Necessary	0.00 F	*- F
19	1	*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
20	1	*TAILGATE LOCK	Bent	0.00 F	*- F
21	1	*TAILGATE RUBBER	Crushed	0.00 F	*- F
F≡Fn	anchise part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Claim Documents

*SLR8331E (1600839725SG) [SLB9018M] TP

> Jan 7 2020 12:00AM [SOH KONG BOON] Wee Hoe

Pho	tos/Images		3 per s	3 per page 💙	
Vο	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
t	10/01/20 17:51	General View	0	Load JPG	~
2	10/01/20 17:51	General View	0	Load JPG	V
3	10/01/20 17:51	General View	0	Load JPG	100
4	10/01/20 17:51	General View	0	Load JPG	V
5	10/01/20 17:51	General View	0	Load JPG	V
6	10/01/20 17:51	General View	0	Load JPG	V
7	10/01/20 17:51	General View	0	Load JPG	1
8	10/01/20 17:51	General View	0	Load JPG	V
9	10/01/20 17:51	General View	0	Load JPG	V
10	10/01/20 17:51	General View	0	Load JPG	8
11	10/01/20 17:51	General View	0	Load JPG	V
12	10/01/20 17:51	General View	0	Load JPG	4
13	10/01/20 17:51	General View	0	Load JPG	V
14	10/01/20 17:51	General View	0	Load JPG	V
15	10/01/20 17:51	General View	0	Load JPG	V
16	10/01/20 17:51	General View	0	Load 3PG	2
17	10/01/20 17:51	General View	0	Load JPG	V
18	10/01/20 17:51	General View	0	Load JPG	V
19	10/01/20 17:51	General View	0	Load JPG	~
20	10/01/20 17:51	General View	0	Load JPG	V
21	10/01/20 17:51	General View	0	Load JPG	~
22	10/01/20 17:51	General View	0	Load JPG	V
23	10/01/20 17:51	General View	0	Load JPG	2
24	10/01/20 17:51	General View	0	Load JPG	~
25	10/01/20 17:51	General View	0	Load JPG	✓
26	10/01/20 17:51	General View	0	Load JPG	~
27	10/01/20 17:51	General View	0	Load JPG	V
28	10/01/20 17:51	General View	0	Load JPG	V
29	10/01/20 17:51	General View	0	Load JPG	V
30	10/01/20 17:51	General View	0	Load JPG	3
31	10/01/20 17:51	General View	0	Load JPG	~
32	10/01/20 17:51	General View	0	Load JPG	V
33	10/01/20 17:51	General View	0	Load 3PG	V
34	10/01/20 17:51	General View	0	Load JPG	V
35	10/01/20 17:51	General View	0	Load JPG	V
36	10/01/20 17:51	General View	0	Load JPG	V
37	10/01/20 17:51	General View	0	Load JPG	V

Pho	tos/Images	I Was a second of the second o	3 per page	4
VO.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ) General View	Thumbna Load JPG	-
8	10/01/20 17:51	POPPER NO. (VIII.)		-
9	10/01/20 17:51	General View	O Load JPG	_
0	10/01/20 17:51	General View	■ Load JPG	1,777
1	10/01/20 17:51	General View	■ Load JPG	_
2	10/01/20 17:51	General View	Load JPG	_
3	10/01/20 17:51	General View	Load JPG	_
4	10/01/20 17:51	General View	Load 3PG	-
5	10/01/20 17:51	General View	1 Load 3PG	_
6	10/01/20 17:51	General View	● Load 3PG	-
7	10/01/20 17:51	General View	1 Load JPG	-
8	10/01/20 17:51	General View	1 Load JPG	-
19	10/01/20 17:51	General View	1 Load JPG	-
0	10/01/20 17:51	General View	Lbad 3PG	_
51	10/01/20 17:51	Odometer Reading	1 Load JPG	-
52	10/01/20 17:51	General View	■ Load 3PG	_
3	10/01/20 17:51	General View	1 Load 3PG	_
54.	10/01/20 17:51	Chassis Number	1 Load 3PC	-
5	10/01/20 17:51	General View	1 Load JPG	3 2
6	30/01/20 13:57	Reinspection Photo	■ Load JPG	3 5
57	30/01/20 13:57	Reinspection Photo	E Load 3PG	5 E
8	30/01/20 13:57	Reinspection Photo	■ Load 3PC	3 Ex
9	30/01/20 13:57	Reinspection Photo	1 Load JPC	3 1
0	30/01/20 13:57	Reinspection Photo	Load JPG	3 5
51	30/01/20 13:57	Reinspection Photo	■ Load JPC	3 5
52	30/01/20 13:57	Reinspection Photo	■ Load 3PC	3 5
63	30/01/20 13:57	Reinspection Photo	Load JPG	3 5
64	30/01/20 13:57	Reinspection Photo	1 Load JPC	3 2
65	30/01/20 13:57	Reinspection Photo	■ Load 3PC	3 2
56	30/01/20 13:57	Reinspection Photo	Oft beo.1	3 E
67	30/01/20 13:57	Reinspection Photo	■ Load 3P3	3 2
68	30/01/20 13:57	Reinspection Photo	Executive Section 190	5 E
69	30/01/20 13:57	Reinspection Photo	■ Load 3PC	3 1
70	30/01/20 13:57	Reinspection Photo	■ Load 3PG	3 5
71	30/01/20 13:57	Reinspection Photo	■ Load 3PC	
72	30/01/20 13:57	Reinspection Photo	■ Load 3PC	
73	30/01/20 13:57	Reinspection Photo	O Load JPG	-
74	30/01/20 13:57	Reinspection Photo	O Load 3PC	400
75	30/01/20 13:57	Reinspection Photo	■ Load JPC	
76	30/01/20 13:57	Reinspection Photo	1 Load 3PC	
77	30/01/20 13:57	Reinspection Photo	■ Load JPC	- 200
78	The state of the s	Reinspection Photo	O Load JPC	-1-12
	30/01/20 13:57	Reinspection Photo	1 Load 3PG	-
79	30/01/20 13:57	Haracolles and annual and a second se	O Load JPC	
80	30/01/20 13:57	Reinspection Photo	3 Load 3PC	
31	30/01/20 13:57	Reinspection Photo		-
82	30/01/20 13:57	Reinspection Photo	O Load JPC	_
33	30/01/20 13:57	Reinspection Photo	O Load JPC	_
94	30/01/20 13:57	Reinspection Photo	€ Load JPC	_
85	30/01/20 13:57	Reinspection Photo	0 Load JPC	-
86	30/01/20 13:57	Reinspection Photo	1 Load JPC	3 B

Page 3 of 3

Photos/Images		3 per s	age V		
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
88	30/01/20 13:57	Reinspection Photo	0	Load JPG	V
89	30/01/20 13:57	Reinspection Photo	0	Load JPG	W
90	30/01/20 13:57	Reinspection Photo	0	Load JPG	3
91	30/01/20 14:17	After Repair Photo	0	Load 3PG	4
92	30/01/20 14:17	After Repair Photo	0	Load 3PG	\square
93	30/01/20 14:17	After Repair Photo	0	Load JPG	8
94	30/01/20 14:17	After Repair Photo	0	Load JPG	100
95	30/01/20 14:17	After Repair Photo	0	Load JPG	$\overline{\mathbf{A}}$
96	30/01/20 14:17	After Repair Photo	0	Load JPG	2
97	30/01/20 14:17	After Repair Photo	0	Load JPG	V
98	30/01/20 14:17	After Repair Photo	0	Load JPG	V
99	30/01/20 14:17	After Repair Photo	0	Load 3PG	V
100	30/01/20 14:18	After Repair Photo	0	Load JPG	V
101	30/01/20 14:18	After Repair Photo	0	Load JPG	100
102	30/01/20 14:18	After Repair Photo	0	Load JPG	V
103	30/01/20 14:18	After Repair Photo	0	Load JPG	V
104	30/01/20 14:18	After Repair Photo	0	Load JPG	3
105	30/01/20 14:18	After Repair Photo	0	Load JPG	V
106	30/01/20 14:18	After Repair Photo	0	Load 3PG	Z
107	30/01/20 14:18	After Repair Photo	0	Load JPG	1
108	30/01/20 14:18	After Repair Photo	0	Load JPG	100
Doc	umentation		1 per	page 🔻	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/01/20 17:54	OI GIA REPORT	0	Load PDF	

Merimen e-Claims

Documents Checklist

There are no document checklists configured.	2577	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
		^
		v

Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG20000667/ETD3E2

Date:

03/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle SLR8331E

Insured Vehicle No:

SLB9018M

Date of Loss:

07/01/2020

Nature of Claim:

Claim No: 1600839725SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLR8331E

Make & Model:

HONDA VEZEL, 1.5 HYBRID X (A) 29/08/2017 (Man. Year: 2017)

Engine No:

LEB5953194

Reg. Date: Colour

Chassis No: Odometer:

RU31253177 104373 km

Engine Capacity:

1496 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Market Value/New Car Price:

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side:

Dunlop 5 mm

Rear Left Side: Rear Right Side: Dunlop 5 mm Dunlop 5 mm

Front Right Side: Dunlop 5 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

10/01/2020

Date Inspected:

10/01/2020

Inspected At:

Wee Hoe (HQ)

19 KIM CHUAN TERRACE

Singapore 537041

Estimated Period of Repair:

9.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty Part N	o. Particulars	Condition	Repairer's	Amount
1	1	*FRT NUMBER PLATE	Broken	0.00 F	*-F
2	1	*FRT NUMBER PLATE GARNISH	Cut	0.00F	*-F
3	1	*FRT BUMPER	Dented	0.00 F	*-F
4	1	*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
5	2	*FRT BUMPER SIDE RETAINER	Broken	0.00F	*- F
6	1	*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
7	1	*FRT GRILLE	Broken	0.00 F	*- F
8	1	*FRT GRILLE EMBLEM	Necessary	0.00F	*- F
9	1	*BONNET	Dented	0.00F	*- F
10	1	*REAR BUMPER	Dented	0.00 F	*- F
11	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
12	2	*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*-F
13	1	*REVERSE SENSOR	Broken	0.00F	*-F
14	1	*REAR END PANEL	Dented	0.00F	*- F
15	1	*REAR END PANEL TOP GARNISH	Crushed	0.00 F	*-F
16	1	*TAILGATE	Dented	0.00 F	*- F
17	2	*TAILGATE EMBLEM	Necessary	0.00 F	*-F
18	1	*TAILGATE GLASS RUBBER	Necessary	0.00F	*- F
19	1	*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
20	1	*TAILGATE LOCK	Bent	0.00 F	*-F
21	1	*TAILGATE RUBBER	Crushed	0.00 F	*-F
F¤Fn	enchise part.		RECEIVED TO PLAN	22.22.20	20/100
			Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >