

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFQ89J/2001006

09th January 2020

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Not Authorized
Mark
10/1/20
The phl below 2-3h.

Date Of Accident : 08th January 2020
Location : Yio Chu Kang Road & AMK Ave 5 Junction
Third Party Claim Vehicle No : SJS 5243 P
Repair Cost for Vehicle No : SFQ 89 J Mercedes Benz E200

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear bumper fascia	no/ox 1	2,241.00	\$ 2,241.00 ✓
2	Rear bumper clips	nu 1 set	36.00	\$ 36.00 ✓
3	Rear bumper towing cover	1n 1	95.00	\$ 95.00 X
4	Rear bumper lower lip chrome	nn 1	335.00	\$ 335.00 ?X
5	Rear bumper lower lip garnish (black)	Scratch 1	302.00	\$ 302.00 ✓
6	Rear bumper side retainer L&R	11 1	90.00	\$ 90.00 X
7	Rear bumper reinforcement beam	SVC 1	886.00	\$ 886.00 ?X
8	Rear bumper reflector L&R	11 2	32.00	\$ 64.00 X
9	Rear bumper parking sensor	SVC 2	304.00	\$ 608.00 ?X
10	Rear bumper rivet	14 1	9.00	\$ 126.00 ✓60
11	Rear exhaust tip L&R(s/nett)	O/S Scratch 2	280.00	\$ 560.00 ✓IPC
				\$ 5,343.00

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFQ89J/2001006

09th January 2020

Balance b/f

\$ 5,343.00

Labour Charges :-

Amounts

Cut out, renew, knocking & welding rear lamp panel, remove & install all damage parts, straighten & re-align body

\$ 980.00

Spray painting on damage parts

\$ 680.00

Remove & refix rear bumper sensor

\$ 100.00

Check all lighting after repairs

\$ 35.00

Remove & refix rear exhaust sensor

\$ 100.00

Diagnostic & reset

\$ 300.00

Labour Charge

\$ 2,195.00

Total Amount

\$ 7,538.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: