



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004957
INV Date 16/07/2020
Reference CC4/FCI20000673/Hea3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMG 9204D
Insured Veh. SHA 1689G
Claim No. D20000244MFSH
Policy No. D-20094922MFSH
Accident Date 06/01/2020
Inspection Date 10/01/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20000673/Hea3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-07-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1689G	Veh. Inspected	SMG 9204D	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20000244MFSH	Excess (\$)	0.00	
Assign From	JASON TEA	Assign Date	09/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI OUTLANDER	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GF7W0600281	Colour	WHITE	
Odometer	22326	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	TOYO	6 mm	
L/H Front Tyre	225/55 R18	TOYO	6 mm	
R/H Rear Tyre	225/55 R18	TOYO	6 mm	
L/H Rear Tyre	225/55 R18	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/01/2020	Inspection Date	10/01/2020	
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 9204D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FACE ,FR BUMPER (SN)	NOT NECESSARY	851.00	-
1	EXTENSION ,FR BUMPER (SN)	SCRATCHED	509.00	509.00
20	CLIP ,FR BUMPER (SN)	NECESSARY	40.00	40.00
10	CLIP ,FR BUMPER (SN)	NECESSARY	30.00	30.00
6	RIVET ,FR BUMPER (SN)	NECESSARY	30.00	30.00
1	COVER ,FR BUMPER (SN)	SCRATCHED	355.00	355.00
1	LH GARNISH ,FR BUMPER (SN)	SERVICEABLE	48.00	-
1	RH SIDE BRACKET ,FR B (SN)	SERVICEABLE	18.00	-
1	LH SIDE BRACKET ,FR B (SN)	NECESSARY	18.00	18.00
1	GARNISH ,FR BUMPER S (SN)	CRACKED	220.00	220.00
1	GARNISH ,FR BUMPER S (SN)	SERVICEABLE	112.00	-
1	GARNISH ,FR BUMPER SI (SN)	SERVICEABLE	48.00	-
1	REINFORCEMENT ,FR BUM (SN)	SERVICEABLE	524.00	-
1	LH HEADLAMP ASSY (SN)	SERVICEABLE	1,938.00	-
1	REINFORCEMENT ,FR BUM (SN)	SERVICEABLE	134.00	-
1	LH SIDE REINFORCEMENT (SN)	SERVICEABLE	60.00	-
2	SIDE REINFORCEMENT ,F (SN)	SERVICEABLE	44.00	-
1	UPR LH PANEL ,HEADLA (SN)	TO REPAIR SEE LABOUR	58.00	-
1	UPR PANEL ,HEADLAMP S (SN)	TO REPAIR SEE LABOUR	182.00	-
1	LH MOULDING ,FR BUMP (SN)	DEFORMED	116.00	116.00
			5,335.00	1,318.00
<u>LABOUR</u>				
	ZERTONA PAINT PROTECTION .		550.00	550.00
	DIAGNOSTIC /SCANNING.		250.00	250.00
	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS.		100.00	80.00
	TO REMOVE AND REINSTALL RAD & A/C TO GIVE WAY ACCESS REPAIR ON FRONT ACCIDENT AFFECTED AREAS .	NOT NECESSARY	180.00	-

Report Ref No. CC4/FCI20000673/Hea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE FRONT BUMPER ,REINFORCEMENT ,ETC - REPAIR UPR & LH SUPPORT PANEL STRAIGHTEN ,REFORM ,ALIGN ON FRONT ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF UPR LH PANEL ,HEADLA AND UPR PANEL ,HEADLAMP S. SPRAY PAINTING.		2,400.00	1,200.00
			1,260.00	840.00
			4,740.00	2,920.00
GRAND TOTAL			10,075.00	4,238.00
RECOMMENDED COST OF REPAIRS				4,238.00

Report Ref No. CC4/FCI20000673/Hea3q2

LEE HOCK ANN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 9204D

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 9204D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

