

Section A - Accident Details

Registration Number	SHC4198B
Case Reference Number	TAX/01/20/2031
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LEW SING LIANG (LIU XINGLIANG)
Type of Accident	Head To Side
Accident Date and Time	8/1/2020 6:46 AM
Accident Reported Date and Time	8/1/2020 10:46 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	8/1/2020 6:48 AM
Replacement Vehicle issued?	No
Job Card Number	24105221
Special Instruction to ARC,if any	TOWED \$40 / TP
Prepared Date and Time	8/1/2020 5:53 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,026.00	\$550.00
Total Spray Cost	\$1,872.00	\$600.00
Total Spare Part Cost	\$16,323.17	\$7,260.17
Total Other Cost	\$396.00	\$110.00
TOTAL COST	\$19,617.17	\$8,520.17 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Fong Soon Loh	Sun Pin (LKK) / Ill
ARC / Surveyor Sign Off Date	13/01/2020 5:28 PM	13/01/2020 1:16 PM
Signature		
Remarks	Total number of repair days = 4 days. SUP = + 1 day.	P/P Repair, before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2001-0355	Invoice Number	
Quotation Date	24.01.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$676.00	\$400.00
ADDITIONAL JOB TO REPAIR FRONT PROTION	\$350.00	\$150.00
Total Labour	\$1,026.00	\$550.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$0.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$378.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,872.00	\$600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TOWING CHARGE	\$56.00	\$40.00
Total Other Costs	\$396.00	\$110.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		5339547040	SEAL, HOOD TO FR END	0.00	\$24.40	0.00	\$0.00	Replace	Check	X SVC
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	/ mis
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	/ cru
		5211447190	BRACKET, FR BUMPER	0.00	\$99.80	0.00	\$0.00	Replace	Check	X SVC
		7531047060	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.33	Replace	Replace	/ cru
		5311247240	GRILLE, RADIATOR	1.00	\$165.00	25.00	\$123.75	Replace	Replace	/ cru
		5216116010	CLIPS PIECE, FRT & RR BUMPER	1.00	\$1.50	25.00	\$1.13	Replace	Replace	/ nec
		5253550060	RETAINER, FR BUMPER, LH & RH	0.00	\$8.50	0.00	\$0.00	Replace	Check	X SVC
		5142047030	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Check	X SVC

	5144747030	COVER, ENGINE UNDER CENTER	0.00	\$94.50	0.00	\$0.00	Replace	Check	X	SVC
	5144247030	COVER, ENGINE UNDER, REAR	0.00	\$36.50	0.00	\$0.00	Replace	Check	X	SVC
	5310147080	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace		Cra
	8118547691	UNIT , HEADLAMP , LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check	X	SVC
	8114547691	UNIT , HEADLAMP , RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace		cru
	8105647690	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X	SVC
	8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X	SVC
	8121047020	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given	X	SVC
	8122047020	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given	X	SVC
	5202147110	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check	X	SVC
	5261147140	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	X	SVC
	5320247901	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given	X	SVC
	5320347901	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given	X	SVC
	5302847010	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Not Given	X	SVC
	5211947962	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace		cru
	5211547050	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Check	X	SVC
	5211647050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Check	X	SVC
	5212747907	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08	Replace	Replace		Scatched
	5212847906	COVER, FR BUMPER LH	1.00	\$28.10	25.00	\$21.08	Replace	Replace		Scatched
	5211447190	BRACKET, FR BUMPER	0.00	\$99.80	0.00	\$0.00	Replace	Check	X	SVC
	5210347010	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given	X	SVC
	5210247020	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given	X	SVC
	5213247010	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Check	X	SVC
	5261847090	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Check	X	SVC
	5380147080	FENDER SUB-ASSY, FR , RH	0.00	\$933.10	0.00	\$0.00	Replace	Not Given	X	SVC
	5380247100	FENDER SUB-ASSY, FR , LH	0.00	\$933.10	0.00	\$0.00	Replace	Not Given	X	SVC
	5387547070	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Check	X	SVC
	5387647110	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Check	X	SVC
	5330147110	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.80	Replace	Replace		cru
	5341047130	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X	SVC
	5342047130	HINGE ASSY, HOOD, LH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X	SVC
	5320547900	SUPPORT S/A UPPER,	0.00	\$364.90	0.00	\$0.00	Replace	Check	X	SVC
Total				\$15,711.80		\$3,922.51				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		5211447190	BRACKET, FR BUMPER	1.00	\$99.80	25.00	\$74.85	Replace	Replace	Cracked
		8118547691	UNIT , HEADLAMP , LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	Cracked
		5202147110	REINFORCEMENT FRONT UPPER	1.00	\$691.10	25.00	\$518.33	Replace	Replace	Bent
		5261147140	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace	Crushed
		5321347050	SUPPORT, RADIATOR UPPER RH	1.00	\$76.70	25.00	\$57.53	Replace	Replace	Bent

	53214470 50	SUPPORT, RADIATOR UPPER LH	1.00	\$76.70	25.00	\$57.53	Replace	Replace	Bent
	53205479 00	SUPPORT S/A UPPER,	1.00	\$364.90	25.00	\$273.68	Replace	Replace	Bent
Total				3,938.40		3,337.66			

17,899.80

22,944.20#

7260.17
 + 550.00
 + 710.00

 8520.17