

First Capital



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLU 481 S

Not Authorized
Resurvey By paint

Parts	(a) Cost / List Price Items	\$	11,002.97
	Plus/Less 25%	\$	2,750.74
	Total of Cost / List	\$	8,252.23
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	700.00
Total Parts Cost		\$	8,952.23
Labour		\$	3,490.00
Total		\$	12,442.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 10/1/2020 at 10am

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 07 day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$

(e) Signature of surveyor : De Date: 10/1/2020



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLU 481 S**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FUX03576160**

Submit By : **SERENCE**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>Bu</i>	1	\$450.80		<i>✓</i>
2	Front bumper clip <i>bu</i>	10	\$40.00		<i>✓</i>
3	Front bumper side retainer LH	1	\$107.20		<i>✓</i>
4	LH front fender <i>Bu</i>	1	\$868.70		<i>✓</i>
5	LH front fender undershield <i>CM</i>	1	\$195.60		<i>✓</i>
6	LH front fender undershield clip <i>bu</i>	10	\$25.00		<i>✓</i>
7	LHF fender wording "HYBRID" <i>bu</i>	1	\$44.17		<i>✓</i>
8	LH front rim <i>nd</i>	1	\$1,555.10		<i>✓</i>
9	LH front tyre	1	\$350.00	S.N	<i>?</i>
10	LH front hub cap <i>nd</i>	1	\$195.65		<i>✓</i>
11	LH side skirt <i>CM</i>	1	\$721.50		<i>✓</i>
12	LH front door <i>nd/wap</i>	1	\$1,121.75		<i>✓</i>
13	LH front door hinge top	1	\$78.30		<i>?</i>
14	LH front door hinge bottom	1	\$78.30		<i>?</i>
15	LH front door weatherstrip <i>bu</i>	1	\$211.69		<i>X</i>
16	LHF door glass outer moulding <i>bu</i>	1	\$122.95		<i>X</i>
17	LHF power window motor	1	\$543.25		<i>?</i>
18	LHF power window regulator	1	\$211.78		<i>?</i>
19	LH rear door <i>nd/wap</i>	1	\$1,211.40		<i>✓</i>
20	LH rear door hinge top <i>R</i>	1	\$78.34		<i>X</i>
21	LH rear door hinge bottom <i>R</i>	1	\$78.34		<i>X</i>
22	LH rear door weatherstrip <i>bu</i>	1	\$198.70		<i>X</i>
23	LHR door glass outer moulding <i>bu</i>	1	\$107.80		<i>X</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :	SLU 481 S
Make & Model :	TOYOTA PRIUS
Chassis No :	JTDKB3FUX03576160

Submit By	:	SERENCE
Year Manufacture	:	2017
Engine No.	:	0

Cost / List

[illegible]

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

