

Lion City Rentals Pte Ltd  
CARROS CENTER  
60 JALAN LAM HUAT #04-01 S(737869)  
Main +65 62524991

Ms LONPAC Insurance Bhd  
Date: 6/1/2020  
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLP253K  
Chassis No: JM6BM42A8H0153569  
MAKE / MODEL: Mazda 3 Sedan 1.5 AT  
DATE OF ACCIDENT: 03/01/2020  
YOUR INSURED VEHICLE NUMBER: XE1092S  
MILEAGE: 188305 km

|        | PARTS DESCRIPTION         | QTY | UNIT PRICE | LIST PRICE |
|--------|---------------------------|-----|------------|------------|
| 1      | Rear bumper / CR4         | 1PC | \$1,129.00 | \$1,129.00 |
| 2      | Rear bumper reinforcement | 1PC | \$564.20   | \$564.20   |
| 3      | Rear bumper LH retainer   | 1PC | \$58.15    | \$58.15    |
| 4      | Rear bumper RH retainer   | 1PC | \$58.15    | \$58.15    |
|        | Tail Lamp / CRA 535-W     |     |            | \$1,809.50 |
|        | 10% DISCOUNT S\$:         |     |            | \$180.95   |
|        |                           |     |            | \$1,628.55 |
| S/Nett |                           |     |            |            |
| 1      | Reverse sensor            |     |            | \$240.00   |
| 2      | Rear bumper clips / Nec   |     |            | \$100.00   |
|        | Total                     |     |            | \$340.00   |

LABOUR CHARGES

- To labour charge for removing rear bumper out and rear end panel to facilitate repairs and replacement of damaged parts
- 1 \$600.00 200 250
- 2 To respray rear bumper and rear boot
- \$900.00 200 400

|                   |            |
|-------------------|------------|
| LABOUR TOTAL S\$: | \$1,500.00 |
| TOTAL S\$:        | \$3,128.55 |
| 7% GST            | \$219.00   |
| GRAND TOTAL S\$:  | \$3,347.55 |

Repair day - 3 days.  
Lump Sum Repair P/P,  
After spray photo.

Sun Pin (CLKL)  
07/01/2020  
TP without prejudice

1,664  
- 20%  
P = 1,331.2  
N = 30  
L = 650  
2,011.2  
P/P \$ 2,011.2  
3 days.

1,664-W  
332.50  
1,331.20  
100-W

650-W  
2,081.20  
Net

## Oi Sun Pin (LKK Auto)

---

**From:** Siak Tong Sim <siaktong@lioncityrentals.com.sg>  
**Sent:** Wednesday, 26 February, 2020 4:46 PM  
**To:** Oi Sun Pin (LKK Auto)  
**Subject:** Re: Final Bill: SLP253K

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Sun Pin  
Ok confirm Part By Part \$2,011.20/3 days


**Regards**

**S.T.Sim (65-97422188)**

**Manager**

**Accident Reporting Center**

60 Jalan Lam Huat  
#04-35/36 Carros Centre  
Singapore 737869



On Wed, Feb 26, 2020 at 4:37 PM Oi Sun Pin (LKK Auto) <[sunpin@lkkauto.com](mailto:sunpin@lkkauto.com)> wrote:

Hi Mr Sim,

Kindly refer the finalize amount is \$2,011.20. Repair day 3 days. (P/P, before gst).

Thank you.

Best Regards,

**Oi Sun Pin** | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: [Sunpin@lkkauto.com](mailto:Sunpin@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)