

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms LONPAC Insurance Bhd
Date: 6/1/2020
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLP253K
Chassis No: JM6BM42A8H0153569
MAKE / MODEL : Mazda 3 Sedan 1.5 AT
DATE OF ACCIDENT : 03/01/2020
YOUR INSURED VEHICLE NUMBER :XE1092S
MILEAGE : 188305 km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear bumper / CR4	1PC	\$1,129.00	\$1,129.00
2	Rear bumper reinforcement ?	1PC	\$564.20	\$564.20
3	Rear bumper LH retainer X	1PC	\$58.15	\$58.15
4	Rear bumper RH retainer X	1PC	\$58.15	\$58.15
	Tail Lamp / CRA			\$1,809.50
	10% DISCOUNT S\$:			\$180.95
				\$1,628.55
S/Nett				
1	Reverse sensor X			\$240.00
2	Rear bumper clips / Nec			\$100.00
	Total			\$340.00

LABOUR CHARGES

1	To labour charge for removing rear bumper out and rear end panel to facilitate repairs and replacement of damaged parts	\$600.00	200250
2	To respray rear bumper and rear boot	\$900.00	200400
LABOUR TOTAL S\$:		\$1,500.00	
TOTAL S\$:		\$3,128.55	
7% GST		\$219.00	
GRAND TOTAL S\$:		\$3,347.55	

Repair day - 3 days.
Lump Sum Repair
After spray photo.

Sun Pin (LKK)
07/01/2020
TP without prejudice