

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not authorized
Respray B4 pain
7 days*

To: First Capital Insurance Limited

Accident Date : 04.01.2020

Third Party
Policy No: _____
Date: 09.01.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda City" Reg. No. SLZ5942U Claiming Against Your Insured Veh. No. SHC8389R			
1pc	Rear Door LH		By 828.19 ✓
1pc	Rear Door Sticker		na 34.20 ✓
1pc	Rear Door Weatherstrip		clip na 95.52 ✓
1pc	Rear Door Lower Rubber Seal		na 29.40 ✓
12pcs	Rear Door Inner Trim Board Clips	5.70	na 68.40 X
1pc	Rear Fender LH		By 1,109.20 ✓
1pc	Rocker Panel LH		R 496.00 X
1pc	Rear Bumper		myent 555.84 ✓
10pcs	Rear Bumper Clips	5.50	na 55.00 ✓
1pc	Rear Bumper Corner Retainer LH		na 23.90 X
1pc	Rear Bumper Reflection Outer Cover LH		na 42.90 ✓
1pc	Rear Windscreen Moulding		na 149.20 ✓
1pc	Rear Wheel Bearing		na 281.90 ?
	Less 20%		3,769.65
			753.93
			3,015.72
1pc	Rear Wheel Rim <i>Pr?</i>		na 690.20 SN ✓
1pc	Rear Door Inner Insulation		na 120.00 SN ?
1pc	Rear Windscreen Sealant		na 50.00 SN ✓
1pc	Rear Windscreen Sealer		na 30.00 SN ✓
1pc	Rear Windscreen Fastener		na 50.00 SN 301
1pc	Rocker Panel Chip Resistant Primer		na 180.00 SN
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		120.00 601
	To Dismantle / Refit Rear Windscreen Glass		160.00 1201
	To Dismantle / Refit Roof Lining		150.00 } 001
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 }
	To Conduct Computerize Wheel Alignment Test		80.00 601
	To Supply Rear Fender Body Sealant		60.00 301
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 601
		C/F	4,885.92

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Accident Date : 04.01.2020

Policy No: Third Party

Date: 09.01.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda City" Reg. No. SLZ5942U Claiming Against Your Insured Veh. No. SHC8389R		
		B/F	4,885.92
	To Conduct Computerize Wheel Alignment Test	<i>Repair</i>	80.00 X
	To Dismantle / Refit Fuel Tank Inlet Hoses & Piping		100.00 <i>601</i>
	Labour Charge - Panel Beating, Repairing Of Fender Inner Panel, Rocker Panel, Front Door etc. Cnt, Weld Rear Fender and Parts Replacement		1,400.00 <i>9001</i>
	To Respray Affected Areas		1,200.00 <i>8001</i>
		Total :	<u><u>7,665.92</u></u>