

# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Authorized  
 Purvey B4 pain  
 7 days*

**5397.37**

To: First Capital Insurance Limited  
 \_\_\_\_\_  
 \_\_\_\_\_  
 Accident Date : 04.01.2020

Policy No: \_\_\_\_\_ Third Party  
 Date: 09.01.2020

Specialised in Car Painting, Welding,  
 Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 額 \$ cts.
Estimate Cost of Repair to "Honda City" Reg. No. SLZ5942U Claiming Against Your Insured Veh. No. SHC8389R			
1pc	Rear Door LH		B1 828.19 ✓
1pc	Rear Door Sticker		M 34.20 ✓
1pc	Rear Door Weatherstrip		clip M 95.52 ✓
1pc	Rear Door Lower Rubber Seal		L 29.40 ✓
12pcs	Rear Door Inner Trim Board Clips	5.70	M 68.40 X
1pc	Rear Fender LH		B1 1,109.20 ✓
1pc	Rocker Panel LH		R 496.00 X
1pc	Rear Bumper <b>483.70</b>		subject 555.84 ✓
10pcs	Rear Bumper Clips	5.50	M 55.00 ✓
1pc	Rear Bumper Corner Retainer LH		S 23.90 X
1pc	Rear Bumper Reflection Outer Cover LH		C 42.90 ✓
1pc	Rear Windscreen Moulding		M 149.20 ✓
1pc	Rear Wheel Bearing		B1 281.90 ✓
	Less 20%		3,769.65
			753.93
			3,015.72
1pc	Rear Wheel Rim <b>P1? 500SN</b>		nd 690.20 SN ✓
1pc	Rear Door Inner Insulation		NN X 120.00 SN ✓
1pc	Rear Windscreen Sealant		40SN 50.00 SN ✓
1pc	Rear Windscreen Sealer		M 30.00 SN ✓
1pc	Rear Windscreen Fastener		M 50.00 SN 30SN ✓
1pc	Rocker Panel Chip Resistant Primer		M 180.00 SN ✓
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		120.00 60L
	To Dismantle / Refit Rear Windscreen Glass		160.00 120L
	To Dismantle / Refit Roof Lining		150.00 } 00L
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 }
	To Conduct Computerize Wheel Alignment Test		80.00 60L
	To Supply Rear Fender Body Sealant		60.00 30L
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 60L
		C/F	4,885.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey vehicle after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary material must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 Accident Date : 04.01.2020

Policy No: Third Party  
 \_\_\_\_\_  
 Date: 09.01.2020

Specialised in Car Painting, Welding,  
 Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda City" Reg. No. SLZ5942U Claiming Against Your Insured Veh. No. SHC8389R		
	To Conduct Computerize Wheel Alignment Test	B/F <i>Revised</i>	4,885.92
	To Dismantle / Refit Fuel Tank Inlet Hoses & Piping		80.00 <i>X</i>
	Labour Charge - Panel Beating, Repairing Of Fender Inner Panel, Rocker Panel, Front Door etc. Cnt, Weld Rear Fender and Parts Replacement		100.00 <i>601</i>
	To Respray Affected Areas		1,400.00 <i>9001</i>
			1,200.00 <i>8001</i>
		<b>Total :</b>	<u><u>7,665.92</u></u>