

ASS. REC. BY:

REF: CS/SMD 20000712/Vgf3n2 Special Instruction:

Surveyor: Mar(uz)

**ASSIGNMENT (Office)**

From (Person): Grace Teo of SMD Date/Time: 13.1.2009 9.43a.m

Estimated Cost: Bill to:

**OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: SGR 2222 Insured: FBQ 91025

at Workshop m/s Joo Hak Tee Tel: 67 431913

of BIK 3007 Ubi road 1 A01-406

Policy No: Claim No: (MT1) 2000179 / SH

Sum Insured: Excess:

Make of Veh: D.O.A 9.1.2009

(Client's Record)

CA / REV / REP. / REV 24 HRS

map

H.O.D. Endorsement:

Date/Time: 13.1.2009 9.56a.m Person Contacted: Shi Min Vehicle: IN/OUT

| Date/Time         | Action/Instruction (✓) Estimate                            |
|-------------------|------------------------------------------------------------|
|                   | SGR 2222 - CC3/A14 12/11/08/ R1 E0392 1209-10/0/2009       |
|                   | FBQ 91025 - X                                              |
| 14/01/2009 2.26pm | Informed Grace Teo, we are pending estimate from repairer. |
| 20/01/2009 9.24am | revised to Huang Guang Yi by email.                        |
|                   |                                                            |
|                   |                                                            |

5/1/121 waf  
ASS. REC. BY: Marcus

REF:

SMD/

ASSIGNMENT

From: Date: :  
Estimated Cost:  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: SAR2222  
at Workshop m/s: JMK  
of  
Insured:  
Policy No:  
Claims No:  
Sum Insured: Excess:  
(Client's Record)  
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: 110k.  
IDAC Accident Report: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: 6 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SAR2222 Yr Regn: 9 16  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA)  
Make: Lexus ES250 CC 2494  
Colour: Black A/C Insured / Std / NI / NA  
Sp. Reading: 56419 T/Radio: Insured / Std / NI / NA  
Eng/No:  
C/No: JTHBJ166102094116  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 215/55R17  
R:  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: 6 mm Rear: 6 mm  
R/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 9/1/20 D.O.I. 13/1/20  
Survey held at:  
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or  
N/S Rec  
The U/C / Chassis frame / body structure affected due to collision.

Date / Time Action / Instruction

17/1/20 4/5 27A 75080  
6250 Confirmed with Shimizu (Ref # 11060.37, 647.)

RECEIVED 20 JAN 2020

Date/Time, File Pass to? ☐ : Prelim. Report

1) 20/1 transfer ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photo:

Other:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL:

Report Format :

Lump Sum / I.B.I. (\$

7P  
6250

450



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD2000179/SYH

Date: 20<sup>th</sup> January 2020

Our Ref: CS/SMO20000712/Uqf3

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SGR 222Z**

We thank you for the instruction on 13/01/2020.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/01/2020 at the premises of M/s JOO HAK KEE and have the following to report:-

|                          |                                  |
|--------------------------|----------------------------------|
| Workshop Estimate Amount | : S\$ <u>17,310.37</u>           |
| Revised Estimate Amount  | : S\$ <u>6,250.00 (Lump Sum)</u> |
| "Check" Items Amount     | : S\$ <u>-</u>                   |
| Market Value             | : S\$ <u>-</u>                   |
| LTA Reimbursement Value  | : S\$ <u>-</u>                   |
| Nett Value               | : S\$ <u>-</u>                   |

Description of Damage:  
The vehicle sustained damages at the  
n/s rear portion.



Comments/ Present Status:  
Damages consistent.  
We have NOT authorize repair.

Yours faithfully

Marcus Chua  
Licensed Appraiser

**Nivitha (LKK Auto)**

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Monday, 13 January 2020 9:48 AM  
**To:** shimin poh; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'  
**Cc:** Hwang, Shiang Yi; Ye, Yong Kang Melvin; Henry, Irene James; sur@lkkauto.com  
**Subject:** CMTD2000179/SYH - LKK/ FBQ9102S & SGR222Z DOA : 09/01/2020 - VEH IN  
**Attachments:** SAS REPORT.pdf

Our Reference: CMTD2000179/SYH  
Your Reference: SGR222Z

Date: 13/01/2020

**Without Prejudice**  
**EMAIL ONLY**

OUR Email: [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

**Attention:**  
**M/S JOO HAK KEE AUTO PTE LTD**

Dear Bridget,

**ACCIDENT INVOLVING FBQ9102S & SGR222Z ON 09.01.2020**

We refer to your email reply of today.

We will appoint Mr. Marcus Chua of LKK Auto to conduct the survey.

Hi LKK AUTO,

Please make the arrangement to survey for **SGR222Z** on a without prejudice basis and admission of liability.

Please revert your report upon completion of survey to my colleague, Ms. Shiang Yi.

Thank you.

Please note our office will be closed on 24<sup>th</sup> January 2020 (Friday). Business will resume on 28<sup>th</sup> January 2020 (Tuesday).

Wishing you a happy and prosperous Lunar New Year, filled with wealth, good health and success always!

Best Regards  
**Grace Teo**  
Claims Division

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** shimin poh <[shimin@jhk.com.sg](mailto:shimin@jhk.com.sg)>

**Sent:** Monday, January 13, 2020 9:36 AM

**To:** Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>

**Subject:** Re: CMTD2000179/ SYH - PRI/ FBQ9102S & SGR222Z DOA : 09/01/2020 \THIRD PARTY DIRECT SETTLEMENT

Hi,

We would like to choose Marcus from lkk

Car is in the workshop, surveyor can come by to survey now

On Mon, 13 Jan 2020, 9:00 AM Teo, Grace, <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)> wrote:

Our Reference: CMTD2000179/SYH

Your Reference: SGR222Z

Without Prejudice

Date: 13/01/2020

EMAIL ONLY

OUR Email: [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

Attention:

M/S JOO HAK KEE AUTO PTE LTD

Dear Bridget,

ACCIDENT INVOLVING FBQ9102S & SGR222Z ON 09.01.2020

We refer to your Notice of Accident dated 10/01/2020.

Please be informed that Ms. Hwang Shiang Yi is the handler of this case who can be contacted at 63295 205/  
[shiangyi.hwang@sompo.com.sg](mailto:shiangyi.hwang@sompo.com.sg).

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

|   | Motor Surveyor       | Surveyor                  | Selection (Indicate as tick) |
|---|----------------------|---------------------------|------------------------------|
| 1 | Raleigh Services     | Andrew Ow Yong            |                              |
|   |                      | Vincent Ng                |                              |
| 2 | LKK Auto Consultants | Kenneth Kong (North area) |                              |
|   |                      | Marcus Chua (East area)   |                              |
|   |                      | Mohd Rasul (West area)    |                              |
|   |                      | Mohd Taufikh (West area)  |                              |
| 3 | Priority Services    | Jimmy Lee                 |                              |
|   |                      | Lawrence Ng               |                              |
|   |                      | Jeffrey Ong               |                              |

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Please note our office will be closed on 24<sup>th</sup> January 2020 (Friday). Business will resume on 28<sup>th</sup> January 2020 (Tuesday).

Wishing you a happy and prosperous Lunar New Year, filled with wealth, good health and success always!

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @



or



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** shimin poh <[shimin@jhk.com.sg](mailto:shimin@jhk.com.sg)>

**Sent:** Friday, January 10, 2020 5:08 PM

**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>

**Subject:** NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SGR222Z/FBQ9102S DOA : 09/01/2020

Dear Sir/Mdm,

Kindly arrange pre-repair survey for the above and if possible would like to do direct settlement.

Please provide us your list of surveyors for our selection.

Attached is the accident report for your reference and we're currently in the midst of preparing the estimate.

Thank you and hope to hear from you soon.

Thank You !

Bridget Poh (Shimin)

Joo Hak Kee Auto Pte Ltd

Blk 3007 Ubi Road 1

#01-406 Singapore 408701

Office: 67431913

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 20 January 2020 9:24 AM  
**To:** 'Teo, Grace'; 'Hwang, Shiang Yi'  
**Cc:** 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; SUR  
**Subject:** RE: CMTD2000179/SYH - LKK/ FBQ9102S & SGR222Z DOA : 09/01/2020 - VEH IN  
**Attachments:** CSSMO20000712Uqf3.pdf

Dear Shiang Yi,

Enclosed herewith preliminary advice of SGR 222Z.

*Wishing you a Happy and Prosperous Lunar New Year*

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Tuesday, 14 January 2020 2:26 PM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Hwang, Shiang Yi' <[shiangyi.hwang@sompo.com.sg](mailto:shiangyi.hwang@sompo.com.sg)>; 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD2000179/SYH - LKK/ FBQ9102S & SGR222Z DOA : 09/01/2020 - VEH IN

Dear Grace,

Please be informed that we have inspected the vehicle SGR 222Z on 13/01/2020.

We are pending for estimate from repairer.

*Wishing you a Happy and Prosperous Lunar New Year*

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Monday, 13 January 2020 11:27 AM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Hwang, Shiang Yi' <[shiangyi.hwang@sompo.com.sg](mailto:shiangyi.hwang@sompo.com.sg)>; 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD2000179/SYH - LKK/ FBQ9102S & SGR222Z DOA : 09/01/2020 - VEH IN

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 14 January 2020 2:26 PM  
**To:** 'Teo, Grace'; assignments  
**Cc:** 'Hwang, Shiang Yi'; 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; SUR  
**Subject:** RE: CMTD2000179/SYH - LKK/ FBQ9102S & SGR222Z DOA : 09/01/2020 - VEH IN

Dear Grace,

Please be informed that we have inspected the vehicle SGR 222Z on 13/01/2020.

We are pending for estimate from repairer.

*« Wishing you a Happy and Prosperous Lunar New Year »*

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Sent:** Monday, 13 January 2020 11:27 AM

**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** 'Hwang, Shiang Yi' <[shiangyi.hwang@sompo.com.sg](mailto:shiangyi.hwang@sompo.com.sg)>; 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>;

'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: CMTD2000179/SYH - LKK/ FBQ9102S & SGR222Z DOA : 09/01/2020 - VEH IN

Dear Sir/Mdm,

Thank you for the assignment.

*« Wishing you a Happy and Prosperous Lunar New Year »*



Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 985H

**Vehicle Details**

Vehicle No.: SGR222Z

Vehicle to be Exported: No

Intended Deregistration Date: 13 Jan 2020

Vehicle Make: TOYOTA

Vehicle Model: LEXUS ES250 LUXURY A/T S/R

Primary Colour: Black

Manufacturing Year: 2016

Engine No.: 2ARF243654

Chassis No.: JTHBJ1GG102094116

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$40,888.00

Original Registration Date: 28 Sep 2016

First Registration Date: 28 Sep 2016

Transfer Count: 0

Actual ARF Paid: \$49,244.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Sep 2026

PARF Rebate Amount: \$36,933.00

**Intended COE Rebate Details**

COE Expiry Date: 27 Sep 2026

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$56,889.00

COE Rebate Amount: \$38,147.00

**Total Rebate Amount: \$75,080.00**

The information contained herein is correct as at 13 Jan 2020

OK

Not Approved  
 2/5/20  
 6/2/20  
 13/1/20  
 The photo attached

ATTN: MOTOR CLAIMS DEPARTMENT  
 OWNER: Leong Lai Yong  
 INSURER: Sampo Insurance Singapore Pte Ltd  
 POLICY NO: 5103649202-01  
 DOA: 09/01/2020

**REPAIR ESTIMATE**

Est No. : EST20010021  
 Date : 11-Jan-20  
 Vehicle Num : SGR222Z  
 Make/Model : Lexus ES250 Luxury  
 Chassis # : JTHBJ1GG102094116  
 Engine # : 2ARF243654  
 Yr. Of Manu : 2016

| No.                        | Description                    | Qty   | U/P     | Amt        |
|----------------------------|--------------------------------|-------|---------|------------|
| <b>Section: LIST ITEMS</b> |                                |       |         |            |
| 1                          | Rear Bumper                    | 1.00  | 1075.10 | 1075.10 ✓  |
| 2                          | Rear Bumper Reinforcement      | 1.00  | 597.10  | 597.10 X   |
| 3                          | Rear Bumper Retainer           | 2.00  | 120.24  | 240.48 12c |
| 4                          | Rear Bumper Clips              | 10.00 | 12.90   | 129.00 ✓   |
| 5                          | LH Rear Bumper Reflector       | 1.00  | 78.10   | 78.10 X    |
| 6                          | Bumper Sponge                  | 1.00  | 110.30  | 110.30 X   |
| 7                          | LH/RH Outer Taillamp           | 2.00  | 654.10  | 1308.20 ✓  |
| 8                          | LH/RH Inner Taillamp           | 2.00  | 453.25  | 906.50 X   |
| 9                          | LH/RH Fender Lamp              | 2.00  | 350.00  | 700.00 X   |
| 10                         | LH Fender                      | 1.00  | 1162.10 | 1162.10 ✓  |
| 11                         | LH Fender Inner Shield         | 1.00  | 336.10  | 336.10 ✓   |
| 12                         | LH Fender Inner Shield Garnish | 1.00  | 294.10  | 294.10 ✓   |
| 13                         | LH Fender Inner Shield Clip    | 1.00  | 12.90   | 12.90 ✓    |
| 14                         | Rear Fender Inner Trim         | 1.00  | 499.00  | 499.00 ✓   |
| 15                         | LH Wheel Bearing               | 1.00  | 880.10  | 880.10 X   |
| 16                         | Petrol Cover                   | 1.00  | 100.40  | 100.40 X   |
| 17                         | ECU PDC control unit           | 1.00  | 890.00  | 890.00 ✓   |
| 18                         | ECU Wire Harness               | 1.00  | 250.00  | 250.00 ✓   |
| 19                         | Bootlid                        | 1.00  | 876.10  | 876.10 X   |
| 20                         | Bootlid Hinge                  | 2.00  | 310.25  | 620.50 X   |
| 21                         | Bootlid "LEXUS" Logo           | 1.00  | 103.10  | 103.10 ✓   |
| 22                         | Bootlid "ES250" Emblem         | 1.00  | 98.25   | 98.25 ✓    |
| 23                         | Bootlid Top Lock               | 1.00  | 509.10  | 509.10 X   |
| 24                         | Bootlid Lower Lock             | 1.00  | 233.00  | 233.00 X   |

Continue on next page...

ATTN: MOTOR CLAIMS DEPARTMENT  
 OWNER: Leong Lai Yong  
 INSURER: Sompoo Insurance Singapore Pte Ltd  
 POLICY NO: 5103649202-01  
 DOA: 09/01/2020

# REPAIR ESTIMATE

Est No. : EST20010021  
 Date : 11-Jan-20  
 Vehicle Num : SGR222Z  
 Make/Model : Lexus ES250 Luxury  
 Chassis # : JTHBJ1GG102094116  
 Engine # : 2ARF243654  
 Yr. Of Manu : 2016

| No. | Description                 | Qty | U/P  | Amt                           |
|-----|-----------------------------|-----|------|-------------------------------|
| 25  | Bootlid Lock Stricker       | 11  | 1.00 | 220.00                        |
| 26  | Reverse Sensor Control Unit | 11  | 1.00 | 350.00                        |
| 27  | Exhaust Pipe                | 11  | 1.00 | 1307.10                       |
|     |                             |     |      | Amt S\$ 13886.63              |
|     |                             |     |      | Discount (10.00%) S\$ 1388.66 |
|     |                             |     |      | Subtotal S\$ 12497.97         |

## Section: SPECIAL NETT ITEMS

|    |                |      |        |                           |
|----|----------------|------|--------|---------------------------|
| 28 | Reverse Sensor | 4.00 | 493.10 | 1972.40                   |
|    |                |      |        | Amt S\$ 1972.40           |
|    |                |      |        | Discount (0.00%) S\$ 0.00 |
|    |                |      |        | Subtotal S\$ 1972.40      |

## Section: LABOUR

|    |                                                                |      |         |                           |
|----|----------------------------------------------------------------|------|---------|---------------------------|
| 29 | To Panel Beat on Necessary Damaged Parts                       | 1.00 | 1250.00 | 1250.00                   |
| 30 | To Sand Down, Putty and Spray Paint on Necessary Damaged Parts | 1.00 | 790.00  | 790.00                    |
| 31 | To Remove & Refit Rear Windscreen                              | 1.00 | 250.00  | 250.00                    |
| 32 | To Remove & Refit Petrol Tank                                  | 1.00 | 280.00  | 280.00                    |
| 33 | To Check Wiring                                                | 1.00 | 150.00  | 150.00                    |
| 34 | To Do 4 Wheel Alignment                                        | 1.00 | 120.00  | 120.00                    |
|    |                                                                |      |         | Amt S\$ 2840.00           |
|    |                                                                |      |         | Discount (0.00%) S\$ 0.00 |
|    |                                                                |      |         | Subtotal S\$ 2840.00      |

LIST ITEMS Subtotal S\$ 12497.97  
 SPECIAL NETT ITEMS Subtotal S\$ 1972.40  
 LABOUR Subtotal S\$ 2840.00  
**Total S\$ 17310.37**

Joo Hak Kee Auto Pte. Ltd.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                          |                             |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|-----------------------------|------------|-------------------------------------------------------------------------------------|
| SOMPO INSURANCE SINGAPORE PL                                                                                                           |                                                                                                          | Ref : CS/SMO20000712/Uqf3n2 |            |                                                                                     |
| 50 RAFFLES PLACE<br>#05-01/06<br>SINGAPORE LAND TOWERSINGAPORE 048623                                                                  |                                                                                                          | Date : 21-01-2020           |            |  |
|                                                                                                                                        |                                                                                                          | Code : SMO                  |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                          |                             |            |                                                                                     |
| Insured Veh.                                                                                                                           | FBQ 9102S                                                                                                | Veh. Inspected              | SGR 222Z   |                                                                                     |
| Policy No.                                                                                                                             |                                                                                                          | Coverage (\$)               | 0.00       |                                                                                     |
| Claim No.                                                                                                                              | CMTD2000179/SYH                                                                                          | Excess (\$)                 | 0.00       |                                                                                     |
| Assign From                                                                                                                            | GRACE TEO                                                                                                | Assign Date                 | 13/01/2020 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                          |                             |            |                                                                                     |
| Make & Model                                                                                                                           | LEXUS ES250 (A)                                                                                          | c.c                         | 2494       |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                                                   | Year of Reg.                | 2016       |                                                                                     |
| Chassis No.                                                                                                                            | JTHBJ1GG102094116                                                                                        | Colour                      | BLACK      |                                                                                     |
| Odometer                                                                                                                               | 56419                                                                                                    | Steering                    | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                                                                 | Modification                | SPORTS RIM |                                                                                     |
| General                                                                                                                                | GOOD                                                                                                     |                             |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                          |                             |            |                                                                                     |
|                                                                                                                                        | Size                                                                                                     | Make                        | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         | 215/55 R17                                                                                               | MICHELIN                    | 6 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                         | 215/55 R17                                                                                               | MICHELIN                    | 6 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 215/55 R17                                                                                               | MICHELIN                    | 6 mm       |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 215/55 R17                                                                                               | MICHELIN                    | 6 mm       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                          |                             |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.<br>DAMAGES SEE DETAILS.                                                         |                                                                                                          |                             |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                                          |                             |            |                                                                                     |
| Accident Date                                                                                                                          | 09/01/2020                                                                                               | Inspection Date             | 13/01/2020 |                                                                                     |
| Survey held at                                                                                                                         | JOO HAK KEE AUTO PTE LTD<br>3007 UBI ROAD 1 #01-406<br>KAMPONG UBI INDUSTRIAL ESTATE<br>SINGAPORE 408701 |                             |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                          |                             |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                          |                             |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                          |                             |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                          | 6 Working Days              |            |                                                                                     |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 222Z

| Qty | Description of Parts             | Condition                | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------|--------------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>      |                          |                           |                   |
| 1   | REAR BUMPER                      | DISTORTED                | 1,075.10                  | 975.10            |
| 1   | REAR BUMPER REINFORCEMENT        | NOT NECESSARY            | 597.10                    | -                 |
| 2   | REAR BUMPER RETAINER @\$120.24   | N/S BENT                 | 240.48                    | 115.00            |
| 1   | SET REAR BUMPER CLIPS            | NECESSARY                | 129.00                    | 50.00             |
| 1   | LH REAR BUMPER REFLECTOR         | NOT NECESSARY            | 78.10                     | -                 |
| 1   | BUMPER SPONGE                    | NOT NECESSARY            | 110.30                    | -                 |
| 2   | TAILLAMPS @\$654.10              | O/S CRACKED / N/S BROKEN | 1,308.20                  | 1,308.20          |
| 2   | LH/RH INNER TAILLAMP @\$453.25   | NOT NECESSARY            | 906.50                    | -                 |
| 2   | LH/RH FENDER LAMP @\$350.00      | NO SUCH PARTS            | 700.00                    | -                 |
| 1   | LH FENDER                        | BADLY DENTED             | 1,162.10                  | 1,162.10          |
| 1   | LH FENDER INNER SHIELD           | TORN                     | 336.10                    | 336.10            |
| 1   | LH FENDER INNER SHIELD GARNISH   | DISTORTED                | 294.10                    | 294.10            |
| 1   | SET LH FENDER INNER SHIELD CLIPS | NECESSARY                | 12.90                     | 12.90             |
| 1   | REAR FENDER INNER TRIM N/S       | DISTORTED                | 499.00                    | 499.00            |
| 1   | LH WHEEL BEARING                 | NOT NECESSARY            | 880.10                    | -                 |
| 1   | PETROL COVER                     | NOT NECESSARY            | 100.40                    | -                 |
| 1   | PDC CONTROL UNIT                 | CRACKED                  | 890.00                    | 878.23            |
| 1   | CONTROL UNIT WIRE HARNESS        | CRACKED                  | 250.00                    | 250.00            |
| 1   | BOOTLID                          | TO REPAIR SEE LABOUR     | 876.10                    | -                 |
| 2   | BOOTLID HINGE @\$310.25          | NOT NECESSARY            | 620.50                    | -                 |
| 1   | BOOTLID "LEXUS" LOGO             | NECESSARY                | 103.10                    | 103.10            |
| 1   | BOOTLID "ES250" EMBLEM           | NECESSARY                | 98.25                     | 98.25             |
| 1   | BOOTLID TOP LOCK                 | NOT NECESSARY            | 509.10                    | -                 |
| 1   | BOOTLID LOWER LOCK               | NOT NECESSARY            | 233.00                    | -                 |
| 1   | BOOTLID LOCK STRICKER            | NOT NECESSARY            | 220.00                    | -                 |
| 1   | REVERSE SENSOR CONTROL UNIT      | NOT NECESSARY            | 350.00                    | -                 |
| 1   | EXHAUST PIPE                     | NOT NECESSARY            | 1,307.10                  | -                 |
|     | LESS 10% DISCOUNT                |                          | -1,388.66                 | -608.21           |
|     |                                  |                          | <b>12,497.97</b>          | <b>5,473.87</b>   |

Report Ref No. CS/SMO20000712/Uqf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts                                                         | Condition               | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------------------------------------|-------------------------|---------------------------|-------------------|
|     | <b>SPECIAL NETT ITEMS</b>                                                    |                         |                           |                   |
| 4   | REVERSE SENSOR @\$493.10 (SN)                                                | N/S SHORTED (1 PC ONLY) | 1,972.40                  | 313.00            |
|     |                                                                              |                         | 1,972.40                  | 313.00            |
|     | <b>LABOUR</b>                                                                |                         |                           |                   |
|     | TO PANEL BEAT ON NECESSARY DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID. |                         | 1,250.00                  | 1,000.00          |
|     | TO SAND DOWN,PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PARTS.               |                         | 790.00                    | 750.00            |
|     | TO REMOVE & REFIT REAR WINDSCREEN.                                           |                         | 250.00                    | 120.00            |
|     | TO REMOVE & REFIT PETROL TANK.                                               |                         | 280.00                    | 60.00             |
|     | TO CHECK WIRING.                                                             |                         | 150.00                    | 50.00             |
|     | TO DO 4 WHEEL ALIGNMENT.                                                     |                         | 120.00                    | 60.00             |
|     |                                                                              |                         | 2,840.00                  | 2,040.00          |
|     | <b>GRAND TOTAL</b>                                                           |                         | <b>17,310.37</b>          | <b>7,826.87</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>  |                         |                           | <b>6,250.00</b>   |

Report Ref No. CS/SMO20000712/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.