

ASS. REC. BY:

REF: CS/CT119009448/Eyd3-1

Special Instruction:

SUMMARY

Steve

ASSIGNMENT (Office)

From (Person):

Clair Chung

of CT

Date/Time: 28.5.19 12:45 p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SU 5914B

Insured:

GBH 1502X

at Workshop m/s

F0124 Autohaus

Tel:

96775722

of NO 29 Wadlands (1080, #01-34/35)

Policy No. DMVSN 30063619000

Claim No:

SNM191202370102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25.5.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

29.5.2019 9.15 a.m.

Person Contacted:

MLA ML

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SU 5914B-X

GBH 1502X-X

Dismantle: 30/5/2019

10/1

Steve confirmed LS \$5900f; 6 days with Mike. (Ref 11, 757.73, 6670)

RECEIVED 13 FEB 2020

ASS. REC. BY:

Steve

REF CT1

ASSIGNMENT

From: _____ Date: 29.5.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJU 5914B

at Workshop m/s For=9 Autohaus

of MD 39 Wyndland close, # 01-34/35

Insured: _____

Policy No. _____


Claims No. _____

Sum insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJU 5914B Yr Regn: 16/12/09

Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota wish C.C. 1797

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 156902 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2GE 2090 29155

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 25/5/19 D.O.L. 29/5/19

Survey held at Feb 29

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 21,900 Repair Range 6K-7K, 7 days

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

3 + RS, \$

Photos

Others

TOTAL

Report Format: PRS.

Lump Sum / L.B.I. (\$) _____

150

150

>Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 2768E

Vehicle Details

Vehicle No.: SJU5914B
Vehicle to be Exported: No
Intended Deregistration Date: 05 Jun 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8X A
Primary Colour: Grey
Manufacturing Year: 2009
Engine No.: 2ZR0481342
Chassis No.: ZGE200028155
Maximum Power Output: 106.0 kW (142 bhp)
Open Market Value: \$22,564.00
Original Registration Date: 16 Dec 2009
First Registration Date: 16 Dec 2009
Transfer Count: 0
Actual ARF Paid: \$22,564.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Dec 2019
PARF Rebate Amount: \$11,282.00

Intended COE Rebate Details

COE Expiry Date: 15 Dec 2019
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$19,003.00
COE Rebate Amount: \$1,001.00
Total Rebate Amount: \$12,283.00

The information contained herein is correct as at 27 May 2019


OK

VEHICLE NO: SJU 5914B

MAKE & MODEL: TOYOTA WISH

DATE OF ACCIDENT	25 / 05 / 2019
TIME OF ACCIDENT	12.50 AM (PM)
LOCATION OF ACCIDENT	TAMPINES LINK
Exact Purpose use during accident	
NAME OF OWNER	QI FEI AUTO PTE LTD
TELP NO	
NRIC	201832768 E
CLAIM TYPE	OD / <u>THIRD PARTY</u> / Reporting Only
PRIVATE HIRE	YES (NO)?
INSURANCE CO.	
TYPE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft
POLICY NO.	
NAME OF DRIVER	As above / If No: ELSON YEO CHONG JIN
NRIC	S 9243045F Any passengers:
DATE OF BIRTH	27 / 10 / 1992
OCCUPATION	Outdoor / Indoor
DATE OF DRIVING PASS	/ /
GENDER	(Male) / Female
CONTACT NO.	8333 7446 Office: Home:
ADDRESS	BLK 243 BISHAN ST 22 #04-280 (570043)
DRIVER HAVE ANY OWN Vehicle	NO / If yes: Reg No:
RELATIONSHIP	Employee / If No:
WEATHER CONDITION	Clear / Raining / Other:
ROAD SURFACE	Dry / Wet / Other:
ANY INJURIES	No / If yes: Who?
CONTACT NO.	
POLICE REPORT	No / If yes: Where?
VEHICLE B NO.	G2H 1502X Any Passenger:
NAME	MUHAMMED ISKANDAR BIN ZAKARIA
CONTACT NO.	
VEHICLE C NO.	
VEHICLE D NO.	Any Passenger:
VEHICLE E NO.	Any Passenger:
VEHICLE F NO.	Any Passenger:
ANY WITNESS	Any Passenger:
WITNESS CONTACT NO.	
Have you been approach by unknown person soliciting (s) / offering accident claims assistance?	YES / NO
PARTICULAR WORKSHOP	
TELP NO	
CONTACT PERSON	
FAX NO.	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25 May 2019 at around 1.00 pm, I was travelling along ~~Campuses Ave 10~~ ^{North Drive Link} towards Ave 10. My vehicle was stationary waiting to move off. Suddenly, I felt a collision impact from the rear. Vehicle B collided onto the rear of my vehicle. I felt aching pain on my neck & back after the impact.

Vehicle A SJU 5914 B.

Vehicle B. GBH 1502X

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



G/20190526/7023

1 of 2

POLICE REPORT (NP299)

Report No. G/20190526/7023

Police Station Of Origin
Bedok Division HQ
30 Bedok North Road SINGAPORE 469676
Tel No:1800-2440000

Date/Time Report Made 26/05/2019 23:51	Vide Report No.	Station Diary No.
Name Of Informant YEO CHONG JIN, ELSON	Address APT BLK 243 BISHAN STREET 22 #04-280 SINGAPORE 570243	
ID Type / ID No. NRIC NO / S9243045F	Contact No. Home/Office:	Mobile: 83337446
Nationality SINGAPORE CITIZEN	Email Address elson.yc@gmail.com	
Occupation Salesperson (door-to-door)	Sex Male	Age 26
Institution/School Name	Date of Birth 27/10/1992	Race Chinese
Date/Time Of Incident 25/05/2019 12:50 - 25/05/2019 13:00	Location Of Incident TAMPINES LINK	

Brief details.

I(ELSON YEO CHONG JIN S9243045F) was driving a Toyota Wish (SJU5914B) along Tampines Link when there was a car in front of me that came to a stop as there was a pedestrian crossing the street. So as I was the car behind, I came to a stop as well.

After being stationary, I looked into the rear mirror and saw a Toyota Hiace Van (GBH1502X)(Driven by MUHAMMAD ISKANDAR BIN ZAKARYA S9411010F) moving at a fast speed with no intention of slowing down. So I braced for impact and he collided into my vehicle's rear.

I suffered whiplash but no visible injuries were incurred.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/05/2019 23:51
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20190526/7023

The driver then proceed to step out of his vehicle and apologized to me as i stepped out of my vehicle as well. Then we took photos of the accident site and exchanged particulars and proceed with our claims. I have no other people in my vehicle at the time of the accident, the other party as well.

Subjects Involved			
Victim			
Person Name	YEO CHONG JIN, ELSON		
ID Type	NRIC NO	ID No	S9243045F
Gender	Male	Age	26
Race	Chinese	Language	English
Occupation	Salesperson (door-to-door)	Address Type	
Address	APT BLK 243 BISHAN STREET 22 #04-280 SINGAPORE 570243	Mobile No	83337446
Is Informant A Victim?	Yes		
Person Name YEO CHONG JIN, ELSON (Informant)			

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/05/2019 23:51
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

Steve Chen (LKK Auto)

From: enquiry@forzaauto.sg
Sent: Friday, January 10, 2020 2:16 PM
To: Steve Chen (LKK Auto)
Subject: RE: SJU5914B, Estimate for vehicle SJU5914B]

Dear Steve,

We shall agreed to the finalize of \$5900.
Shall prepare the LOD and submit to insurance directly

Thanks
Mike

----- Original Message -----

Subject: SJU5914B, Estimate for vehicle SJU5914B]
From: "Steve Chen (LKK Auto)" <SteveChen@lkkauto.com>
Date: Mon, October 14, 2019 1:49 pm
To: "enquiry@forzaauto.sg" <enquiry@forzaauto.sg>

Dear Mike,

After revise above vehicle finalize \$5900 (L/S, before GST). 6 repair days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: enquiry@forzaauto.sg [<mailto:enquiry@forzaauto.sg>]
Sent: Thursday, October 03, 2019 11:12 AM
To: Steve Chen (LKK Auto)
Subject: RE: SJU5914B, Estimate for vehicle SJU5914B]

Dear Steve,

Thanks for the prompt reply

As refer to your return marking,

We hope you could revise on the claim for the below item

1) Rear Bumper reflector



FORZA AUTOHAUS PTE LTD

COMPANY REG NO.: 201833193C

39 Woodlands Close, #01-34/35, Mega @ Woodlands,
Singapore 737856

+65 6278 1889 enquiry@forzaauto.sg

ESTIMATE

QIFEI AUTO PTE LTD
1 TAMPINES NORTH DRIVE 1 #07-20, T-SPACE
Singapore 528559

Contact: 83337446

Code: C100022

Date in: 27/05/2019

Vehicle Num: SJU59148

Model: TOYOTA WISH 1.6X A

Chassis/Eng#: ZGE200028155/2ZR0481342

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
REAR BUMPER / BR	1	451.90	451.90 /
REAR BUMPER CORNER RETAINER L/R / BR	2	171.85 92	343.70 180 /
REAR BUMPER IMPACT BRACKET L/R X NM	2	182.30	364.60 X
REAR BUMPER REFLECTOR L/R (LH) / OR	1	178.85	357.70 49.70 /
REAR BUMPER SIDE RETAINER L/R X NM	2	172.45	344.90 X
REAR END PANEL / OO	1	581.90	581.90 /
REAR END PANEL INNER TOP GARNISH / CR4	1	371.85	371.85 204.60 /
REAR END PANEL INNER TOP GARNISH CLIPS / MC	1 set	12.00 10	51.60 10 /
REAR FENDER INNER SHIELD L/R X NM	2	231.35	462.70 X
REAR FENDER INNER TRIMBOARD L/R X NM	2	751.85	1,503.70 X
REAR SUB-CHASSIS FRAME L/R X NM	2	581.90	1,163.80 X
REAR TAILGATE / OO	1	1217.85	1,217.85 /
REAR TAILGATE 'LOGO' EMBLEM / MC	1	61.10	61.10 /
REAR TAILGATE 'VALVE Matic' EMBLEM / MC	1	171.25	171.25 90.50
REAR TAILGATE DAMPER L/R X NM	2	371.45	742.90 X
REAR TAILGATE HINGE L/R X NM	2	178.85	357.70 X
REAR TAILGATE INNER HANDLE X NM	1	178.85	178.85 X



FORZA AUTOHAUS PTE LTD

COMPANY REG NO.: 20183212C

39 Woodlands Close, #01-34/35, Mega @ Woodlands,
Singapore 737856

+65 6278 1889 enquiry@forzaauto.sg

REAR TAILGATE INNER TRIMBOARD / CRU	1	731.35	731.35 680/
REAR TAILGATE MECHANISM LOCK / BT	1	581.90	581.90 530/
REAR TAILGATE MECHANISM LOCK STRIKER X NMI	1	43.70	43.70 X
REAR TAILGATE No.PLATE LAMP CHROME GARNISH / BR	1	281.90	281.90 /
REAR TAILGATE No.PLATE LAMP CHROME GARNISH STAY CLIPS / RS 1 set	1	12.90 10	49.60 11/
REAR TAILGATE No.PLATE LAMP L/R X NMI	2	274.45	548.90 X
REAR TAILGATE OUTER HANDLE X NMI	1	174.45	174.45 X
REAR TAILGATE REFLECTOR LAMP L/R / BR	2	274.45	548.90 /
REAR TAILGATE RUBBER GUIDE STOPPER X NMI	4	43.70	174.80 X
REAR TAILGATE RUBBER WEATHER STRIP / CRU	1	174.45	174.45 /
REAR TAILGATE WINDSCREEN GLASS / BR	1	971.45	971.45 /
REAR TAILGATE WINDSCREEN GLASS RUBBER MOULDING / RC	1	181.90	181.90 /
REAR TAILGATE WIPER ARM X NMI	1	174.45	174.45 X
REAR TAILGATE WIPER ARM BLADE X NMI	1	181.90	181.90 X
REAR TAILGATE WIPER MOTOR X NMI	1	561.60	561.60 X
REAR TAILLAMP L/R (LH) BR /	21	371.85	743.70 371.85/
REAR TAILLAMP STAY CLIPS X NMI	4	12.90	51.60 X
REAR TRUNK PANEL X NMI	1	972.45	972.45 X
REAR TRUNK PANEL TOP COVER WITH CARPET X NMI	1	531.40	531.40 X
REAR TRUNK PANEL TOP COVER BASE GARNISH X NMI	1	181.90	181.90 X

page 2

6598
-25%
4948.50



FORZA AUTOHAUS PTE LTD

COMPANY REG NO.: 20183292C

39 Woodlands Close, #01-34/35, Mega @ Woodlands,
Singapore 737856

+65 6278 1889 enquiry@forzaauto.sg

		Subtotal before discount	16,590.30	
Percentage discount 25%			4,147.58	
		Sub-total 1	12,442.73	
REAR BUMPER CLIPS SET	MC	1	350.00	350.00 30/
REAR FENDER INNER TRIMBOARD CLIPS SET L/R	X NI	2	30.00	60.00 X
REAR TAILGATE REVERSE CAMERA	X NI	1	350.00	350.00 X
REAR TAILGATE INNER TRIMBOARD CLIPS SET	/ MC	1	30.00	30.00 20/
REAR TAILGATE No.PLATE	/ CMT	1	25.00	25.00
REAR TAILGATE No.PLATE GARNISH	/ CMT	2	50.00	100.00 20/
REAR TAILGATE WINDSCREEN GLASS SEALANT	/ MC	1	80.00	80.00 40/
REAR TAILGATE WINDSCREEN SOLAR FILM	/ MC	1	150.00	150.00
REAR TRUNK PANEL INSULATOR MAT	X NI	1	350.00	350.00
		Subtotal before discount	1,495.00	
Percentage discount 0%			0.00	
		Sub-total 2	1,495.00	283
		Parts-total	13,937.73	285

LABOUR

Description	Price
TO PROVIDE TOWING CHARGE	50.00 (Invoice) /
TO DIAGNOSE,REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	100.00 X
TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING.(TO FR)	60.00 30/
TO REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	80.00 30/
TO REMOVE,CHANGE REAR TAILGATE WINDSCREEN.	200.00 120/



FORZA AUTOHAUS PTE LTD

COMPANY REG NO.: 30183292C

39 Woodlands Close, #01-34/35, Mega @ Woodlands,
Singapore 737856

+65 6278 1889 enquiry@forzaauto.sg

TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM
GARNISH, TRIM LINER CARPET (TO FR)

80.00

TO TRANSFER TAILGATE/BOOTLID MECHANISM AND WIRING ASSY (TO FR)

100.00

TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND
WHERE CONSISTENT TO THE ACCIDENT

1,200.00

TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN
WHERE NECESSARY CONSISTENT TO THE ACCIDENT

80.00

TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED
BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND
DAMAGED CONSISTENT TO THE ACCIDENT

1,250.00

TO DISMANTLE, REPAIR AND RE-ALIGN REAR WIPER LINKAGE AND MOTOR
ASSY TO PROPER FUNCTIONING

150.00

TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL

120.00

TO SET ON CHASSIS BENCH, ADJUST, ALIGN REAR CHASSIS ALIGNMENT BACK
INTO ITS ORIGINAL SPECIFICATIONS

250.00

Labour Total

3,720.00

Parts & Labour Total

17,657.73

page 4

Steve (LKK) wil Arindree
8322 8813 29/5/19
L/S
Ruj AL spy
6 days

P-4948.50
N-285
L-2110
7343.50
L/S-5874.80
=5900

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019		28 May 2019 17:24 Edit Adj Rpt	\$55,900.00 Edit Estimates	\$55,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ONE PARTY STORE , Co. Reg. No.: 53218136X								
Main Claimant:	QIFEI AUTO TPE LTD , Co. Reg. No.: 201832768E								
Vehicle Reg. No.:	SJU5914B	Date of Loss:	25/05/2019 12:00 - :59 [113 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202370C02	Policy/Cover Note No.:	DMCVSN30062619000 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBH1502X	Policy No. (Claimant):	2018-V0105874						
		Excess:	\$50.00						
Repairer:	Forza Autohaus Pte Ltd (HQ) No.39 Woodlands Close, #01-34/35, Mega@Woodlands, 737856 Woodlands - Tel: 6278 1889								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 14/02/2020]								
Driver/Custodian (Insured):	MUHAMMAD ISKANDAR BIN ZAKARYA (25 / Male) , NRIC: S9411010F Email:								
Adj Asg. Remarks:	please assign Mr Chua Wei Jie for SJE. thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (12/02/2020): Report Send Back Alerts - SJU5914B (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU5914B (SNM19D202370C02)
[GBH1502X]
TP
QIFEI AUTO TPE LTD
May 25 2019 12:00PM
[ONE PARTY STORE]
Forza Autohaus Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	27/05/19 17:37	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 18:11	General View	 Load JPG	☒
2	29/05/19 18:11	General View	 Load JPG	☒
3	29/05/19 18:11	General View	 Load JPG	☒
4	29/05/19 18:11	General View	 Load JPG	☒
5	29/05/19 18:11	Odometer Reading	 Load JPG	☒
6	29/05/19 18:11	General View	 Load JPG	☒
7	29/05/19 18:11	Chassis Number	 Load JPG	☒
8	29/05/19 18:11	General View	 Load JPG	☒
9	29/05/19 18:11	General View	 Load JPG	☒
10	29/05/19 18:11	General View	 Load JPG	☒
11	29/05/19 18:11	General View	 Load JPG	☒
12	29/05/19 18:11	General View	 Load JPG	☒
13	29/05/19 18:11	General View	 Load JPG	☒
14	29/05/19 18:11	General View	 Load JPG	☒
15	29/05/19 18:11	General View	 Load JPG	☒
16	29/05/19 18:11	General View	 Load JPG	☒
17	29/05/19 18:11	General View	 Load JPG	☒
18	29/05/19 18:11	General View	 Load JPG	☒
19	29/05/19 18:11	General View	 Load JPG	☒
20	29/05/19 18:11	General View	 Load JPG	☒
21	29/05/19 18:11	General View	 Load JPG	☒
22	29/05/19 18:11	General View	 Load JPG	☒
23	29/05/19 18:11	General View	 Load JPG	☒
24	29/05/19 18:11	General View	 Load JPG	☒
25	29/05/19 18:11	General View	 Load JPG	☒
26	29/05/19 18:11	General View	 Load JPG	☒
27	29/05/19 18:11	General View	 Load JPG	☒
28	29/05/19 18:11	General View	 Load JPG	☒
29	29/05/19 18:11	General View	 Load JPG	☒
30	29/05/19 18:11	General View	 Load JPG	☒
31	29/05/19 18:11	General View	 Load JPG	☒
32	29/05/19 18:11	General View	 Load JPG	☒
33	29/05/19 18:11	General View	 Load JPG	☒
34	29/05/19 18:12	General View	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
				☒
35	29/05/19 18:12	General View	 Load JPG	☒
36	29/05/19 18:12	General View	 Load JPG	☒
37	29/05/19 18:12	General View	 Load JPG	☒
38	29/05/19 18:12	General View	 Load JPG	☒
39	29/05/19 18:12	General View	 Load JPG	☒
40	29/05/19 18:12	General View	 Load JPG	☒
41	29/05/19 18:12	General View	 Load JPG	☒
42	29/05/19 18:12	General View	 Load JPG	☒
43	29/05/19 18:12	General View	 Load JPG	☒
44	29/05/19 18:12	General View	 Load JPG	☒
45	29/05/19 18:12	General View	 Load JPG	☒
46	29/05/19 18:12	General View	 Load JPG	☒
47	29/05/19 18:12	General View	 Load JPG	☒
48	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
49	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
50	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
51	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
52	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
53	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
54	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
55	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
56	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
57	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
58	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
59	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
60	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
61	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
62	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
63	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
64	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
65	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
66	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
67	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
68	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
69	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
70	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
71	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
72	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
73	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
74	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
75	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
76	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
77	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
78	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
79	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
80	03/06/19 08:36	Photographs of Damaged Items	Load JPG	☒
81	03/06/19 08:36	Photographs of Damaged Items	Load JPG	☒
82	03/06/19 08:36	Photographs of Damaged Items	Load JPG	☒
83	03/06/19 08:36	Photographs of Damaged Items	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
84	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
85	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
86	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
87	03/06/19 08:36	Photographs of Damaged Items	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/05/19 17:25	PRI	 Load PDF	
2	28/05/19 17:25	INSD GBH1502X GIA REPORT	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/02/20 12:22	PRS Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	04/09/19 01:11	Accident Statement	 Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	27/05/19 17:32	Accident Photo	 Load JPG	☒
2	27/05/19 17:32	Accident Photo	 Load JPG	☒
3	27/05/19 17:32	Accident Photo	 Load JPG	☒
4	27/05/19 17:32	Accident Photo	 Load JPG	☒
5	27/05/19 17:32	Accident Photo	 Load JPG	☒
6	27/05/19 17:32	Accident Photo	 Load JPG	☒
7	27/05/19 17:32	Accident Photo	 Load JPG	☒
8	27/05/19 17:32	Accident Photo	 Load JPG	☒
9	27/05/19 17:32	Accident Photo	 Load JPG	☒
10	27/05/19 17:32	Accident Photo	 Load JPG	☒
11	27/05/19 17:32	Accident Photo	 Load JPG	☒
12	27/05/19 17:32	Accident Photo	 Load JPG	☒
13	27/05/19 17:32	Accident Photo	 Load JPG	☒
14	27/05/19 17:32	Accident Photo	 Load JPG	☒
15	27/05/19 17:32	Accident Photo	 Load JPG	☒
16	27/05/19 17:32	Accident Photo	 Load JPG	☒
17	27/05/19 17:32	Accident Photo	 Load JPG	☒
18	27/05/19 17:32	Accident Photo	 Load JPG	☒
19	27/05/19 17:32	Accident Photo	 Load JPG	☒
20	27/05/19 17:32	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	27/05/19 16:12	Accident Sketch Plan	 Load TIF	
2	27/05/19 16:12	Accident Sketch Plan	 Load TIF	
3	27/05/19 16:12	police report	 Load TIF	
4	27/05/19 16:12	police report	 Load TIF	
5	27/05/19 16:12	nric & dl	 Load TIF	
6	27/05/19 16:12	nric & dl	 Load TIF	
7	27/05/19 16:12	ci	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT19009448/EYD3E2-1

Date: 13/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30062619000

Claimant Vehicle
No: SJU5914BInsured Vehicle
No: GBH1502X

Date of Loss: 25/05/2019

Nature of Claim: TP

Claim
No: SNM19D202370C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU5914B

Make & Model: TOYOTA WISH, 1.8 X (A)

Engine No: 2ZR0481342

Reg. Date: 16/12/2009 (Man. Year: 2009)

Chassis No: ZGE200028155

Colour: Grey

Odometer: 156902 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,937.72	5,233.50	8,704.22	62.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,720.00	2,110.00	1,610.00	43.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,657.72	7,343.50	10,314.22	58.41
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	17,657.72	5,900.00	11,757.72	66.59

INSPECTION

Date of Assignment: 28/05/2019

Date Inspected: 29/05/2019 Inspected At:

Forza Autohaus Pte Ltd (HQ)
No.39 Woodlands Close, #01-34/35,
Mega@Woodlands
Singapore 737856

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2020)	
Parts: M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SJU5914B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	451.90 FL	*451.90 FL
2	2		*REAR BUMPER CORNER RETAINER L/R	Broken	343.70 FL	*180.00 FL
3	2		*REAR BUMPER IMPACT BRACKET L/R	Not Necessary	364.60 FL	*- FL
4	1		*REAR BUMPER REFLECTOR L/R	N/S Broken	357.70 FL	*49.70 FL
5	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	344.90 FL	*- FL
6	1		*REAR END PANEL	Dented	581.90 FL	*581.90 FL
7	1		*REAR END PANEL INNER TOP GARNISH	Crushed	371.85 FL	*204.60 FL
8	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	51.60 FL	*10.00 FL
9	2		*REAR FENDER INNER SHIELD L/R	Not Necessary	462.70 FL	*- FL
10	2		*REAR FENDER INNER TRIMBOARD L/R	Not Necessary	1,503.70 FL	*- FL
11	2		*REAR SUB-CHASIS FRAME L/R	Not Necessary	1,163.80 FL	*- FL
12	1		*REAR TAILGATE	Dented	1,217.85 FL	*1,217.85 FL
13	1		*REAR TAILGATE LOGO EMBLEM	Necessary	61.10 FL	*61.10 FL
14	1		*REAR TAILGATE VALVE MATIC EMBLEM	Necessary	171.25 FL	*90.50 FL
15	2		*REAR TAILGATE DAMPER L/R	Not Necessary	742.90 FL	*- FL
16	2		*REAR TAILGATE HINGE L/R	Not Necessary	357.70 FL	*- FL
17	1		*REAR TAILGATE INNER HANDLE	Not Necessary	178.85 FL	*- FL
18	1		*REAR TAILGATE INNER TRIMBOARD	Crushed	731.35 FL	*680.00 FL
19	1		*REAR TAILGATE MECHANISM LOCK	Bent	581.90 FL	*530.00 FL
20	1		*REAR TAILGATE MECHANISM LOCK STRIKER	Not Necessary	43.70 FL	*- FL
21	1		*REAR TAILGATE NO. PLATE LAMP CHROME GARNISH	Broken	281.90 FL	*281.90 FL
22	1		*SET REAR TAILGATE NO. PLATE LAMP CHROME GARNISH STAY CLIPS	Necessary	49.60 FL	*10.00 FL
23	2		*REAR TAILGATE NO. PLATE LAMP L/R	Not Necessary	548.90 FL	*- FL
24	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	174.45 FL	*- FL
25	2		*REAR TAILGATE REFLECTOR LAMP L/R	Broken	548.90 FL	*548.90 FL
26	4		*REAR TAILGATE RUBBER GUIDE STOPPER	Not Necessary	174.80 FL	*- FL
27	1		*REAR TAILGATE RUBBER WEATHER STRIP	Crushed	174.45 FL	*174.45 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR TAILGATE WINDSCREEN GLASS	Broken	971.45 FL	*971.45 FL
29	1		*REAR TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	181.90 FL	*181.90 FL
30	1		*REAR TAILGATE WIPER ARM	Not Necessary	174.45 FL	*- FL
31	1		*REAR TAILGATE WIPER ARM BLADE	Not Necessary	181.90 FL	*- FL
32	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	561.60 FL	*- FL
33	1		*REAR TAILLAMP L/R	N/S Broken	743.70 FL	*371.85 FL
34	4		*REAR TAILLAMP STAY CLIPS	Not Necessary	51.60 FL	*- FL
35	1		*REAR TRUNK PANEL	Not Necessary	972.45 FL	*- FL
36	1		*REAR TRUNK PANEL TOP COVER WITH CARPET	Not Necessary	531.40 FL	*- FL
37	1		*REAR TRUNK PANEL TOP COVER BASE GARNISH	Not Necessary	181.90 FL	*- FL
38	1		*SET REAR BUMPER CLIPS	Necessary	350.00 FS	*30.00 FS
39	2		*SET REAR FENDER INNER TRIMBOARD CLIPS L/R	Not Necessary	60.00 FS	*- FS
40	1		*REAR TAILGATE REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
41	1		*SET REAR TAILGATE INNER TRIMBOARD CLIPS	Necessary	30.00 FS	*20.00 FS
42	1		*REAR TAILGATE NO PLATE	Cut	25.00 FS	*25.00 FS
43	2		*REAR TAILGATE NO. PLATE GARNISH	Cut	100.00 FS	*20.00 FS
44	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
45	1		*REAR TAILGATE WINDSCREEN SOLAR FILM	Necessary	150.00 FS	*150.00 FS
46	1		*REAR TRUNK PANEL INSULATOR MAT	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	18,085.30	6,883.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,147.58	1,649.50
Total Parts (\$\$)	13,937.72	5,233.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING CHARGE	New	50.00	50.00
2	TO DIAGNOSE, REPLACE AND / OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	100.00	0.00
3	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR)	New	60.00	30.00
4	TO REFIX / RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	New	80.00	30.00
5	TO REMOVE, CHANGE REAR TAILGATE WINDSCREEN	New	200.00	120.00
6	TO TRANSFER TAILGATE / BOOTLID MECHANISM AND WIRING ASSY (TO FR)	New	100.00	50.00
7	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
8	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	80.00	0.00
9	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,250.00	900.00
10	TO DISMANTLE, REPAIR AND RE-ALIGN REAR WIPER LINKAGE AND MOTOR ASSY TO PROPER FUNCTIONING	New	150.00	0.00
11	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	50.00
12	TO SET ON CHASSIS BENCH, ADJUST, ALIGN REAR CHASSIS ALIGNMENT BACK INTO ITS ORIGINAL SPECIFICATIONS	New	250.00	0.00
13	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	80.00	80.00
Gross Labour Cost (S\$)			3,720.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >