

DATE/TIME

ASS. REC. BY:

REF:

eslctt20000735/Gyd3n

Special Instruction:

Surveyor: AWO (Tan)

ASSIGNMENT (Office)

From (Person): Ben Tan

of

CTI

Date/Time:

13/01/2020 @ 11:13am

Estimated Cost:

Bill to:

Mein

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 4737Z

Insured:

SGM 86 56 D

at Workshop m/s

Indeco

Tel:

0382 2736

of

39 Defu Lane 12

Policy No:

Claim No:

SNM19D206177/SGM 8656D/BEN

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:20am @ 13/01/2020

Person Contacted:

Mr. Tan

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>13/01/2020</u> ✓
	<u>SLV 4737Z - X</u>
	<u>SGM 8656D - X</u>

ASSIGNMENT

From: 6/2 Date: 21

Estimated Cost: 735/67

OD ☒ TR / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: Indeco Engineering

at Workshop m/s Indeco Engineering

of Indeco Engineering

Insured: Indeco Engineering

Policy No. Indeco Engineering

Claims No. Indeco Engineering


Sum Insured: Indeco Engineering Excess: Indeco Engineering

(Client's Record)

Make of Veh: Indeco Engineering

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: Indeco Engineering

IDAC Accident Rpt: Indeco Engineering Consistent? : Yes or No

GIA / PR Seen: Indeco Engineering Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: Indeco Engineering % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Indeco Engineering Person Contacted: Indeco Engineering

Vehicle: IN / OUT

Veh No: SLV 47378 Regn: 21 Dec 2017

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Blue car C.C. Indeco Engineering

Colour: white A/C: Indeco Engineering Insured / Std / NI / NA

Sp Reading: Indeco Engineering T/Radio: Indeco Engineering Insured / Std / NI / NA

Eng/No: Indeco Engineering

C/No: VL 4BC EB 4R HT 003155

Gen. Cond: Indeco Engineering Good / Fair / Poor / Burnt

Steering: Indeco Engineering In order / Jammed / Leaked / Burnt or

Brake: Indeco Engineering In order / Jammed / Leaked / Burnt or

Modi: Indeco Engineering Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65 R15

R: Indeco Engineering

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A. Indeco Engineering

D.O.I. 13-01-20

Survey held at w/s

2:30pm

Des. of Damages: Indeco Engineering Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/3	Finalized \$1323 with Tan (Red \$716.00, 36%)

RECEIVED 10 MAR 2020

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

10/3/20 Typist

Days Of Repair: 2

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Final (\$

Survey Fee:

Transportation:

3 x \$5.00

Phone

Other

Other

Other

Other

270

270

Report Email

Long Com / M/s

PIP \$1323

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Monday, 13 January 2020 11:13 AM
To: 'assignments@lkkauto.com'
Subject: FW: OUR REF: SNM19D206177/SGM8656D/BEN - FW: SLV4737Z - TP Claims against SGM8656D (CNTP) DOA 29/12/2019

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SLV4737Z.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Sent: Monday, January 13, 2020 11:01 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>; Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Goh Chee Khoo <ckgoh@sg.indeco.cwtlimited.com>
Subject: RE: OUR REF: SNM19D206177/SGM8656D/BEN - FW: SLV4737Z - TP Claims against SGM8656D (CNTP) DOA 29/12/2019

Hi Ben,

Please appoint any of the surveyors from your list

Warmest Regards

Tan Cheng Huat
Technical Officer
INDECO ENGINEERS PTE LTD
(A member of the CWT Group)

DID +65 63822736 | Fax +65 63822817 | www.indeco.cwtlimited.com

CONFIDENTIALITY NOTICE: This communication is meant only for the addressee(s) named above and may contain information, which is confidential and/or legally privileged. If you are not the named addressee(s), or the agent responsible for receiving and delivering this communication to the named addressee(s), this communication has been sent to you in error. If so, kindly contact us immediately for retrieval purposes. Unauthorized dissemination, distribution, copying or reliance on this communication is prohibited and may attract criminal penalties. Thank you.

From: Ben Tang [<mailto:Ben.Tang@sg.cntaiping.com>]
Sent: Monday, 13 January, 2020 10:07 AM
To: Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>; Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Goh Chee Khoo <ckgoh@sg.indeco.cwtlimited.com>
Subject: RE: OUR REF: SNM19D206177/SGM8656D/BEN - FW: SLV4737Z - TP Claims against SGM8656D (CNTP) DOA 29/12/2019

Hi Mr Tan

We refer to your email below.

Please confirm if you are agreeable to our list of surveyors and confirm which one of the motor surveyor as the SJE for the pre repair survey.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Sent: Monday, January 13, 2020 8:52 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>; Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Goh Chee Khoo <ckgoh@sg.indeco.cwtlimited.com>
Subject: RE: OUR REF: SNM19D206177/SGM8656D/BEN - FW: SLV4737Z - TP Claims against SGM8656D (CNTP) DOA 29/12/2019

Hi Ben,

Abovementioned vehicle is still waiting for your surveyor to conduct the survey.

Please arrange as soon as possible.

Thank you.

Warmest Regards

Tan Cheng Huat
Technical Officer
INDECO ENGINEERS PTE LTD
(A member of the CWT Group)

DID +65 63822736

Fax +65 63822817

www.indeco.cwtlimited.com

CONFIDENTIALITY NOTICE: This communication is meant only for the addressee(s) named above and may contain information, which is confidential and/or legally privileged. If you are not the named addressee(s), or the agent responsible for receiving and delivering this communication to the named addressee(s), this communication has been sent to you in error. If so, kindly contact us immediately for retrieval purposes. Unauthorized dissemination, distribution, copying or reliance on this communication is prohibited and may attract criminal penalties. Thank you.

From: Tan Cheng Huat
Sent: Wednesday, 8 January, 2020 4:08 PM
To: 'Ben Tang' <Ben.Tang@sg.entaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.entaiping.com>; Chee So Chow <sochow.chee@sg.entaiping.com>
Subject: RE: OUR REF: SNM19D206177/SGM8656D/BEN - FW: SLV4737Z - TP Claims against SGM8656D (CNTP) DOA 29/12/2019

Hi Ben,

Please proceed with the appointment of surveyor.

Thank you.

Warmest Regards

Tan Cheng Huat
Technical Officer
INDECO ENGINEERS PTE LTD
(A member of the CWT Group)

DID +65 63822736

Fax +65 63822817

www.indeco.cwtlimited.com

CONFIDENTIALITY NOTICE: This communication is meant only for the addressee(s) named above and may contain information, which is confidential and/or legally privileged. If you are not the named addressee(s), or the agent responsible for receiving and delivering this communication to the named addressee(s), this communication has been sent to you in error. If so, kindly contact us immediately for retrieval purposes. Unauthorized dissemination, distribution, copying or reliance on this communication is prohibited and may attract criminal penalties. Thank you.

From: Ben Tang [<mailto:Ben.Tang@sg.entaiping.com>]
Sent: Wednesday, 8 January, 2020 3:47 PM
To: Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Cc: Claims Dept of CTI <claimsdept@sg.entaiping.com>; Chee So Chow <sochow.chee@sg.entaiping.com>
Subject: RE: OUR REF: SNM19D206177/SGM8656D/BEN - FW: SLV4737Z - TP Claims against SGM8656D (CNTP) DOA 29/12/2019

WITHOUT PREJUDICE

Dear Sir,

We refer to your email dated 08 January 2020.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, January 8, 2020 3:36 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; tanch@sg.indeco.cwtlimited.com
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OUR REF: SNM19D206177/SGM8656D/BEN - FW: SLV4737Z - TP Claims against SGM8656D (CNTP) DOA 29/12/2019

Dear Ben,

Please conduct PRS for SLV4737Z.

Note : officer in charge – Ben tang 63896175.

***Kindly quote our reference number when replying.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tan Cheng Huat [<mailto:tanch@sg.indeco.cwtlimited.com>]

Sent: Wednesday, January 08, 2020 2:42 PM

To: Claims Dept of CTI

Cc: Lai Bee Yin; Seah Wan Er; Goh Chee Khoo

Subject: SLV4737Z - TP Claims against SGM8656D (CNTP) DOA 29/12/2019

Hi Officer-In-Charge,

We are submitting the repair quotation for repair of accident damages for vehicle No. SLV4737Z on behalf of our client/policy holder, BLUECAR EAST ASIA PTE LTD . The accident damages were caused by your insured's vehicle No. SGM8656D .

Please refer to attachments on the Repair quotation and GIA report with photos.

Appreciate your arrangement for survey of the abovementioned vehicle as soon as possible and let us know in advance the date of survey.

Vehicle is currently parked at our workshop at the following address:

Indeco Engineers Pte Ltd

No. 39, Defu Lane 12,

Singapore 539139

Thank you

Warmest Regards

Tan Cheng Huat
Technical Officer

INDECO ENGINEERS PTE LTD

(A member of the CWT Group)

DID +65 63822736

Fax +65 63822817

www.indeco.cwtlimited.com

CONFIDENTIALITY NOTICE: This communication is meant only for the addressee(s) named above and may contain information, which is confidential and/or legally privileged. If you are not the named addressee(s), or the agent responsible for receiving and delivering this communication to the named addressee(s), this communication has been sent to you in error. If so, kindly contact us immediately for retrieval purposes. Unauthorized dissemination, distribution, copying or reliance on this communication is prohibited and may attract criminal penalties. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/01/2020 18:39
Date Of Accident	29/12/2019 16:05
Exact Location Of Accident	LN 3 TPE (TPE/SLE TWDS PONGGOL NEAR LAMP POST 615)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV4737Z
Insured/Policyholder	
Name Of Registered Owner	BLUECAR EAST ASIA PTE LTD
Co Reg No	2XXXXX259H
Email Address	CLAIMS@BLUESG.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-31637900

Vehicle Particulars

Manufacturer	BLUECAR
Model	BLUECAR-(A)
Exact Purpose for which vehicle was being used at time of accident	CAR RENTAL BY OWNER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MSD/VPCP/18-000001
Cover Note Number	

Driver

Name of Driver	KWOK WEI ZHANG TIMOTHY
NRIC No	SXXXX001E
Date Of Birth	17/06/1995
Occupation	INDOOR
Date Of Driving Pass	13/02/2014
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92317180
Fax Number	
Contact Number	
EMail Address	TIMOTHYKWOK95@GMAIL.COM

Address	BLK 699B HOUGANG STREET 52 #06-51 SINGAPORE 532699
Postcode	532699
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : WILLIE NG GENDER: : MALE
Passenger 2	NAME: : BEVERLY NG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 29/12/2019 at about 1605hrs, I was driving a BlueSG vehicle bearing, SLV4737Z, on the third lane along TPE/SLE towards Ponggol. As I was driving near to Lamp Post 615, there was one vehicle at the front driving very slowly and eventually, the vehicle braked abruptly. I was able to react on time and brake my vehicle. As soon as I came to a stop, there was an impact to the rear of my vehicle. Upon further checks, the plate number of the said vehicle was SGM8656D. There was no one injured at that point of time. Due to the accident, the rear of my vehicle was damaged. As for the other vehicle, the front bonnet & bumper was dented.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGM8656D
-----------------------------	----------

Vehicle Make/Model/Colour	NISSAN / LATIO / LIGHT BLUE
Details Of Properties	FRONT BUMPER AND BONNET DENTED
Vehicle Category	PRIVATE CAR
Name of Driver	KOH KEE YEOW
NRIC/Passport Number	SXXXX878A
Contact Number	96260413
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 30/12/19


1513 HRS -

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/12/2019 at about 1605hrs, I was driving a Blazer vehicle bearing, SLV 4737Z, on the third lane along TPE/SE towards Pongol. As I was driving near to Lamp Post 615, there was one vehicle at the front driving very slowly and eventually, the vehicle halted abruptly. I was able to react on time and brake my vehicle. As soon as I came to a stop, there was an impact to the rear of my vehicle. Upon further checks, the ~~car~~ plate number of the said vehicle was SGM 8656D.

There was no one injured at that point of time.

Due to the accident, the rear of my vehicle was damaged. As for the other vehicle, the front bumper & bumper was dented.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

GIAMC SketchPlanForm_V5

Driver's Signature
(If driver is not the policyholder)
Date & Time: 30/12/19

1513 Hrs.

Reporting Centre Personnel's Signature
Name:
NRIC/PPN No.:



Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999



T/20191229/2080

1 of 3

Report No. T/20191229/2080

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/12/2019 17:32		Vide Report No.:		Station Diary No.: 113	
Informant's Particulars					
Name of Informant: KWOK WEI ZHANG TIMOTHY		Address: APT BLK 699B HOUGANG STREET 52 #05-51 SINGAPORE 532699			
ID Type / ID No.: NRIC NO / S9521001E		Contact No.:		Mobile: 92317180	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 24	Date of Birth: 17/06/1995	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: SAF		Driving Licence Information: Class: 2B,3		Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Driver: No	Date/Time of Accident: 29/12/2019 18:05	Type of Location: Straight Road
Location: Along Road 1 TAMPINES EXPRESSWAY TPE/SLE TOWARDS PUNGGOL				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGM8856D	Car				Slightly Damaged	0
SLV4737Z	Car				Slightly Damaged	2

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



T/20191229/2080

2 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20191229/2080

CONTINUATION OF REPORT

Driver			
Name	KOH KEE YEOW	ID No.	S0188875A
Related Vehicle	SGM8656D (Car)	Contact No.	96280413
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	KWOK WEI ZHANG TIMOTHY	ID No.	S9521001E
Related Vehicle	SLV4737Z (Car)	Contact No.	92317180
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 29/12/2019 at about 1606hrs, I was driving a BlueSG vehicle bearing, SLV4737Z, on the third lane along TPE/SLE towards Punggol. As I was driving near to Lamp post 515, there was one vehicle at the front was driving very slowly and eventually the vehicle braked abruptly. I was able to react on time and brake my vehicle. As soon as I came to a stop, there was an impact on the rear of my vehicle. Upon further checks, the plate number of the said vehicle was SGM8656D.

There was no one injured at that point of time. There was no police or ambulance at scene.

Due to the accident, the rear of my vehicle was damaged. As for the other vehicle, his front plate number was damage and came off and his front portion of the vehicle was dented.

I am lodging this report for insurance purpose.

Police Report



SINGAPORE
POLICE FORCE



T/20191229/2080

Police Station Of Origin:
Hougang N.P.C.
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3

Report No. T/20191229/2080

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 3 PHUA JIA JUN, MARK

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No: 65476151

SN 001

Authentication Stamp
MP168



Signature

Singapore Police Force

Signature Of Informant:

Date/Time:
29/12/2019 17:32

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	259H
Vehicle No.:	SLV4737Z
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jan 2020
Vehicle Make:	BLUECAR
Vehicle Model:	BLUECAR
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	-
Chassis No.:	VL4BCEB4RHT003155
Maximum Power Output:	50.0 kW (67 bhp)
Open Market Value:	\$33,888.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$9,444.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2027
PARF Rebate Amount:	\$7,083.00
COE Expiry Date:	28 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
PQP Paid:	\$42,698.00
COE Rebate Amount:	\$33,974.00
Total Rebate Amount:	\$41,057.00

The information contained herein is correct as at 13 Jan 2020

OK

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SLV4737Z

Type of Claim : TPVehicle No. : SLV4737ZMake & Model : BLUECARYear of Manufacture : 2017Chassis No. : VL4BCEB4RHT003155Ins Company : CHINA TAIPING
INSURANCE (SINGAPORE)

PTE LTD

Engine No. : 921955T17W442206846Excess : Policy No. : Date of Accident : 29.12.2019Time of Accident : 16:05Suggested Days of Repair : Case Owner : BLUECAR EAST ASIA

PTE LTD

Repair EstimatesParts (a) Cost / List Price Items \$ 920.00Plus/Less 20.0% 15 \$ 184.00Total of Cost / List \$ 1,104.00(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 45.00Total Parts Cost (Appendix A) \$ 1,149.00Labour (Appendix B) \$ 950.00Total Repair Cost \$ 2,099.00

The above total will be subjected to 7% G.S.T.

TP Vehicle No. SGM8656D

- TP Auto Consultants hence notify the Repairer of the following:
- To resurvey before start spray painting
 - To display damaged part(s) during resurvey
 - Paint prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 2 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ (e) Signature of surveyor : Date:



VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

ESTIMATED REPAIR COST DETAILS

Vehicle No	: <u>SLV4737Z</u>	Case Owner	: <u>BLUECAR EAST ASIA</u> <u>PTE LTD</u>
Make & Model	: <u>BLUECAR</u>	Year Manufacture	: <u>2017</u>
Chassis No	: <u>VL4BCEB4RHT003155</u>	Engine No	: <u>921955T17W442206846</u>
Date & Time	: _____	Supplier	: _____
Order By	: _____	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	REAR BUMPER ASSY / <i>RL</i>	1	\$ 850.00	\$ 850.00			
2	REAR BUMPER SCREW / <i>RL</i>	10	\$ 2.00	\$ 20.00			
3	REAR BUMPER REFLECTOR RH / <i>CPA</i>	1	\$ 50.00	\$ 50.00			
4	REAR NUMBER PLATE W CASING / <i>CPA</i>	1					\$ 45.00
5	0	0					
6	0	0					
7	0	0					
8	0	0					
9	0	0					
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 902.00 \$ 920.00 \$ - \$ - \$ 45.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR
EAST ASIA

Case Owner
Year of Manufacture

RTF LTD
2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO REPAIR, REPLACE REAR BUMPER, REFLECTOR, NUMBER PLATE AND AFFECTED AREA	\$400.00	200
2	TO PUTTY AND RESPRAY ON REAR BUMPER AND AFFECTED AREA	\$300.00	X 200 NA
3	TO APPLY TUFF KOTE	\$150.00	X NA
4	TO CHECK WIRING	\$100.00	R 20
5			
6			(\$20)
7			220
8			
	TOTAL	\$950.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary
















...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jan 2020		10 Mar 2020 11:49 Edit Adj Rpt	S\$1,323.00 Edit Estimates	S\$1,323.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	BLUECAR EAST ASIA PTE LTD								
Vehicle Reg. No.:	SLV4737Z	Date of Loss:	29/12/2019 16:00 - :59 [24 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D206177/SGM8656D/BEN		Policy/Cover Note No.:	DMPCSN3075701904 (Comprehensive)					
Vehicle Reg. No. (Insured):	SGM8656D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Indeco Engineers Pte Ltd - Defu (HQ) No. 39, Defu Lane 12,, S39139 Defu Lane - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/03/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV4737Z (SNM19D206177/SGM8656D/BEN)
[SGM8656D]
TP
BLUECAR EAST ASIA PTE LTD
Dec 29 2019 4:00PM
[-]
Indeco Engineers Pte Ltd - Defu

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
2	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
3	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
4	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
5	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
6	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
7	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
8	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
9	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
10	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
11	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
12	10/03/20 12:02	General View	 Load JPG	<input checked="" type="checkbox"/>
13	10/03/20 12:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
14	10/03/20 12:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
15	10/03/20 12:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT120000735/GYD3E2

Date: 16/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3075701904
Claimant Vehicle No: SLV4737Z Insured Vehicle No: SGM8656D
Date of Loss: 29/12/2019 Nature of Claim: TP Claim No: SNM19D206177/SGM8656D/BEN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV4737Z
Make & Model: BLUECAR BLUECAR, (A) Engine No: HIDDEN
Reg. Date: 29/12/2017 (Man. Year: 2017) Chassis No: VL4BCEB4RHT003155
Colour: White Odometer: 0 km
Engine Capacity: 0 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,149.00	1,103.00	46.00	4.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	220.00	730.00	76.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,099.00	1,323.00	776.00	36.97
+ GST 7.00/7.00% (S\$)	146.93	92.61	54.32	36.97
Nett Amount (S\$)	2,245.93	1,415.61	830.32	36.97

INSPECTION

Date of Assignment: 10/03/2020
Date Inspected: 13/01/2020 Inspected At: Indeco Engineers Pte Ltd - Defu (HQ)
No. 39, Defu Lane 12,
Singapore 539139
Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2020)
Parts: 144	BLUECAR BLUECAR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV4737Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY (WCP)	Deformed	850.00 F	*850.00 F
2	10		*REAR BUMPER SCREW (WCP)	Necessary	20.00 F	*20.00 F
3	1		*REAR BUMPER REFLECTOR RH (WCP)	Cracked	50.00 F	*50.00 F
4	1		*REAR NUMBER PLATE W CASING	Cracked	45.00 FS	*45.00 FS
					Sub Total (S\$)	965.00
					+ Margin on L,N Items 20.00/15.00% (S\$)	184.00
					Total Parts (S\$)	1,149.00
						1,103.00

F=Franchise part. S=SpcNetL.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR, REPLACE REAR BUMPER, REFLECTOR, NUMBER PLATE AND AFFECTED AREA	New	400.00	200.00
2	TO PUTTY AND RESPRAY ON REAR BUMPER AND AFFECTED AREA	New	300.00	0.00
3	TO APPLY TUFF KOTE	New	150.00	0.00
4	TO CHECK WIRING	New	100.00	20.00
Gross Labour Cost (S\$)			950.00	220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >