


Repairer Estimates

Page 1 of 2

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

SLH9339E

OD/ECICS

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ECICS
Policy No:	MPC19P00032000	Date of Loss:	10/01/2020
Vehicle Reg. No.:	SLH9339E	Driveable?	
Driver Age/Info:	47 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG LING LONG		
Driver:	NEO HWEE CHING		
Make/Model:	HONDA ODYSSEY, 2.4 (A)	Vehicle Reg. Date:	23/11/2016
Vehicle Colour:	PURPLE		
Engine No:	K24W1412061	Chassis No:	RC11111820
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO POLICE REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING AT WOODLANDS WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS

	Amount
Parts	4,463.80
Miscellaneous Items	40.00
Labour	2,440.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	6,943.80
+ GST 7.00% (\$\$)	486.07
Nett Amount (\$\$)	7,429.87

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Repairer Estimates

Page 2 of 2

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jan 2020)

Parts: M1-MPV HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SLH9339E/13/01/2020 10:44

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR LH DOOR	0.00	0.00	*600.00F
2	1		*1 PC REAR LH DOOR GLASS	0.00	0.00	*340.00F
3	1		*1 PC REAR LH DOOR GLASS REGULATOR	0.00	0.00	*285.00F
4	1		*1 PC REAR LH DOOR GLASS OUTER MOULDING	0.00	0.00	*58.00F
5	1		*1 PC REAR LH DOOR INNER LOCK	0.00	0.00	*380.00F
6	1		*1 PC REAR LH DOOR INNER BOARD	0.00	0.00	*420.00F
7	1		*1 PC REAR LH DOOR GLASS CHANNEL	0.00	0.00	*68.00F
8	1		*1 PC REAR LH DOOR INNER RUBBER	0.00	0.00	*85.00F
9	1		*1 PC REAR LH DOOR LOWER MOULDING	0.00	0.00	*250.00F
10	1		*1 PC REAR LH DOOR OUTER HANDLE	0.00	0.00	*55.00F
11	1		*1 PC REAR LH DOOR OUTER HANDLE NOTE	0.00	0.00	*55.00F
12	1		*1 PC REAR LH DOOR STEP GARNISH	0.00	0.00	*65.00F
13	1		*1 PC REAR LH DOOR ROLLER	0.00	0.00	*35.00F
14	1		*1 PC REAR LH FENDER	0.00	0.00	*680.00F
15	1		*1 PC REAR LH FENDER GLASS MOULDING	0.00	0.00	*52.00F
16	1		*1 PC FRT LH DOOR	0.00	0.00	*550.00F

F=Franchise part.

Sub Total (\$\$) 4,058.00

+ Margin on L,N Items 10.00% (\$\$) 405.80

Total Parts (\$\$) 4,463.80

Cheng Hoe Motor Pte Ltd/SLH9339E/13/01/2020 10:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 ROLL REAR LH FENDER GLASS GUM	40.00
Sub Total (\$\$)			40.00

Estimates on Labour

No	Particulars	Lab. Type	Amount
1	REMOVE & REFIX REAR LH FENDER GLASS	New	100.00
2	REMOVE & REFIX FRT & REAR LH DOORS, TRANSFER DOORS ATTACHMENTS, TO CUT, WELD & RENEW REAR LH FENDER, KNOCK & REPAIR LH ROCKER PANEL, LH DOOR PILLAR & REALIGN THE SAME	New	1,100.00
3	REMOVE & REFIX FRT & REAR LH DOOR GLASS	New	120.00
4	REMOVE & REFIX SEAT, CARPET, GARNISH, TOP ROOF LINING, ETC	New	120.00
5	PUTTY & RESPRAY ON FRT & REAR LH DOORS, LH PILLAR, LH ROCKER PANEL, REAR LH FENDER	New	1,000.00
Gross Labour Cost (\$\$)			2,440.00

Cheng Hoe Motor Pte Ltd/SLH9339E/13/01/2020 10:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >