

WTS Engineering Pte Ltd
 8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163
 Company Registration Number: 200505706E

Quotation

DATE: 09/01/20 LOCATION: Gul Workshop
 VEHICLE NO: PA6346T Q REF No: Q20/01/1108
 DRIVER: MA YONG LIANG DEPARTMENT: WTS Bus Department
 ATTENTION TO: ACCIDENT DATE: 08/01/20
 PREPARED BY: Chan Soo Lye REF No: JW-0120-132

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	REAR BUMPER FIBRE PART	1	1717.8	1,717.80
2	LHS REAR TAIL LAMP	1	141.6	141.60
Labour Costs				
1	TO REMOVE DAMAGED PARTS AND REPLACE REAR BUMPER FIBRE. TO REPLACE REAR LHS TAIL LAMP.	1	450	450.00
Spray Paint				
1	Spray Painting TO SPRAY PAINTING REAR BUMPER.	1	400	400.00
TOTAL:				2,709.40
Total Amount				SGD 2,709.40

Remarks:

 9/1/20
 Signature of Workshop Dpt

 9/1/20
 Signature of Department Head

 9/1/20
 Signature of Claim Department

Surveyor Sign: 

Surveyor Name: Steve CLKK

Date: 15/1/20, 10.30 am

83228813

will m/p
 L/S
 Ry AL SJ
 3 days 111

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: