



Claim No: G0065735 Date: 18/03/2020
Repairer: SME MOTOR PTE LTD

REFERENCE

Insured: BODESTYNE FRANCIS GHAZALIE Policy No: 10612261
Date of Loss: 02/01/2020 Nature of Claim: OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SKC4036A
Make & Model: KIA CERATO, 1.6 SX (A) Reg. Date: 23/08/2011
Engine No: G4FCBH360159 Chassis No: KNAFW411MB5459830

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm
Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable): Yes Engine Modification: No
Handbrake (Serviceable): Yes Steering (Serviceable): Yes Pre-accident Condition: Good

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,788.18	1,837.63	1,950.55	51.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	445.50	202.50	243.00	54.55
Paintwork Labour	464.93	370.73	94.20	20.26
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,698.61	2,410.86	2,287.75	48.69
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	4,698.61	1,950.00	2,748.61	58.50
+ GST 7.00/7.00% (S\$)	328.91	136.50	192.41	58.50
Nett Amount (S\$)	5,027.52	2,086.50	2,941.02	58.50

Submit L/s \$ 1950
7% GST
2086.50

REPAIR DETAILS

cost price

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER	Cracked <i>D.S</i>	250.00 F	*250.00 F ✓
2	1	NA	*L/FASTENING CLIP	Necessary <i>NA</i>	20.00 F	*20.00 F ✓
3	1	NA	*L/F BUMPER BRACKET	Necessary <i>Che</i>	10.00 F	*10.00 F ✓
4	1	NA	*L/F DRIVE SHAFT	Not Necessary <i>11</i>	500.00 F	*-F X
5	1	NA	*L/F SHOCK ABSORBER	Bent <i>Set</i>	120.00 F	*120.00 F ✓
6	1	NA	*L/F STEERING KNUCKLE	Warped <i>Warped</i>	160.00 F	*160.00 F ✓
7	1	NA	*L/F WHEEL BEARING	Necessary <i>NA</i>	75.00 F	*75.00 F ✓
8	1	NA	*L/F WHEELHOUSE COVER	Torn / Deformed <i>70.1</i>	50.00 F	*50.00 F ✓
9	1	NA	*L/F WING	Distorted <i>D.S</i>	165.00 F	*165.00 F ✓
10	1	NA	*L/LOWER CONTROL ARM	Bent <i>Bent</i>	150.00 F	*150.00 F ✓
11	1	NA	*LEFT HEADLAMP ASSY	Cracked <i>Che</i>	220.00 F	*220.00 F ✓
12	1	NA	*SCREW	Not Necessary <i>11</i>	20.00 F	*-F X
13	1	NA	*STEERING GEAR	Not Necessary <i>11</i>	1,200.00 F	*-F X
14	1	NA	*SUNDRY PARTS <i>clips</i>	Necessary	58.80 F	*31.13 FS <i>S.N</i>
15	1	NA	*FRONT SPORT RIM LH	Cut	250.00 F	*250.00 FS <i>S.N</i>

Supplementary #1

16	1		*FRT LH ABS WIRE	Cracked <i>Che</i>	195.00 F	*195.00 F ✓
----	---	--	------------------	--------------------	----------	-------------

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,443.80	1,696.13
+ Margin on L,N Items 10.00/10.00% (\$\$)	344.38	141.50
Total Parts (\$\$)	3,788.18	1,837.63

Aviva Ltd/SKC4036A/18/03/2020 15:29. Not valid without Reference section.

P-1415
 10%
 P-1556.50
 S.N-281.13
 L-573.23
 2410.86
 less 20%
 1928.68

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	328.50	238.50
2	Total Paint Materials	New	136.43	132.23
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	445.50	202.50
Gross Labour Cost (S\$)			910.43	573.23

328.50 + 132.23 + 202.50 = 573.23

Aviva Ltd/SKC4036A/18/03/2020 15:29. Not valid without Reference section.

< END OF REPORT >

MV 20
L1A 14684
N44 558

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

not Affiliated
all
10/1/20
L/S for
the 2nd Affiliating
S4

M/S : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITY HOUSE
Singapore 068877
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department
Your Ref No: 20/FC/TP-007(01)
Claim Type: Third Party
Accident Date: 02/01/2020
TP Veh Reg No: SHC923B

Estimate No: EST0005249
Date: 06 Jan 2020
Policy No: 10612261
Veh Reg No: SKC4036A
Make/Model: KIA CERATO
Chasis No: 0
Engine No:
Reg. Date:

Estimate Repair Cost to Vehicle No :SKC4036A

Description	Quantity	List Price	Amount
		SS	SS
List Price			
1 FRT BUMPER	1 PC	11.5 562.00	—
2 FRT BUMPER RETAINER LH	1 PC	Can 22.00	—
3 FRT BUMPER CLIPS	10 PC	rec 50.00	—
4 LH HEADLAMP	1 PC	Can 546.00	—
5 FRT LH FENDER	1 PC	2.3 464.00	—
6 FRT LH FENDER INNER COWLING	1 PC	2.1 55.00	—
7 INNER COWLING CLIPS	10 PC	rec 50.00	—
8 FRT LH SHOCK ABSORBER	1 PC	best 233.00	—
9 FRT LH LOWER ARM	1 PC	best 305.00	—
10 FRT LH LOWER ARM BALL JOINT	1 PC	17 75.00	X
11 FRT LH KNUCKLE ARM	1 PC	worped 330.00	—
12 FRT LH KNUCKLE BEARING	1 PC	rec 108.00	—
13 FRT LH DRIVE SHAFT	1 PC	11 968.00	X
14 STEERING RACK ASSY	1 PC	11 1,543.00	X
		5,311.00	
	Less 10%	531.10	4,779.90
Special Net			
15 FRT LH SPORTS RIM	1 PC	Can 250.00	✓
		250.00	250.00
Labour			
16 WIRE CHECKING	1 UNIT	30.00	20
17 REMOVE & REFIX FRT UNDERCARRIAGE	1 UNIT	200.00	220
18 WHEEL ALIGNMENT	1 UNIT	65.00	✓
19 TOWING FEE	1 UNIT	50.00	✓
20 LABOUR CHARGE	1 UNIT	500.00	400
21 SPRAY PAINTING	1 UNIT	700.00	620
		1,545.00	1,545.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7.2728
3557.5
3166.