

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SPORE 417883

VEHICLE No: SJZ 9144D

TOTAL LOSS

ESTIMATE COST FOR REPAIR HYUNDAI TUCSON SJZ 9144D PARTS AND LABOUR

\$12,000.00

not Allowed
done
TOTAL LOSS

MV \$12000
LTA \$9090.
\$2910

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: