

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jan 2020 09:56		13 Jan 2020 16:32 Edit Adj Rpt	S\$4,063.60 Edit Estimates	S\$4,063.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: RAIMANA HERMAN CHAUVIN , ID: S8368787H, Tel: +6582282619, Email: RAIMANAC@GMAIL.COM									
Vehicle Reg. No.: SMJ9770U		Date of Loss: 10/01/2020 08:00 - :59 [4 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 4945638793SG		Policy/Cover Note No.: 1900067384 (Comprehensive)							
		Excess: S\$800.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Azlan, Syazairdina] syazairdina.azlan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 22/01/2020]									
Driver/Custodian: RAIMANA HERMAN CHAUVIN (36 / Male) , NRIC: S8368787H, Tel: +6582282619 Email: RAIMANAC@GMAIL.COM									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
- AIG_SG (23/04/2020): Alert - Adj Mandate Approved (S\$4063.60) - SMJ9770U - Claim Handler: Azlan, Syaz... - AIG_SG (14/01/2020): SMJ9770U / OD / 10/01/2020 / Coverage & Excess update - AIG_SG (14/01/2020): Alert - Adj Mandate Approved (S\$3983.00) - SMJ9770U - Claim Handler: Mohd Rizal,... - AIG_SG (14/01/2020): SMJ9770U / OD / 10/01/2020 / Coverage & Excess update									
ALL ASSOCIATED TASKS ☐				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMJ9770U (4945638793SG)
OD
Jan 10 2020 8:00AM
[RAIMANA HERMAN CHAUVIN]
Premium Automobiles Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
------------------	---------------	--------------------	--------------	--------------	---

Assessment Reports

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/01/20 11:21	Adjuster Immediate Advice		Load HTM	

1 per page ▼

☒

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/01/20 09:43	General View		Load JPG	☒
2	14/01/20 09:43	General View		Load JPG	☒
3	14/01/20 09:43	General View		Load JPG	☒
4	14/01/20 09:43	General View		Load JPG	☒
5	14/01/20 09:43	General View		Load JPG	☒
6	14/01/20 09:43	General View		Load JPG	☒
7	14/01/20 09:43	General View		Load JPG	☒
8	14/01/20 09:43	General View		Load JPG	☒
9	14/01/20 09:43	General View		Load JPG	☒
10	14/01/20 09:43	General View		Load JPG	☒
11	14/01/20 09:43	General View		Load JPG	☒
12	14/01/20 09:43	General View		Load JPG	☒
13	14/01/20 09:43	General View		Load JPG	☒
14	14/01/20 09:43	General View		Load JPG	☒
15	14/01/20 09:43	General View		Load JPG	☒
16	14/01/20 09:43	General View		Load JPG	☒
17	14/01/20 09:43	General View		Load JPG	☒
18	14/01/20 09:43	General View		Load JPG	☒
19	14/01/20 09:43	General View		Load JPG	☒
20	14/01/20 09:43	General View		Load JPG	☒
21	14/01/20 09:43	General View		Load JPG	☒
22	14/01/20 09:43	General View		Load JPG	☒
23	14/01/20 09:43	General View		Load JPG	☒
24	14/01/20 09:43	General View		Load JPG	☒
25	14/01/20 09:43	General View		Load JPG	☒
26	14/01/20 09:43	General View		Load JPG	☒
27	14/01/20 09:43	General View		Load JPG	☒
28	14/01/20 09:43	General View		Load JPG	☒
29	14/01/20 09:43	General View		Load JPG	☒
30	14/01/20 09:43	General View		Load JPG	☒
31	14/01/20 09:43	General View		Load JPG	☒

3 per page ▼

☒

Documentation

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/01/20 09:33	Certificate of Insurance		Load PDF	
2	14/01/20 09:33	Singapore Accident Statement		Load PDF	
3	14/01/20 09:33	SG CAR MART		Load PDF	
4	14/01/20 09:33	ESTIMATE		Load PDF	
5	14/01/20 09:44	Driver's Driving License		Load PDF	
6	14/01/20 14:40	Foreign Driving License		Load PDF	

1 per page ▼

☒

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
7	31/03/20 14:47	mark estiamte		Load PDF	
8	17/06/20 12:13	DISCHARGE VOUCHER		Load PDF	
9	17/06/20 12:13	WORKSHOP INVOICE		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	10/01/20 16:42	Accident Statement		Load HTM	

Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	10/01/20 16:34	Accident Photo		Load JPG	☒
2	10/01/20 16:34	Accident Photo		Load JPG	☒
3	10/01/20 16:34	Accident Photo		Load JPG	☒
4	10/01/20 16:34	Accident Photo		Load JPG	☒
5	10/01/20 16:34	Accident Photo		Load JPG	☒
6	10/01/20 16:34	Accident Photo		Load JPG	☒
7	10/01/20 16:34	Accident Photo		Load JPG	☒
8	10/01/20 16:34	Accident Photo		Load JPG	☒
9	10/01/20 16:34	Accident Photo		Load JPG	☒
10	10/01/20 16:34	Accident Photo		Load JPG	☒
11	10/01/20 16:34	Accident Photo		Load JPG	☒
12	10/01/20 16:34	Accident Photo		Load JPG	☒
13	10/01/20 16:34	Accident Photo		Load JPG	☒
14	10/01/20 16:34	Accident Photo		Load JPG	☒
15	10/01/20 16:34	Accident Photo		Load JPG	☒
16	10/01/20 16:34	Accident Photo		Load JPG	☒
17	10/01/20 16:34	Accident Photo		Load JPG	☒
18	10/01/20 16:34	Accident Photo		Load JPG	☒
19	10/01/20 16:34	Accident Photo		Load JPG	☒
20	10/01/20 16:34	Accident Photo		Load JPG	☒
21	10/01/20 16:34	Accident Photo		Load JPG	☒
22	10/01/20 16:34	Accident Photo		Load JPG	☒
23	10/01/20 16:34	Accident Photo		Load JPG	☒
24	10/01/20 16:34	Accident Photo		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	10/01/20 16:40	Sketch Plan		Load JPG	☒
2	10/01/20 16:40	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20000770/ATD3S2**Date:** 17/06/2020**REFERENCE**

Insured/Claimant:	RAIMANA HERMAN CHAUVIN	Policy No:	1900067384
Date of Loss:	10/01/2020	Nature of Claim:	OD Claim No: 4945638793SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ9770U		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZC32959
Reg. Date:	22/08/2019 (Man. Year: 2019)	Chassis No:	WAUZZZGA7KA082500
Colour:	Black	Odometer:	5235 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$119,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,557.00	1,911.60	13,645.40	87.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,552.00	2,152.00	3,400.00	61.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,109.00	4,063.60	17,045.40	80.75
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	20,309.00	3,263.60	17,045.40	83.93
+ GST 7.00/7.00% (S\$)	1,421.63	228.45	1,193.18	83.93
Nett Amount (S\$)	21,730.63	3,492.05	18,238.58	83.93

INSPECTION

Date of Assignment:	13/01/2020	
Date Inspected:	13/01/2020	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER - LH / RH	Repair	1,571.00 FS	*- FS
2	1		*FRONT BUMPER CONNECTING PIECE - CENTER	Not Necessary	134.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	179.00 FS	*143.20 FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	308.00 FS	*- FS
6	1		*FRONT BUMPER END CAP - LH / RH	Not Necessary	62.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Deformed	273.00 FS	*218.00 FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	142.00 FS	*- FS
9	1		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	62.00 FS	*- FS
10	1		*FRONT BUMPER ADAPTER - LH	Not Necessary	32.00 FS	*- FS
11	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	38.00 FS	*- FS
12	1		*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
13	1		*RADIATOR STRIKER PLATE	Not Necessary	114.00 FS	*- FS
14	1		*FRONT BUMPER CARRIER	Not Necessary	625.00 FS	*- FS
15	1		*FOAM FILLER PIECE	Not Necessary	71.00 FS	*- FS
16	1		*FRONT BUMPER TOP COVER	Not Necessary	91.00 FS	*- FS
17	1		*SIGN CAUTION	Not Necessary	13.00 FS	*- FS
18	1		*A/C STICKER	Not Necessary	7.00 FS	*- FS
19	1		*FAN FARE - LH	Not Necessary	262.00 FS	*- FS
20	1		*SIGNAL HORN - RH	Not Necessary	180.00 FS	*- FS
21	1		*SPRING SHACKLE - LH / RH	Not Necessary	58.00 FS	*- FS
22	1		*BONNET	Not Necessary	2,549.00 FS	*- FS
23	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
24	1		*IMPACT PROTECTION - CENTER	Not Necessary	27.00 FS	*- FS
25	1		*IMPACT PROTECTION - LH	Not Necessary	28.00 FS	*- FS
26	1		*IMPACT PROTECTION - RH	Not Necessary	27.00 FS	*- FS
27	1		*BONNET STRIKER - LH / RH	Not Necessary	200.00 FS	*- FS
28	1		*GAS FILLED STRUT	Not Necessary	93.00 FS	*- FS
29	1		*BONNET ENGINE ABS SOUND COVER	Not Necessary	201.00 FS	*- FS
30	2		*LID LOCK MICROSWITCH	Not Necessary	367.00 FS	*- FS
31	1		*BOWDEN CABLE - CENTER	Not Necessary	53.00 FS	*- FS
32	1		*RELEASE ELEMENT	Not Necessary	53.00 FS	*- FS
33	1		*RELEASE LEVER	Not Necessary	12.00 FS	*- FS
34	1		*BOWDEN CABLE - LH / RH	Not Necessary	106.00 FS	*- FS
35	1		*HEADLIGHT MOUNTING	Not Necessary	107.00 FS	*- FS
36	1		*LED HEADLIGHT - RH	Not Necessary	4,491.00 FS	*- FS
37	1		*LIFT CYLINDER - LH / RH	Not Necessary	256.00 FS	*- FS
38	1		*FRONT WHEEL COVER - LH / RH	Necessary	588.00 FS	*469.60 FS
39	1		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	54.00 FS	*- FS
40	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	19.00 FS	*- FS
41	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS
42	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **15,557.00** **1,911.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,200.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,552.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >