

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SMJ 9770 U

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	500 ✓
3	To respray front bumper and bonnet.	\$ 2,200.00	1100 H.S. ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 5,552.00</b>	