

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'ed | Status                                                          |
|------|-----------------------------------------|---------------|---------------------------------------------------|------------------------------------------------------|------------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 10 Jan 2020<br><a href="#">Edit Reg</a> |               | 10 Jan 2020 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$5,706.40</b><br><a href="#">Edit Estimates</a> | <b>S\$5,706.40</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | Reference | Claim Details                                                                              | Documents  | <a href="#">Show All</a> |         |             |              |            |       |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------------------------------------------------------------------------------------|------------|--------------------------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>                                                                                                                                                                                                                                                                                                                                                                                                                       |           |                                                                                            |            |                          |         |             |              |            |       |
| Insured: <b>NG PUEY KOON</b> , ID: S1405682C                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |           |                                                                                            |            |                          |         |             |              |            |       |
| Main Claimant: <b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: 200303878K                                                                                                                                                                                                                                                                                                                                                                                                                                   |           |                                                                                            |            |                          |         |             |              |            |       |
| Vehicle Reg. No.: <b>SHD5256E</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |           | Date of Loss: 09/01/2020 07:00 - :59<br>[11 Months and 23 Days From LTA Reg Date (Man Yr)] |            |                          |         |             |              |            |       |
| Claim Type: <b>TP / 0323276589SG</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |           | Policy/Cover Note No.: 1800022445 (Comprehensive)                                          |            |                          |         |             |              |            |       |
| Vehicle Reg. No. (Insured): <b>SKN9115P</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |           | Policy No. (Claimant): VFX/P2203857                                                        |            |                          |         |             |              |            |       |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |           | Excess:                                                                                    |            |                          |         |             |              |            |       |
| Repairer: <b>Trans-cab Auto Services Pte Ltd (Ang Mo Kio)</b> 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666                                                                                                                                                                                                                                                                                                                                                                                      |           |                                                                                            |            |                          |         |             |              |            |       |
| Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] <a href="#">Saliha.Syed-Yusoff@aig.com</a>                                                                                                                                                                                                                                                                                                                           |           |                                                                                            |            |                          |         |             |              |            |       |
| Claimant's Insurer: <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6880 4888                                                                                                                                                                                                                                                                                                                                                                                                                                        |           |                                                                                            |            |                          |         |             |              |            |       |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 22/01/2020]                                                                                                                                                                                                                                                                                                                                                                      |           |                                                                                            |            |                          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                                                                                                                                                                                                                                                                                                                                                 |           |                                                                                            |            |                          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (29/07/2020): <b>Alert - Adj Mandate Approved (S\$6793.74) - SHD5256E - Claim Handler: Syed-Yusoff...</b></li> <li>AIG_SG_EXPRESS (02/07/2020): <b>Alert - Adj Mandate Approved (S\$6280.89) - SHD5256E - Claim Handler: Syed-Yusoff...</b></li> <li>AIG_SG_EXPRESS (13/04/2020): <b>Alert - Adj Mandate Maintained - SHD5256E - Claim Handler: Syed-Yusoff, Saliha</b></li> <li>AIG_SG (14/01/2020): <b>Request to upload TP GIA Report</b></li> </ul> |           |                                                                                            |            |                          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>                                                                                                                                                                                                                                                                                                                                 |           |                                                                                            |            |                          |         |             |              |            |       |
| Due Date                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | Priority  | Type                                                                                       | Task Group | Subject                  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |           |                                                                                            |            |                          |         |             |              |            |       |



## Claim Documents

\*SHD5256E (0323276589SG)  
[SKN9115P]  
TP  
TRANS-CAB SERVICES PTE LTD  
Jan 9 2020 7:00AM  
[NG PUEY KOON]  
Trans-cab Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

**View** View in Browser ▾

### Letters/Correspondences

1 per page ▾
☒

| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ)                  |  | Thumbnail            | Print |
|----|--------------|----------------------------------------------------|--|----------------------|-------|
| 1  | (Draft)      | Third Party Express Settlement – Payment Breakdown |  | <a href="#">Edit</a> |       |

### Assessment Reports

1 per page ▾
☒

| No | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) |  | Thumbnail                | Print |
|----|----------------|-----------------------------------|--|--------------------------|-------|
| 1  | 16/03/20 14:11 | Adjuster Immediate Advice         |  | <a href="#">Load HTM</a> |       |

### Photos/Images

3 per page ▾
☒

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |  | Thumbnail                | Print                               |
|----|-----------------|-----------------------------------|--|--------------------------|-------------------------------------|
| 1  | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 2  | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 3  | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 4  | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 5  | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 6  | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 7  | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 8  | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 9  | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 10 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 11 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 12 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 13 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 14 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 15 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 16 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 17 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 18 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 19 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 20 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 21 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 22 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |
| 23 | 16/03/20 13:38  | General View                      |  | <a href="#">Load JPG</a> | <input checked="" type="checkbox"/> |

### Documentation

1 per page ▾
☒

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                          |  | Thumbnail                | Print |
|----|-----------------|----------------------------------------------------------------------------|--|--------------------------|-------|
| 1  | 19/01/20 01:00  | TP GIA REPORT                                                              |  | <a href="#">Load PDF</a> |       |
| 2  | 18/02/20 15:39  | LETTER TO OI                                                               |  | <a href="#">Load PDF</a> |       |
| 3  | 16/03/20 13:48  | TP ESTIMATE - MARKED                                                       |  | <a href="#">Load PDF</a> |       |
| 4  | 20/07/20 15:36  | EMAIL TP REJECT OFFER                                                      |  | <a href="#">Load PDF</a> |       |
| 5  | 20/07/20 15:38  | Traffic Police Outcome                                                     |  | <a href="#">Load PDF</a> |       |
| 6  | 20/07/20 15:38  | LOD, Repair Bill, Authorisation to Act, LTA Search, Rental supporting docs |  | <a href="#">Load PDF</a> |       |
| 7  | 25/08/20 15:15  | Authorisation to Act                                                       |  | <a href="#">Load PDF</a> |       |
| 8  | 25/08/20 15:15  | LTA SEARCH                                                                 |  | <a href="#">Load PDF</a> |       |
| 9  | 25/08/20 15:15  | Release Voucher                                                            |  | <a href="#">Load PDF</a> |       |
| 10 | 25/08/20 15:15  | RENTAL MILEAGE                                                             |  | <a href="#">Load PDF</a> |       |

| Letters/Correspondences |                |                                           |  | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-------------------------------------------|--|------------|-------------------------------------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ)         |  | Thumbnail  | Print                               |
| 11                      | 25/08/20 15:15 | RENTAL RECEIPT                            |  | Load PDF   |                                     |
| 12                      | 25/08/20 15:15 | WORKSHOP INVOICE                          |  | Load PDF   |                                     |
| No                      | Finalized On   | AIG Asia Pacific Insurance Pte. Ltd. (SG) |  | Thumbnail  | Print                               |
| 1                       | 14/01/20 15:30 | OI GIA REPORT                             |  | Load PDF   |                                     |

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                      |
|-------------------|---------------------|--------|----------------------|
| Vehicle No:       | SKN9115P (Insd veh) | Model: | TOYOTA PRIUS 1.8 5DR |
|                   | SHD5256E (TP veh)   |        | HATCHBACK (A)        |
| Date of Accident: | 09/01/2020          |        |                      |

|                                                                                                             |   |     |     |       |    |                        |
|-------------------------------------------------------------------------------------------------------------|---|-----|-----|-------|----|------------------------|
| Global Sum Settlement                                                                                       | : | [ ] | Yes | [ X ] | No |                        |
| Repair Estimate                                                                                             | : | \$  |     |       |    | 49,671.13              |
| Final Repair Cost                                                                                           | : | \$  |     |       |    | 6,105.85               |
| Loss of Use                                                                                                 | : | \$  |     |       |    | days at \$0.00 per day |
| Rental (if any)                                                                                             | : | \$  |     |       |    | 680.40                 |
| LTA / GIA Search Fee                                                                                        | : | \$  |     |       |    | 7.49                   |
| Others:                                                                                                     | : | \$  |     |       |    |                        |
|                                                                                                             | : | \$  |     |       |    |                        |
| Final Settlement Sum                                                                                        | : | \$  |     |       |    | 6,793.74               |
| <b>Is Third Party Workshop GIA Registered?</b> [ ] <b>YES</b> [ X ] <b>NO</b> (Kindly indicate below)       |   |     |     |       |    |                        |
| <b>A) For Non GIA Registered Workshop:</b> Agreed Liability _____ 100 _____ (%)                             |   |     |     |       |    |                        |
| <b>B) For GIA Registered Workshop:</b> BOLA Applicable: Yes/ No    BOLA Scenario No: _____                  |   |     |     |       |    |                        |
| BOLA Liability: _____ (%)    Assessed Liability (*): _____ (%)                                              |   |     |     |       |    |                        |
| <i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i> |   |     |     |       |    |                        |
| Remarks _____<br>_____<br>_____                                                                             |   |     |     |       |    |                        |

| Payment Instruction: Payee's Breakdown |                                 |      |          |
|----------------------------------------|---------------------------------|------|----------|
| 1)                                     | Trans-Cab Auto Services Pte Ltd | : \$ | 6,793.74 |
| 2)                                     |                                 | : \$ |          |
| 3)                                     |                                 | : \$ |          |
| 4)                                     |                                 | : \$ |          |

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

25 Aug  
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG20000780/KKA3S2**Date:** 25/08/2020REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1800022445   |
| <b>Claimant Vehicle No :</b> | SHD5256E                             | <b>Insured Vehicle No :</b> | SKN9115P     |
| Date of Loss:                | 09/01/2020                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 0323276589SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                     |             |                   |
|-----------------------------|-------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHD5256E</b>                     |             |                   |
| Make & Model:               | TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) | Engine No:  | 2ZR2C00224        |
| Reg. Date:                  | 17/01/2019 (Man. Year: 2018)        | Chassis No: | JTDKB3FU103079322 |
| Colour:                     | Metallic Pearl White/Red            | Odometer:   | 71024 km          |
| Engine Capacity:            | 1798 cc                             |             |                   |
| Market Value/New Car Price: | N/A                                 |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>   |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

CONDITION OF TYRES

|                   |             |                  |               |
|-------------------|-------------|------------------|---------------|
| Front Tyre Size:  | 195/65 R15  | Rear Tyre Size:  | 195/65 R15    |
| Front Left Side:  | Sailun 9 mm | Rear Left Side:  | Goodyear 6 mm |
| Front Right Side: | Sailun 9 mm | Rear Right Side: | Goodyear 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 24,431.62         | 3,666.40          | 20,765.22         | 84.99         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 21,990.00         | 2,040.00          | 19,950.00         | 90.72         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>                        | <b>46,421.62</b>  | <b>5,706.40</b>   | <b>40,715.22</b>  | <b>87.71</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 3,249.51          | 399.45            | 2,850.06          | 87.71         |
| <b>Nett Amount (S\$)</b>                        | <b>49,671.13</b>  | <b>6,105.85</b>   | <b>43,565.28</b>  | <b>87.71</b>  |
| <b>+ Car Rental (6.0 x S\$113.40/day) (S\$)</b> |                   | 680.40            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.49              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>6,793.74</b>   |                   |               |

INSPECTION

|                             |            |                                                                                                           |
|-----------------------------|------------|-----------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 10/01/2020 |                                                                                                           |
| Date Inspected:             | 10/01/2020 | Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)<br>2, Ang Mo Kio Street 63<br>Singapore 569111 |
| Estimated Period of Repair: | 5.0 days   |                                                                                                           |

**Adjuster:** KENNETH KONG**Manager:** Khanchna Pothuraj*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. Particulars                            | Condition     | Repairer's  | Amount       |
|-----|-----|-------------------------------------------------|---------------|-------------|--------------|
| 1   | 1   | *REAR BUMPER                                    | Bent          | 442.60 FL   | *442.60 FL   |
| 2   | 1   | *REAR BUMPER RE-INFORCEMENT                     | Bent          | 332.70 FL   | *332.70 FL   |
| 3   | 1   | *REAR BUMPER TOWING COVER                       | Missing       | 15.40 FL    | *15.40 FL    |
| 4   | 1   | *REAR BUMPER UNDER COVER (BLACK)                | Distorted     | 576.30 FL   | *576.30 FL   |
| 5   | 1   | *REAR BUMPER SIDE RETAINER LH                   | Distorted     | 116.50 FL   | *116.50 FL   |
| 6   | 1   | *REAR BUMPER SIDE RETAINER RH                   | Serviceable   | 117.70 FL   | *- FL        |
| 7   | 1   | *SEAL, REAR BUMPER SIDE, LH                     | Serviceable   | 88.50 FL    | *- FL        |
| 8   | 1   | *SEAL, REAR BUMPER SIDE, RH                     | Serviceable   | 88.50 FL    | *- FL        |
| 9   | 1   | *REAR TAILGATE                                  | Buckled       | 1,147.80 FL | *1,147.80 FL |
| 10  | 1   | *REAR TAILGATE OUTER GARNISH                    | Not Necessary | 925.60 FL   | *- FL        |
| 11  | 1   | *ANTENNA, ELECTRICAL KEY                        | Serviceable   | 72.00 FL    | *- FL        |
| 12  | 1   | *COVER, REAR COMBINATION LAMP, RH               | Serviceable   | 64.50 FL    | *- FL        |
| 13  | 1   | *COVER, REAR COMBINATION LAMP, LH               | Serviceable   | 64.50 FL    | *- FL        |
| 14  | 1   | *GARNISH, BACK DOOR SIDE, LH                    | Serviceable   | 95.60 FL    | *- FL        |
| 15  | 1   | *GARNISH, BACK DOOR SIDE, RH                    | Serviceable   | 95.60 FL    | *- FL        |
| 16  | 1   | *MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER     | Serviceable   | 56.50 FL    | *- FL        |
| 17  | 1   | *MOULDING, BACK DOOR OUTSIDE GARNISH. LOWER LH  | Serviceable   | 56.50 FL    | *- FL        |
| 18  | 1   | *BOARD ASSY, BACK DOOR TRIM                     | Serviceable   | 259.20 FL   | *- FL        |
| 19  | 1   | *REAR TAILGATE WEATHERSTRIP                     | Serviceable   | 372.30 FL   | *- FL        |
| 20  | 1   | *COVER, BACK DOOR LOCK                          | Repair        | 30.20 FL    | *- FL        |
| 21  | 1   | *LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH   | Dented        | 467.00 FL   | *467.00 FL   |
| 22  | 1   | *SWITCH ASSY, BACK DOOR OPENER                  | Serviceable   | 179.10 FL   | *- FL        |
| 23  | 1   | *SPOILER, SUB ASSY, REAR                        | Serviceable   | 1,575.40 FL | *- FL        |
| 24  | 1   | *GLASS, BACK WINDOW FIX                         | Serviceable   | 761.40 FL   | *- FL        |
| 25  | 1   | *PANEL SUB-ASSY, BODY LOWER BACK                | Bent          | 650.30 FL   | *650.30 FL   |
| 26  | 1   | *TAILLAMP LOWER RH                              | Serviceable   | 502.00 FL   | *- FL        |
| 27  | 1   | *TAILLAMP UPPER RH                              | Serviceable   | 451.80 FL   | *- FL        |
| 28  | 1   | *REAR BUMPER SIDE RH                            | Mtg Cracked   | 123.70 FL   | *123.70 FL   |
| 29  | 1   | *REAR BUMPER SIDE LH                            | Mtg Cracked   | 123.70 FL   | *123.70 FL   |
| 30  | 1   | *TAILLAMP LOWER LH                              | Serviceable   | 502.00 FL   | *- FL        |
| 31  | 1   | *TAILLAMP UPPER LH                              | Not Necessary | 443.30 FL   | *- FL        |
| 32  | 1   | *REAR FENDER LH                                 | Repair        | 871.50 FL   | *- FL        |
| 33  | 1   | *LINER, REAR WHEEL HOUSE, LH                    | Repair        | 139.80 FL   | *- FL        |
| 34  | 1   | *DUCT ASSY, QUARTER VENT, LH                    | Serviceable   | 67.00 FL    | *- FL        |
| 35  | 1   | *DUCT ASSY, QUARTER VENT, RH                    | Serviceable   | 67.00 FL    | *- FL        |
| 36  | 1   | *REAR FENDER RH                                 | Repair        | 871.50 FL   | *- FL        |
| 37  | 1   | *LINER, REAR WHEEL HOUSE, RH                    | Repair        | 139.80 FL   | *- FL        |
| 38  | 1   | *BOARD, BACK DOOR TRIM                          | Serviceable   | 225.20 FL   | *- FL        |
| 39  | 1   | *PANEL ASSY, DECK TRIM SIDE, RH                 | Serviceable   | 355.90 FL   | *- FL        |
| 40  | 1   | *PANEL ASSY, DECK TRIM SIDE, LH                 | Serviceable   | 355.90 FL   | *- FL        |
| 41  | 1   | *COVER, FLOOR UNDER, NO.1                       | Serviceable   | 175.10 FL   | *- FL        |
| 42  | 1   | *COVER, FLOOR UNDER, NO.2                       | Serviceable   | 241.90 FL   | *- FL        |
| 43  | 1   | *COVER, REAR FLOOR                              | Serviceable   | 229.90 FL   | *- FL        |
| 44  | 1   | *COVER, DECK TRIM, REAR                         | Serviceable   | 126.70 FL   | *- FL        |
| 45  | 1   | *BOARD, REAR FLOOR, NO.1                        | Serviceable   | 519.00 FL   | *- FL        |
| 46  | 1   | *BOX, DECK FLOOR, RH                            | Serviceable   | 313.60 FL   | *- FL        |
| 47  | 1   | *BOX, DECK FLOOR, LH                            | Serviceable   | 313.00 FL   | *- FL        |
| 48  | 1   | *BOX, DECK FLOOR, REAR                          | Serviceable   | 105.80 FL   | *- FL        |
| 49  | 1   | *PAN, REAR FLOOR                                | Repair        | 583.40 FL   | *- FL        |
| 50  | 1   | *EXTENSION, REAR FLOOR SIDE PANEL, RH           | Serviceable   | 78.30 FL    | *- FL        |
| 51  | 1   | *EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH | Serviceable   | 196.50 FL   | *- FL        |
| 52  | 1   | *EXTENSION, REAR FLOOR SIDE PANEL, LH           | Serviceable   | 78.30 FL    | *- FL        |
| 53  | 1   | *EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH | Serviceable   | 196.50 FL   | *- FL        |
| 54  | 1   | *PIPE ASSY, EXHAUST, TAIL                       | Repair        | 1,655.40 FL | *- FL        |
| 55  | 1   | *TROUGH, BACK DOOR OPENING, LH                  | Serviceable   | 103.40 FL   | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. Particulars                               | Condition     | Repairer's  | Amount     |
|-----|-----|----------------------------------------------------|---------------|-------------|------------|
| 56  | 1   | *STAY ASSY, BACK DOOR, LH                          | Serviceable   | 242.50 FL   | *- FL      |
| 57  | 1   | *STAY ASSY, BACK DOOR, RH                          | Serviceable   | 242.50 FL   | *- FL      |
| 58  | 1   | *WIRE, BACK DOOR, NO.2                             | Serviceable   | 294.40 FL   | *- FL      |
| 59  | 1   | *WIRE, LUGGAGE ROOM, NO.3                          | Serviceable   | 170.70 FL   | *- FL      |
| 60  | 1   | *WIRE, BACK DOOR, NO.1                             | Serviceable   | 247.40 FL   | *- FL      |
| 61  | 1   | *SOCKET & WIRE SUB ASSY, REAR COMBINATION LAMP, LH | Serviceable   | 63.30 FL    | *- FL      |
| 62  | 1   | *SOCKET & WIRE SUB ASSY, REAR COMBINATION LAMP, RH | Serviceable   | 63.30 FL    | *- FL      |
| 63  | 1   | *SET PARKING AID                                   | Dented        | 700.00 FS   | *220.00 FS |
| 64  | 1   | *SET REAR BUMPER CLIP                              | Necessary     | 66.00 FS    | *66.00 FS  |
| 65  | 2   | *REAR WINDSCREEN SEALANT                           | Necessary     | 80.00 FS    | *40.00 FS  |
| 66  | 1   | *WINDSCREEN MOULDING                               | Necessary     | 100.00 FS   | *100.00 FS |
| 67  | 1   | *REAR WINDSCREEN INNER SPONGE SEAL                 | Necessary     | 100.00 FS   | *30.00 FS  |
| 68  | 1   | *REAR TAILGATE TOYOTA LOGO                         | Necessary     | 47.00 FS    | *47.00 FS  |
| 69  | 1   | *REAR TAILGATE WORDING PRIUS                       | Necessary     | 52.90 FS    | *52.90 FS  |
| 70  | 1   | *REAR TAILGATE WORDING HYBRID                      | Necessary     | 53.50 FS    | *53.50 FS  |
| 71  | 1   | *REAR TAILGATE STICKER TRANS-CAB                   | Necessary     | 80.00 FS    | *30.00 FS  |
| 72  | 1   | *REAR TAILGATE STICKER 6555-3333                   | Necessary     | 80.00 FS    | *30.00 FS  |
| 73  | 1   | *REAR BUMPER PROTECTOR                             | Serviceable   | 100.00 FS   | *- FS      |
| 74  | 1   | *REAR LH WHEEL RIM                                 | Serviceable   | 1,879.40 FS | *- FS      |
| 75  | 1   | *REAR LH WHEEL RIM COVER                           | Serviceable   | 211.50 FS   | *- FS      |
| 76  | 1   | *SPARE WHEEL RIM                                   | Serviceable   | 1,879.40 FS | *- FS      |
| 77  | 1   | *SPARE WHEEL RIM COVER                             | Serviceable   | 211.50 FS   | *- FS      |
| 78  | 1   | *SET REAR RH FENDER LINER CLIP                     | Not Necessary | 35.00 FS    | *- FS      |
| 79  | 1   | *REAR LH TYRE 195/65/15                            | Serviceable   | 350.00 FS   | *- FS      |
| 80  | 1   | *REAR NUMBER PLATE WITH MOULDING                   | Serviceable   | 200.00 FS   | *- FS      |
| 81  | 1   | *SPARE TYRE 195/65/15                              | Serviceable   | 350.00 FS   | *- FS      |
| 82  | 1   | *SET REAR BUMPER RETAINER LH CLIP                  | Not Necessary | 30.00 FS    | *- FS      |
| 83  | 1   | *SET REAR BUMPER RETAINER RH CLIP                  | Not Necessary | 30.00 FS    | *- FS      |
| 84  | 1   | *SET REAR LH FENDER LINER CLIP                     | Not Necessary | 35.00 FS    | *- FS      |
| 85  | 1   | *REAR RH TYRE 195/65/15                            | Serviceable   | 350.00 FS   | *- FS      |
| 86  | 1   | *REAR RH WHEEL RIM                                 | Serviceable   | 1,879.40 FS | *- FS      |
| 87  | 1   | *REAR RH WHEEL RIM COVER                           | Serviceable   | 211.50 FS   | *- FS      |
| 88  | 1   | *SET REAR FLOOR UNDER COVER CLIP                   | Not Necessary | 35.00 FS    | *- FS      |
| 89  | 1   | *SET REAR FENDER LINER SCREW                       | Not Necessary | 30.00 FS    | *- FS      |
| 90  | 1   | *SET EXHAUST PIPE SUPPORT                          | Serviceable   | 100.00 FS   | *- FS      |
| 91  | 1   | *EXHAUST PIPE GASKET                               | Serviceable   | 55.00 FS    | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>29,464.80</b> | <b>4,665.40</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 5,033.18         | 999.00          |
| <b>Total Parts (\$\$)</b>                                  | <b>24,431.62</b> | <b>3,666.40</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                | Lab.Type | Repairer's       | Amount          |
|---------------------------------|----------------------------------------------------------------------------------------------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                            |          |                  |                 |
| 1                               | TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                                              | New      | 170.00           | 60.00           |
| 2                               | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                                                   | New      | 220.00           | 0.00            |
| 3                               | TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                         | New      | 170.00           | 60.00           |
| 4                               | PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. | New      | 9,000.00         | 600.00          |
| 5                               | TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                                           | New      | 170.00           | 0.00            |
| 6                               | TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.                                                        | New      | 170.00           | 120.00          |
| 7                               | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                                    | New      | 170.00           | 30.00           |
| 8                               | TO REINSTALL REAR BUMPER PARKING SENSOR.                                                                                   | New      | 170.00           | 50.00           |
| 9                               | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                          | New      | 9,000.00         | 1,100.00        |
| 10                              | TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                            | New      | 380.00           | 0.00            |
| 11                              | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.                                                           | New      | 380.00           | 0.00            |
| 12                              | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.                            | New      | 380.00           | 0.00            |
| 13                              | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                               | New      | 170.00           | 0.00            |
| 14                              | TO REPAIR AND REALIGN REAR EXHAUST PIPE.                                                                                   | New      | 170.00           | 0.00            |
| 15                              | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                    | New      | 170.00           | 20.00           |
| 16                              | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.                                                                           | New      | 170.00           | 0.00            |
| 17                              | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.                                            | New      | 380.00           | 0.00            |
| 18                              | TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.                                       | New      | 170.00           | 0.00            |
| 19                              | TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.        | New      | 380.00           | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                            |          | <b>21,990.00</b> | <b>2,040.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >