

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5256E**AAD2001-088***Not Authorised
Pursuing B4 paint*

Vehicle No.:

Chassis No.:

10 JAN 2020

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 5256E

JTDKB3FU103079322

TOYOTA

PRIUS

9.1.2020

AIG

17/1/2019

PART**LIST**

1	REAR BUMPER	\$	B ₁	442.60	✓
1	REAR BUMPER RE-INFORCEMENT	\$	B ₁	332.70	✓
1	REAR BUMPER TOWING COVER	\$	mi	15.40	✓
1	REAR BUMPER UNDER COVER (BLACK)	\$	DIT	576.30	✓
1	REAR BUMPER SIDE RETAINER LH	\$	DIT	116.50	✓
1	REAR BUMPER SIDE RETAINER RH	\$	Sm	117.70	X
1	SEAL, REAR BUMPER SIDE, LH	\$	Sm	88.50	X
1	SEAL, REAR BUMPER SIDE, RH	\$	Sm	88.50	X
1	REAR TAILGATE	\$	Bu	1,147.80	✓
1	REAR TAILGATE OUTER GARNISH	\$		925.60	7 x NN
1	ANTENNA, ELECTRICAL KEY	\$	Sm	72.00	X
1	COVER, REAR COMBINATION LAMP, RH	\$	Sm	64.50	X
1	COVER, REAR COMBINATION LAMP, LH	\$	Sm	64.50	X
1	GARNISH, BACK DOOR SIDE, LH	\$	Sm	95.60	X
1	GARNISH, BACK DOOR SIDE, RH	\$	Sm	95.60	X
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	Sm	56.50	X
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	Sm	56.50	X
1	BOARD ASSY, BACK DOOR TRIM	\$	Sm	259.20	X
1	REAR TAILGATE WEATHERSTRIP	\$	Sm	372.30	X
1	COVER, BACK DOOR LOCK	\$	N	30.20	X
1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	Net	467.00	✓
1	SWITCH ASSY, BACK DOOR OPENER	\$	Sm	179.10	X
1	SPOILER, SUB ASSY, REAR	\$	Sm	1,575.40	X
1	GLASS, BACK WINDOW FIX	\$	Sm	761.40	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	B ₁	650.30	✓
1	TAILLAMP LOWER RH	\$	Sm	502.00	X
1	TAILLAMP UPPER RH	\$	Sm	451.80	X
1	REAR BUMPER SIDE RH	\$	mgcra	123.70	✓

Trans-cab Auto Services Pte Ltd**AAD2001-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5256E

1	REAR BUMPER SIDE LH	\$	<i>mjens</i> 123.70 ✓
1	TAILLAMP LOWER LH	\$	<i>sn</i> 502.00 X
1	TAILLAMP UPPER LH	\$	443.30 ? x NN
1	REAR FENDER LH	\$	<i>R</i> 871.50
1	LINER, REAR WHEEL HOUSE, LH	\$	<i>n</i> 139.80
1	DUCT ASSY, QUARTER VENT, LH	\$	<i>sn</i> 67.00
1	DUCT ASSY, QUARTER VENT, RH	\$	<i>sn</i> 67.00
1	REAR FENDER RH	\$	<i>R</i> 871.50
1	LINER, REAR WHEEL HOUSE, RH	\$	<i>R</i> 139.80
1	BOARD, BACK DOOR TRIM	\$	<i>sn</i> 225.20
1	PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>sn</i> 355.90
1	PANEL ASSY, DECK TRIM SIDE, LH	\$	<i>sn</i> 355.90
1	COVER, FLOOR UNDER, NO.1	\$	<i>sn</i> 175.10
1	COVER, FLOOR UNDER, NO.2	\$	<i>sn</i> 241.90
1	COVER, REAR FLOOR	\$	<i>sn</i> 229.90
1	COVER, DECK TRIM, REAR	\$	<i>sn</i> 126.70
1	BOARD, REAR FLOOR, NO.1	\$	<i>sn</i> 519.00
1	BOX, DECK FLOOR, RH	\$	<i>sn</i> 313.60
1	BOX, DECK FLOOR, LH	\$	<i>sn</i> 313.00
1	BOX, DECK FLOOR, REAR	\$	<i>sn</i> 105.80
1	PAN, REAR FLOOR	\$	<i>R</i> 583.40
1	EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	<i>sn</i> 78.30
1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	<i>sn</i> 196.50
1	EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	<i>sn</i> 78.30
1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	<i>sn</i> 196.50
1	PIPE ASSY, EXHAUST, TAIL	\$	<i>R</i> 1,655.40
1	TROUGH, BACK DOOR OPENING, LH	\$	<i>sn</i> 103.40
1	STAY ASSY, BACK DOOR, LH	\$	<i>sn</i> 242.50
1	STAY ASSY, BACK DOOR, RH	\$	<i>sn</i> 242.50
1	WIRE, BACK DOOR, NO.2	\$	<i>sn</i> 294.40
1	WIRE, LUGGAGE ROOM, NO.3	\$	<i>sn</i> 170.70
1	WIRE, BACK DOOR, NO.1	\$	<i>sn</i> 247.40
1	SOCKET & WIRE SUB ASSY, REAR COMBINATION LAMP, LH	\$	<i>sn</i> 63.30
1	SOCKET & WIRE SUB ASSY, REAR COMBINATION LAMP, RH	\$	<i>sn</i> 63.30

TOTAL \$ 20,132.70

Trans-cab Auto Services Pte Ltd**AAD2001-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5256E

25%	\$	5,033.18
	\$	15,099.53

Special Nett

1SET PARKING AID	\$	<i>nd</i> 700.00 <i>220sn</i>
1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 <i>✓</i>
2 REAR WINDSCREEN SEALANT	\$	<i>na</i> 80.00 <i>40sn</i>
1 WINDSCREEN MOULDING	\$	<i>na</i> 100.00 <i>✓</i>
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00 <i>30sn</i>
1 REAR TAILGATE TOYOTA LOGO	\$	<i>na</i> 47.00 <i>✓</i>
1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i> 52.90 <i>✓</i>
1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i> 53.50 <i>✓</i>
1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>na</i> 80.00 <i>30sn</i>
1 REAR TAILGATE STICKER '6555-3333'	\$	<i>na</i> 80.00 <i>30sn</i>
1 REAR BUMPER PROTECTOR	\$	<i>sn</i> 100.00 <i>X</i>
1 REAR LH WHEEL RIM	\$	<i>sn</i> 1,879.40
1 REAR LH WHEEL RIM COVER	\$	<i>sn</i> 211.50
1 SPARE WHEEL RIM	\$	<i>sn</i> 1,879.40
1 SPARE WHEEL RIM COVER	\$	<i>sn</i> 211.50
1SET REAR RH FENDER LINER CLIP	\$	<i>na</i> 35.00
1 REAR LH TYRE 195/65/15	\$	<i>sn</i> 350.00
1 REAR NUMBER PLATE WITH MOULDING	\$	<i>sn</i> 200.00
1 SPARE TYRE 195/65/15	\$	<i>sn</i> 350.00
1SET REAR BUMPER RETAINER LH CLIP	\$	<i>na</i> 30.00
1SET REAR BUMPER RETAINER RH CLIP	\$	<i>na</i> 30.00
1SET REAR LH FENDER LINER CLIP	\$	<i>na</i> 35.00
1 REAR RH TYRE 195/65/15	\$	<i>sn</i> 350.00
1 REAR RH WHEEL RIM	\$	<i>sn</i> 1,879.40
1 REAR RH WHEEL RIM COVER	\$	<i>sn</i> 211.50
1SET REAR FLOOR UNDER COVER CLIP	\$	<i>na</i> 35.00
1SET REAR FENDER LINER SCREW	\$	<i>na</i> 30.00
1SET EXHAUST PIPE SUPPORT	\$	<i>sn</i> 100.00
1 EXHAUST PIPE GASKET	\$	<i>sn</i> 55.00
TOTAL	\$	9,332.10

TOTAL PARTS	\$	24,431.63
--------------------	-----------	------------------

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5256E**AAD2001-088****LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	60%
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	60%
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,000.00	60%
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	nn X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	120%
To Rust-Proofing Of The Affected Areas.	\$	170.00	30%
To reinstall rear bumper parking sensor.	\$	170.00	50%
Putty And Spray Painting Of The Affected Portion.	\$	9,000.00	1100%
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	↪ X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	↪ X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	↪ X

Trans-cab Auto Services Pte Ltd**AAD2001-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5256E

To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>2cl</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>4</i> 170.00	<i>X</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>4</i> 380.00	<i>X</i>
TOTAL	\$	21,990.00	
Over All Total	\$	46,421.63	

(PART-BY-PART) Repair Days*30 Days*
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: