

2004200

ASS. REC. BY:

REF: es/MSG20000785/AGY d30h

Special Instruction:

Assigner: Admin

ASSIGNMENT (Office)

From (Person): Crystal Lee

of MSG

Date/Time: 13/01/2020 @ 4:52pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

JLG 3287

Insured:

SKP 57384

at Workshop m/s

S.M. Automotive

Tel:

6747 9241

of

1 Kaki Bukit Ave 6 # 01-43 Autobay

9710 8881

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vehl:
(Client's Record)

D.O.A. 11/01/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5:15pm @ 13/1/2020

Person Contacted:

Sukyi

Vehicle IN / OUT

Date/Time	Action/Instruction
	Is done ✓
	JLG 3287 - X
	SKP 57384 - X
15/1	Pending Estimate from Repairer (Merimen Submit)
9/3	Revert Preli by Merimen

Merimen

ASSIGNMENT

File No: 2463287

Estimated Date: 2008 Oct.

OD / TP / WS / TP RES / CO RES / EVA / RV / REV

To inspect Vehicle No: Honda Civic

at Workshop no: Black

at: 1799

Insured: Insured / Std / M / NA

Policy No: PMHFD/63080303296

Claim No: PMHFD/63080303296

Sum Insured: Insured / Std / M / NA

(Client's Record) Excess: _____

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Considered? Yes or No

GIA / PR Seat: _____ Constant? Yes or No

Est. Repair: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS: _____

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Year: 2008

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer

Make: Honda Civic

Colour: Black

Sp. Reading: 125695

Engine: _____

C/N: PMHFD/63080303296

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt

Brake: In order / Jammed / Leaked / Burnt

Mod: Nil / S/Rim / STD A/Rim

Tyre Size: F: 225/40R18
R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Presc.

Front	Rear
R/Bal: <u>06</u> mm	R/Bal: <u>06</u> mm
L/Bal: <u>06</u> mm	L/Bal: <u>06</u> mm
D.O.A. _____	D.O.I. <u>13/01/20</u>

Survey held at: SM

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>IPMS/G</u>
<u>1/3</u>	<u>LIS \$4700/= (Red \$7658-56, 61%)</u> <u>MV: 43k RM ~ 21K.</u> <u>PV: 3k RM ~ 1K.</u> <u>Nett: 40k RM ~ 20K.</u>

RECEIVED 09 MAR 2020

Order Type: Prel. Report Final Report

Days Of Repair: 7

Resturvey No. of Trip: 2

Order Type: Typist

Amount Paid: \$4700/=

Survey Fee	<u>200</u>
Transportation	
Other	
	<u>11</u>
	<u>211</u>

View Sent Message

This mail is associated with :

***JLG3287**
[SKP5738H]

TP
SHOFIAN BIN MUSTAMI
Jan 11 2020 12:00AM
[ROGERIO BERNARDO]
Sm Automotive - Kaki Bukit

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 15/01/2020 18:05 PM.
To monica_chung@sg.msg-asia.com
CC sur@lkkauto.com
Subject VEHICLE NO: JLG3287 DOA: 11/01/2020

Dear Monica

Please be informed that we have inspected the vehicle JLG3287 on 13/01/2020.

We are still pending estimate from repairer.

Thank you

Regards
Yvonne Wong
LKK AUTO CONSULTANTS PTE LTD

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 09 Mar 2020

Preliminary Advice

Insured Vehicle No	: SKP5738H	Accident Date	: 11/01/2020
TP Vehicle No	: JLG3287	Assignment Date	: 15/01/2020
Make	: HONDA CIVIC	Est. Duration of Repair	: 7.00
Date of Inspection	: 13/01/2020		
Inspection At	: SM AUTOMOTIVE - KAKI BUKIT (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,358.56
Revised Amount	:S\$	4,700.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,700.00
Lump Sum Repair	:S\$	4,700.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 13 January 2020 4:52 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: JLG3287 PRI.pdf; JLG3287 POLICE REPORT AND LOG CARD.pdf

JLG3287 CLAIMING AGAINST SKP5738H (MSIG) DOA:11.01.2020

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua <helene_phua@sg.msig-asia.com>

Sent: Monday, 13 January 2020 3:46 PM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>

Subject: FW: JLG3287 CLAIMING AGAINST SKP5738H (MSIG) DOA:11.01.2020

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com





A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Monday, 13 January 2020 3:45 PM
To: sm automotive <sm_automotive@hotmail.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: JLG3287 CLAIMING AGAINST SKP5738H (MSIG) DOA:11.01.2020

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



A Member of **MS&AD** INSURANCE GROUP

From: sm automotive <sm_automotive@hotmail.com>
Sent: Monday, 13 January 2020 11:28 AM
To: Helene Phua <helene_phua@sg.msig-asia.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: Re: JLG3287 CLAIMING AGAINST SKP5738H (MSIG) DOA:11.01.2020

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Without Prejudice

Hi Helene

Please arrange for 1) LKK Auto Consultants Pte Ltd

Regards,

Sukyi Chong
SM AUTOMOTIVE

1 Kaki Bukit Ave 6
Blk C #01-43
Singapore 417883
Tel: 6747 9241 Fax: 6741 7276

From: Helene Phua <helene_phua@sg.msig-asia.com>
Sent: Monday, January 13, 2020 10:17 AM
To: sm_automotive@hotmail.com <sm_automotive@hotmail.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: JLG3287 CLAIMING AGAINST SKP5738H (MSIG) DOA:11.01.2020

Hi,

We refer to your email dated 13/01/2020.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1. Xing Guo Qiang	6) Chow Bo Xiong
2. Kenneth Kong	7) Siew Meng Hui
3. Marcus Chua	8) Daniel Chan
4. Ng You Han	9) Victor Png
5. Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- a. ***Fast lane settlement is not applicable for cases that liability is in dispute***
- b. If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: sm automotive <sm_automotive@hotmail.com>
Sent: Monday, 13 January 2020 10:06 AM
To: Claims <claims@sg.msig-asia.com>
Cc: Helene Phua <helene_phua@sg.msig-asia.com>
Subject: JLG3287 CLAIMING AGAINST SKP5738H DOA:11.01.2020

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Without Prejudice

Hi Motor Claim Dept

Please kindly send us your surveyor list,thanks.

Regards,

Sukyi Chong
SM AUTOMOTIVE

1 Kaki Bukit Ave 6
Blk C #01-43
Singapore 417883
Tel: 6747 9241 Fax: 6741 7276

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SM AUTOMOTIVE

Our Ref : JLG3287
Your Ref : SKP5738H
Date : 13/1/2020

1 Kaki Bukit Ave 6
Blk C @ Autobay, #01-43
Singapore 417883
Tel : (65) 6747 9241
Fax : (65) 6741 7276

MSIG INSURANCE (SINGAPORE) PTE LTD

BY EMAIL

claims@sg.msig-asia.com

Attn : Motor Claims Department

Dear Sirs,

DATE OF ACCIDENT : **11 JAN 2020 @ 13:45 hours**
NOTICE OF INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We act for **SHOFIAN BIN MUSTAMI** who has appointed the undermentioned workshop to repair motor vehicle no. **JLG3287**

Please be informed that the said vehicle can be inspected at :

SM AUTOMOTIVE
1 KAKI BUKIT AVE 6
#01-43 BLK C @ AUTOBAY
SINGAPORE 417883

Contact Person : Office @ 6747 9241 (Reena / Sukyi)

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The said workshop will commence repairs thereafter without further reference to you.

Yours Faithfully

SM AUTOMOTIVE

For Surveyor,
Please initial here after completion of
Pre-repair inspection. Thank you

Surveyor Name :
& signature

Date&Time :



Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

Report No. T/20200111/2067

CONTINUATION OF REPORT

Driver			
Name	SHOFIAN BIN MUSTAMI	ID No.	A36405024
Related Vehicle	NIL	Contact No.	0167440451
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 11/01/2020 I was driving Malaysia registered vehicle bearing registration number: JLG3287. On the same day at about 1.45pm, I was driving along PIE towards Changi on the 1st lane. The traffic was heavy on the 1st lane and slow moving. When I noticed the vehicle in-front of me had stopped. I then applied my brakes and came to a complete stopped. Seconds later, I felt a huge impact from the rear. After which I came out of the my vehicle to assess the damaged. I then found out that a vehicle bearing registration number: SKP5738H had hit the rear of my vehicle. I and the other driver exchange particular and left the place. No parties were injured at that point of time. No Police or ambulance were called in. I do not have an on-board camera install in my vehicle.

Damage to my vehicle: Booth dented inwards and unable to close. Rear bumper dented inwards. Fender crack and rear sensor has some issue.



**SINGAPORE
POLICE FORCE**



T/20200111/2067

3 of 3

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

Report No: T/20200111/2067

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
E /
Sgt 3 MUHAMMAD AL-RAZIF S/O G
SUPPAIYAH MD FAIZAL

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SSI 2 YEO GEAK ENG CECILIA
Contact No.: 65476404

Signature Of Informant:

Date/Time:
11/01/2020 15:04

Classification Of Case:

Authentication Stamp
NP168

SIGNATURE

SN 64

THE SCHEDULE

ORIGINAL COPY

JADUAL

SALINAN ASAL

Agent Code (Kod Ejen) : T61762E-001 SUTERA AGENCY	Date (Tarikh) : 30 JAN 2019
Replacing Cover Note No. (Menggantikan Nota Lindung No.) : TH19-00001056	Receipt No. (No. Resit) :
Certificate No. (No. Sijil) :	ACT (ACT) : 73.63
The Participant (Peserta) : SHOFIAN BIN MUSTAMI	Contribution (Caruman) : 1700.43
Address (Alamat) : NO 108 JALAN SETIA 10/6, TAMAN SETIA INDAH JOHOR BAHRU 81100 JOHOR DARUL TAKZIM	NCD:55.00%(30 JAN 2019) : 935.24
Business Reg No. (No. Sykt.) :	REBATE:0.00% : 0.00
I/C No. New (No. K/P Baru) : 740316-08-6677 Old I/C No. (No. K/P Lama) :	SERVICE TAX : 45.91
Business / Profession (Perniagaan / Pekerjaan) : OTHERS	EXT COVER : 0.00
Hire Purchase Owners (Pemilik Sewa Beli) : PHP	
Employer / Lessors (Majikan / Pemajak) :	
Period of Coverage (Tempoh Perlindungan) (a) From (Dari) : 02 FEB 2019 To (Hingga) : 01 FEB 2020 Termasuk kedua-dua Time (Masa) : 12:01 AM To (Hingga) : 11:59:59PM tarikh dan masa	STAMP DUTY (DUTI SETEM) : RM 10.00
(b) Any subsequent period for which you shall pay and we shall agree to accept a renewal contribution Sebarang tempoh selanjutnya untuk mana anda membayar dan kami bersetuju menerima caruman pembaharuan	TOTAL (JUMLAH) : RM 821.10

The Motor Vehicle

Any of the following (Mana - mana daripada yang berikut) :

Kenderaan Motor

Registration No.	Make	Type of Body	Cubic Capacity	Year of Manufacture	Seating Capacity Including Driver	Your Estimate of Value Including Accessories
No. Pendaftaran	Buatan	Jenis Badan	Keupayaan Enjin	Tahun Diberbuat	Muatan Tempat Duduk termasuk Pemandu	Nilai Anggaran Anda termasuk Aksesori
JLG3287	HONDA CIVIC I-VTEC	SALOON	1799 CC	2008	5	43,000.00

Date of Signature of Proposal and Declaration (Tarikh Cadangan dan Pernyataan Ditandatangani) : **EXCESS : 0.00 (LEBIHAN) Theft Excess : RM0.00** **Engine (Enjin) : R18A11933267 CHASIS (Chassis) : PMHFD16308D303206**

Subject to the terms and conditions of the Certificate and endorsement as numbered below :
Terdakluk kepada peraturan - peraturan dan syarat - syarat Sijil dan pengendaraan seperti disenaraikan di bawah :

Named Driver : a) THE PARTICIPANT
b) NORAZZAH BINTI OTHMAN

Include Endorsement No :

Additional Extra Coverage/Endorsements :-

Code	Description	Value	Contribution
07	ADDITIONAL DRIVERS	0.00	0.00

LEGISLATION:-

Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third Party Risks and Compensation) Act (Cap 188) Republic of Singapore Motor Vehicles (Third Party Risks and Compensation) Rules (Republic of Singapore) Motor Vehicles Takaful (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam (the reference to legislation under the heading "Avoidance of Certain Terms and Right of Recovery" is invited to Section 94, 95 and 96 of the Road Transport Act 1987 (Malaysia) Section 7, 8 and 9 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and Section 7 of the Motor Vehicles Takaful (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

UNDANG - UNDANG:-

Akta Pengangkutan Jalan Raya, 1987 (Malaysia), Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura, Peraturan Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) 1987 (Republik Singapura), Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam (rujukan kepada undang - undang di bawah tajuk "Pengecualan Peraturan - Peraturan Dan Hak Tuntutan Tertentu" adalah terhad kepada Seksyen 94, 95 dan 96 Akta Pengangkutan Jalan Raya, 1987 (Malaysia), Seksyen 7, 8 dan 9 Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura, dan Seksyen 7 Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam).


Limits of Liability:

Had Tanggungan:

Limit of the amount of the Takaful Operator's Liability under Section B-1(a) : **Unlimited**
Had jumlah tanggungan Pengendali Takaful di bawah Seksyen B-1(a) :

Limit of the amount of the Takaful Operator's Liability under Section B-1(b) : **RM3,000,000.00**
Had jumlah tanggungan Pengendali Takaful di bawah Seksyen B-1(b) :

For and on behalf of / Untuk dan bagi pihak
ZURICH GENERAL TAKAFUL MALAYSIA BERHAD



Zuhair Ismail

Limitation as to Use

Had Penggunaan

: As shown in the Certificate of Takaful
: Seperti ditunjukkan dalam Sijil Takaful

Geographical Area

Had Wilayah

: Malaysia, Republic of Singapore and Negara Brunei Darussalam
: Malaysia, Republik Singapura dan Negara Brunei Darussalam

Authorised Driver

Pemandu Yang Dibenarkan:

: As shown in the Certificate of Takaful
: Seperti ditunjukkan dalam Sijil Takaful

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN: JLG3287

No. Siri A 6637375

6434-4

740316086677
[MAL]

Nama Pemunya Berdaftar : SHOFIAN BIN MUSTAMI
Alamat : 02-07 JALAN BAYU TEBRAU 1 TAMAN BAYU TEBRAU
81750 JOHOR BAHRU JOHOR D.T.

No. Enjin	: R18A11933267	B.D.M/B.G.K	: -
No. Casis	: PMHFD16308D303296	B.T.T.	: -
Buatan	: HONDA	Berat Kerb	: -
Nama Model	: CIVIC 1.8L I-VTEC (A)	B.T.M.	: -
Keupayaan Enjin	: 1799 S.P	B.G.1	: -
Bahan Bakar	: PETROL	B.G.2	: -
Warna	: HITAM	B.G.3	: -
Keles Kegunaan	: PERSENDIRIAN-MOTOKAR INDIVIDU	B.G.4	: -
Jenis Badan	: MOTOKAR	B.G.5	: -
Tahun Dibuat	: 2008	B.G.6	: -
Tarikh Pendaftaran	: 29/10/2008	B.G.7	: -
Status Pemunya	: PERSENDIRIAN	B.G.8	: -
Muatan Tempet		B.G.9	: -
Duduk	: 5	B.G.10	: -
Kadar Lesen		B.G.11	: -
Kenderaan Motor	: 6 bulan 12 bulan	B.G.12	: -
	RM139.80 RM279.60		

Tandatangani Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan
oleh Pengarah JPJ Negeri KOMPLEKS JPJ, NEGERI JOHOR II

PEWASANGAN TEMPATAN

UNTUK KEGUNAAN PEJABAT

HAK MILIK DITUNTUT OLEH : AFFIN BANK BERHAD NO SIRI SURAT : 0750249

NOTA PENTING

- Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengarah Jabatan Pengangkutan Jalan [JPJ].
- Semak butir-butir kenderaan di muke ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
- Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membarui lesen 60 hari sebelum tempohnya tamat.
- Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengarah JPJ sekiranya kenderaan anda tidak berlesen.
- Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
- Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
- Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

BAYARAN-BAYARAN

1	109012 29102008 12:18:01 031000 N 42-67428 ROKIAH 02500 CK 0 02500 JLG3287 28/10/2008 2102040RM*****300.00 2353070RM*****50.00 RM*****350.00	11
2	109012 29102008 12:18:37 035600 N 42-67429 ROKIAH 02584 CK 0 02584 JLG3287 28/10/2009 2203000RM*****279.60 RM*****279.60	12
3	109011 18102010 11:48:47 039600 N 36-19872 IJAH 02050 TV 0 02050 JLG3287 28/10/2011 2203000RM*****279.60 RM*****279.60	13
4		14
5		15
6		16
7		17
8		18
9		19
10		20

PERTUKARAN-PERTUKARAN MILIKAN DAN ALAMAT

1	No. K.P./Def. Negeri/Sykt	Tandatangan Pemunya Berdaftar
2	No. K.P./Def. Negeri/Sykt	Tandatangan Pemunya Berdaftar
3	No. K.P./Def. Negeri/Sykt	Tandatangan Pemunya Berdaftar
4	No. K.P./Def. Negeri/Sykt	Tandatangan Pemunya Berdaftar
5	No. K.P./Def. Negeri/Sykt	Tandatangan Pemunya Berdaftar

REKOD-REKOD PEMERIKSAAN

1	5	9
2	6	10
3	7	11
4	8	12

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

13/01/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPMS16

YVonne

Accident date: 13/01/2020

Estimated repair cost for vehicle no: JLG3287 HONDA CIVIC 1.8 A

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$621.40 ✓
2	2	Rear Boot Lid Hinge <i>New</i>	\$48.00	\$96.00 ✓
3	1	Rear Boot Lid Emblem Logo		\$35.00 ✓
4	1	Rear Boot Lid Civic Logo		\$38.80 ✓
5	1	Rear Boot Lid 1.8 Logo		\$32.00 ✓
6	1	Rear Boot Lid Ivtec Logo		\$36.10 ✓
7	1/2	Rear Boot Lid Side Reflector <i>2 out</i>	\$202.20	\$404.40 <i>202.20</i>
8	1	Rear Boot Lid Number Plate <i>New</i>		\$50.00 ✓
9	2	Rear Boot Lid Number Plate Lamp <i>New</i>	\$83.10	\$166.20 ✓
10	1	Rear Boot Lid Inner Lock <i>Painted</i>		\$194.50 ✓
11	1	Rear Boot Lid Inner Rubber <i>Kit</i>		\$137.60 ✓
12	2	Rear Tail Lamp <i>Cracked</i>	\$328.70	\$657.40 ✓
13	4	Rear Tail Lamp Clip <i>New</i>	\$6.50	\$26.00 ✓
14	1	Rear Bumper <i>Dented</i>		\$645.30 ✓
15	10	Rear Bumper Clip <i>New</i>	\$6.50	\$65.00 <i>30</i>
16	2	Rear Bumper Side Retainer <i>New</i>	\$33.10	\$66.20 ✓
17	1	Rear Bumper Reverse Sensor (Special Nett) <i>Dented</i>		\$350.00 <i>200/sn</i>
18	2	Rear Bumper Bracket <i>New</i>		\$55.20 ✓
19	1	Rear End Panel <i>Dented</i>		\$318.30 ✓
20	1	Rear End Panel Top Garnish <i>Dented</i>		\$161.20 ✓
21	2	Rear Fender Inner Trim Board <i>New</i>	\$232.80	\$465.60 ✓
22	16	Rear Fender Inner Trim Board Clip <i>New</i>	\$6.50	\$104.00 ✓
23	1	Rear Spare Tyre Panel <i>Repair</i>		\$1,254.40 ✓
24	1	Rear Spare Tyre Panel Top Cover <i>Dented</i>		\$329.96 ✓
25	1	Rear Spare Tyre Panel & End Panel Sealant <i>New</i>		\$450.00 <i>180/sn</i>
26	1	Rear Exhaust <i>Repair</i>		\$728.50 ✓
27	2	Rear Exhaust Chrome Pipe <i>Paint</i>	\$186.00	\$372.00 <i>100/sn</i>
28	1	Rear Center Exhaust <i>New</i>		\$637.50 ✓

3531.96
282556

SN 480

Subtotal :- \$8,498.56

Labour charges

To remove & refit rear cushion		\$280.00 80
To remove & refit reverse sensor		\$100.00 50
To remove & refit rear exhaust		\$280.00 80
To check wiring		\$100.00 30
Tuff kote		\$150.00 60
Towing fee	2600	\$150.00 X
Panel beating		\$1,400.00 1200
Spray painting		\$1,400.00 1400

Subtotal :- \$3,860.00

Total:- \$12,358.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
h/s ~~13~~ 13/01/20

07 Days

total: 5005.56

l/s: A.7K.

47K

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Jan 2020		15 Jan 2020 14:04 Edit Adj Rpt	S\$4,700.00 Edit Estimates	S\$4,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Rogério Bernardo , ID: S74895498, Tel: +6593364853, Email: rogeriobernardo@dbs.com								
Main Claimant:	SHOFIAN BIN MUSTAMI , ID: A36405024								
Vehicle Reg. No.:	JLG3287	Date of Loss:	11/01/2020 00:00 - :59 [134 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 237330	Policy/Cover Note No.:	1000890478 (Comprehensive) Coverage: 17/02/2019 - 16/02/2020						
Vehicle Reg. No. (Insured):	SKP5738H	Policy No. (Claimant):							
		Excess:							
Repairer:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/02/2020]								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 13/01/2020. (Manual Assign). Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Sukyl Chong @ 6747 9241.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JLG3287 (237330)
[SKP5738H]
TP
SHOFIAN BIN MUSTAMI
Jan 11 2020 12:00AM
[Rogerio Bernardo]
Sm Automotive - Kaki Bukit

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="button" value="v"/>
Assessment Reports			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/03/20 11:25	Adjuster Immediate Advice	 Load HTML	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/03/20 16:18	General View	 Load JPG	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/03/20 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	06/03/20 16:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation				
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/01/20 12:38	Agree on SJE	Load PDF	
2	15/01/20 12:38	PRI	Load PDF	
3	15/01/20 12:38	JLG3287 PRI	Load PDF	
4	15/01/20 12:40	JLG3287 POLICE REPORT AND LOG CARD	Load PDF	
5	17/01/20 17:21	SKP5738H E-filed GIA report	Load PDF	
6	17/01/20 17:23	Status of Driving Licence - Invalid	Load PDF	
7	10/02/20 13:16	Status of Driving Licence - invalid.pdf	Load PDF	
8	17/02/20 09:24	Status of Driving Licence - invalid (SG).pdf	Load PDF	
9	26/02/20 09:33	Status of Driving Licence - valid.pdf	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	15/01/20 14:03	Survey Request - Manual Assigned	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20000785/AGYD3E2

Date: 17/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 1000890478
Claimant Vehicle No : JLG3287	Insured Vehicle No : SKP5738H
Date of Loss: 11/01/2020	Nature of Claim: TP Claim No: 237330

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JLG3287	Engine No: R18A11933267
Make & Model: HONDA CIVIC, 1.8 L (A)	Chassis No: PMHFD16308D303296
Reg. Date: 29/10/2008 (Man. Year: 2008)	Odometer: 125695 km
Colour: Black	Engine Capacity: 1799 cc
Market Value/New Car Price: N/A	Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No
	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18	Rear Tyre Size: 225/40 R18
Front Left Side: Presa 6 mm	Rear Left Side: Presa 6 mm
Front Right Side: Presa 6 mm	Rear Right Side: Presa 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,498.56	3,305.57	5,192.99	61.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	2,600.00	1,260.00	32.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,358.56	5,905.57	6,452.99	52.21
Approved Total (Overridden) (S\$)		4,700.00		
Nett Amount (S\$)	12,358.56	4,700.00	7,658.56	61.97

INSPECTION

Date of Assignment: 15/01/2020	Inspected At: Sm Automotive - Kaki Bukit (HQ)
Date Inspected: 13/01/2020	BLOCK C - 1, KAKI BUKIT AVE 6, #01-43
	Singapore 417883
Estimated Period of Repair: 7.0 days	

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2020)
Parts: 143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for JLG3287)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	621.40 F	*621.40 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	96.00 F	*- FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	35.00 F	*35.00 FL
4	1		*REAR BOOT LID CIVIC LOGO	Necessary	38.80 F	*38.80 FL
5	1		*REAR BOOT LID 1.8 LOGO	Necessary	32.00 F	*32.00 FL
6	1		*REAR BOOT LID IVTEC LOGO	Necessary	36.10 F	*36.10 FL
7	1		*REAR BOOT LID SIDE REFLECTOR	O/S Cut	404.40 F	*202.20 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	166.20 F	*- FL
10	1		*REAR BOOT LID INNER LOCK	Damaged	194.50 F	*194.50 FL
11	1		*REAR BOOT LID INNER RUBBER	Cut	137.60 F	*137.60 FL
12	2		*REAR TAIL LAMP	Cracked	657.40 F	*657.40 FL
13	4		*REAR TAIL LAMP CLIP	Necessary	26.00 F	*26.00 FL
14	1		*REAR BUMPER	Deformed	645.30 F	*645.30 FL
15	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	66.20 F	*66.20 FL
17	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
18	2		*REAR BUMPER BRACKET	Not Necessary	55.20 F	*- FL
19	1		*REAR END PANEL	Dented	318.30 F	*318.30 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	161.20 F	*161.20 FL
21	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	465.60 F	*- FL
22	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
23	1		*REAR SPARE TYRE PANEL	Repair	1,254.40 F	*- FL
24	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	329.96 F	*329.96 FL
25	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Necessary	450.00 FS	*180.00 FS
26	1		*REAR EXHAUST	Repair	728.50 F	*- FL
27	2		*REAR EXHAUST CHROME PIPE	Bent	372.00 FS	*100.00 FS
28	1		*REAR CENTER EXHAUST	Not Necessary	637.50 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,498.56	4,011.96
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	706.39
Total Parts (\$\$)	8,498.56	3,305.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REAR CUSHION	New	280.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REAR EXHAUST	New	280.00	80.00
4	TO CHECK WIRING	New	100.00	30.00
5	TUFF KOTE	New	150.00	60.00
6	TOWING FEE	New	150.00	0.00
7	PANEL BEATING	New	1,400.00	1,200.00
8	SPRAY PAINTING	New	1,400.00	1,100.00
Gross Labour Cost (S\$)			3,860.00	2,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >