

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047
Tel: 9695 5547 Fax: 6481 5727 e-mail: ngs motorsportpteltd@gmail.com
Reg No: 201812604N

FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

Attn: Motor Claims Dept

Dear Sir,

RE: ACCIDENT ON 28/12/2019, INVOLVING VEH NO.: SKB3227C & SGC2722M
CLAIMS AGAINST SGC2722M (FWD)

We submit herewith our direct claim estimate quotation as follow:-

Replacement parts - Toyota Wish

- | | |
|---|---------------------------------|
| 1 | Rear Boot Lid |
| 2 | Weatherstrip, Rear Door RH/LH |
| 1 | Rear Boot Sensor |
| 1 | Lock, Rear Boot Lid |
| 1 | Rear Bumper |
| 2 | Extension, Rear Bumper RH/LH |
| 2 | Support, Rear Bumper Side RH/LH |
| 2 | Retainer, Rear Bumper RH/LH |
| 1 | Rear End Panel |
| 1 | Garnish, Rear End Panel |
| 2 | Extension Panel RH/LH |

By	\$	1,461.50	✓
Rm	\$	88.10	\$ 176.20 X
Sm	\$		162.50 X
Rd	\$		336.90 ✓
Bu	\$		570.00 ✓
Sm	\$	68.50	\$ 137.00 X
Rm	\$	101.70	\$ 203.40 X
Sm	\$	61.00	\$ 122.00 X
			\$ 548.80 ?
			\$ 336.20 ?
R	\$	70.70	\$ 141.40 X
			\$ 4,195.90

Less 25% \$ (1,048.97)
\$ 3,146.93

- | | | |
|----|---------------------------------------|--------|
| 1 | Parking Sensor | S.Nett |
| 16 | Clips, Top Garnish | S.Nett |
| 4 | Clips, (for back door center garnish) | S.Nett |
| 16 | Clips, Inner Garnish | S.Nett |
| 1 | Emblem, Bonnet | S.Nett |
| 1 | Emblem, 'VALVE MATIC' | S.Nett |
| 1 | Emblem 'BADGE' | S.Nett |
| 1 | Rear No Plate c/w Casing | S.Nett |

Rm	\$	280.00	X
	\$	5.00	\$ 80.00 ?
Sm	\$	5.00	\$ 20.00 X
	\$	5.00	\$ 80.00 ?
Rm	\$		53.50 ✓
Rm	\$		57.00 ✓
Rm	\$		57.50 ✓
Rd	\$		50.00 455m

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and/2 is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*Not Withheld
L1Pm & ?
Arriving After Rain
4-5 days*

Vehicle No : SKB3227C

To remove all damaged parts with all necessary components/
attachments. Straighten chassis member, repair/reshape dented
body panel in accordance with factory specifications..
Replace/reposition damaged parts, refit align into Refix all
necessary components/attachment.

\$ 800.00 ?

To transfer door mechanism

\$ 150.00 601

To spray portion

\$ 600.00 ✓

To check wiring/proper function on light and etc.

\$ 50.00 201

\$ 5,424.93

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully,

NGS MOTORSPORT PTE LTD

EVELYN NG