



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Buss.Reg.No.: 52888887X

CC9/LPC0000787/Ada3

QUOTATION

No : QT-000207

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

Attention: Motor Claim Department

TEL : 62507388

FAX : 62962706

Your Ref. : SMD240Z
Vehicle No. : SGW3518A
Make & Model : HONDA STREAM
Chassis No. : RN61039637
Engine No. : R18A1744728
Accident Date : 10-01-2020
Policy No. : 210042060904
Date : 16-01-2020
Page : 1 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	WHEEL BEARING (L/H/F) <i>Best</i>	1.0 PCS	156.90	156.90 ✓
2	STEERING KNUCKLE (FRONT) (L/H) <i>and</i>	1.0 PCS	294.20	294.20 ✓
3	BRAKE HOSE (L/H/F) <i>ut</i>	1.0 PCS	103.60	103.60 ✓
4	SHOCK ABSORBER (L/H/F) <i>Best</i>	1.0 PCS	427.30	427.30 ✓
5	SHOCK ABSORBER MOUNTING (L/H/F) <i>new</i>	1.0 PCS	78.00	78.00 ✓
6	LOWER ARM (L/H/F) <i>Best</i>	1.0 PCS	361.30	361.30 ✓
7	STABILIZER LINKAGE (L/H) <i>Best</i>	1.0 PCS	75.00	75.00 ✓
8	POWER STEERING RACK	1.0 PCS	1,779.10	1,779.10 ✗
9	STEERING LINKAGE (L/H/F) <i>new</i>	1.0 PCS	97.80	97.80 ✓
10	STEERING BALL JOINT (L/H)	1.0 PCS	68.00	68.00 ✓
11	DRIVE SHAFT (L/H/F) <i>new</i>	1.0 PCS	1,146.60	1,146.60 ✗
12	WHEEL HUB (L/H/R) <i>Damaged</i>	1.0 PCS	274.70	274.70 ✓
13	WIPER GARNISH (L/H) <i>new</i>	1.0 PCS	88.90	88.90 ✗
14	FRONT WHEEL HOUSING PANEL (L/H/F) <i>Repair</i>	1.0 PCS	530.70	530.70 ✗
15	FENDER (L/H/F) <i>Distorted</i>	1.0 PCS	482.20	482.20 ✓
16	FENDER SIGNAL LAMP (L/H) <i>cracked</i>	1.0 PCS	21.50	21.50 ✓
17	FENDER INNER GARNISH (L/H/F) <i>new</i>	1.0 PCS	88.20	88.20 ✗
18	HEADLIGHT (L/H) <i>smashed</i>	1.0 SET	654.40	654.40 ✓
19	HEADLIGHT LOWER BRACKET (L/H) <i>new</i>	1.0 PCS	33.70	33.70 ✓
20	FRONT BUMPER <i>Distorted</i>	1.0 PCS	699.60	699.60 ✓
21	FRONT BUMPER REINFORCEMENT <i>new</i>	1.0 PCS	240.70	240.70 ✓
22	BUMPER CLIP <i>new</i>	12.0 PCS	4.50	54.00 <i>30</i>
23	FOG LIGHT COVER (L/H) <i>new</i>	1.0 PCS	25.60	25.60 ✗
24	BUMPER SIDE RETAINER (L/H/F) <i>Damaged</i>	1.0 PCS	18.50	18.50 ✓
25	FRONT GRILLE <i>new</i>	1.0 PCS	256.00	256.00 ✗
26	SUPPORT PANEL <i>new</i>	1.0 PCS	514.50	514.50 ✗



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Buss.Reg.No.: 52888887X

QUOTATION

No : QT-000207

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

Attention: Motor Claim Department

TEL : 62507388

FAX : 62962706

Your Ref. : SMD240Z
Vehicle No. : SGW3518A
Make & Model : HONDA STREAM
Chasis No. : RN61039637
Engine No. : R18A1744728
Accident Date : 10-01-2020
Policy No. : 210042060904
Date : 16-01-2020
Page : 2 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
27	SUPPORT PANEL GARNISH (TOP) <i>2 Hem</i>	1.0	PCS 125.40	125.40 <i>+</i>
28	AIR RESONATE BOX	1.0	PCS 203.90	203.90 <i>+</i>
29	DOOR (L/H/R) <i>Dented</i>	1.0	PCS 1,014.10	1,014.10 <i>✓</i>
30	DOOR HINGE (L/H/F UPPER) <i>2 Hem</i>	1.0	PCS 40.60	40.60 <i>+</i>
31	DOOR HINGE (L/H/F LOWER)	1.0	PCS 57.20	57.20 <i>+</i>
32	DOOR (L/H/F) <i>Dented</i>	1.0	PCS 860.00	860.00 <i>✓</i>
33	ROCKER PANEL (L/H) <i>Peris</i>	1.0	PCS 249.30	249.30 <i>+</i>
34	REAR BUMPER <i>Peris</i>	1.0	PCS 960.00	960.00 <i>+</i>
35	BUMPER SIDE RETAINER (L/H/R) <i>2 Hem</i>	1.0	PCS 32.00	32.00 <i>+</i>
36	Discount 20 %			
37	SubTotal (L)			-2,422.70
38	SPORT RIM (L/H/R) <i>wt</i>			9,690.80
39	SPORT RIM (L/H/F) <i>can be</i>	1.0	PCS 300.00	300.00 <i>✓</i>
40	TYRE (L/H/R) <i>Not New</i>	1.0	PCS 300.00	300.00 <i>✓</i>
41	TYRE (L/H/F) <i>selid</i>	1.0	PCS 220.00	220.00 <i>+</i>
42	SubTotal (S)	1.0	PCS 220.00	220.00 <i>180</i>
43	TOWING CHARGES			1,040.00
44	TO COMPUTERISE ADJUST WHEEL ALIGNMENT	1.0	X 120.00	120.00 <i>60</i>
45	TO CHECK UNDERCARRIAGE AND REPLACE DAMAGED PARTS	1.0	X 100.00	100.00 <i>80</i>
46	TO PROVIDE UNDER TURF COAT	1.0	X 350.00	350.00 <i>220</i>
47	PANEL BEATING & REPLACING OF THE ABOVE	1.0	X 150.00	150.00 <i>60</i>
48	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X 1,500.00	1,500.00 <i>800</i>
49	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0	X 1,750.00	1,750.00 <i>1200</i>
50	TO REMOVE AND REFIT SIDE WINDSCREEN GLASS (L/H)	1.0	X 50.00	50.00 <i>30</i>
51	TO REMOVE, TRANSFER & INSTALL RELATED COMPONENT	1.0	X 150.00	150.00 <i>+</i>
52	PRESS BEARING	1.0	PCS 240.00	240.00 <i>160</i>
		1.0	PCS 50.00	50.00 <i>+</i>

5473.30

4378.64

780



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Buss.Reg.No.: 52888887X

QUOTATION

No : QT-000207

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

Attention: Motor Claim Department

TEL : 62507388

FAX : 62962706

Your Ref. : SMD240Z
Vehicle No. : SGW3518A
Make & Model : HONDA STREAM
Chasis No. : RN61039637
Engine No. : R18A1744728
Accident Date : 10-01-2020
Policy No. : 210042060904
Date : 16-01-2020
Page : 3 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
53	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0 X	180.00	180.00
54	SubTotal (LABOUR)			4,640.00

2610

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 7768.64

n/s : 5.5K (Nett Value)

09 Days.

SINGAPORE DOLLAR FIFTEEN THOUSAND THREE HUNDRED SEVENTY AND CENTS EIGHTY ONLY

E. & O.E

Total	S\$	15,370.80
Discount	S\$	0.00
Net Total	S\$	15,370.80

Customer's Signature/Co. Stamp

ZERO GRAVITY

Terms: C.O.D.

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.