



Mer

0.0

0.0

## ESTIMATE FOR SJP1336Y

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

WIP No  
Reg No/Reg Date  
Date In/Mileage  
Chassis No  
Engine No  
Make/Model  
Colour/Trim

1,481.83+  
2,473.48+  
77.91+  
21.42+  
354.79+  
193.89+  
136.49=  
4,739.81\*

0.0 irey

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	09/01/2020/ 17:34	K0	301 / Kerlyn Ong
Description of Goods / Services				

## Z REQUEST

Customer Request  
M BPNSUN

POLICY NO/ACC DATE : DHOM120045731900 // 09/01/2020  
DRIVE IN/TP VEHICLE NO : 09/01/2020 // XD1043P - LONPAC  
DATE IN/DATE SURVEY:  
BY/AUTHORIZED ON :

## A BPILAB

STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT  
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

## A BPIRES

RESPRAY BONNET & FRONT BUMPER

## A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO  
IDENTIFICATION STANDARD. NETT

## A BPILAB

TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT

M FRONT BUMPER cut	1.00	1481.83	00.00	1481.83 ✓
M LH/ FRONT BUMPER RAIL ?	1.00	17.62	00.00	17.62 x
M FRONT BUMPER SEAL ?	1.00	56.92	00.00	56.92 x
M LH/ BASIC MOUNTING FOR BUMPER	1.00	85.35	00.00	85.35 x
M BONNET bf	1.00	2473.48	00.00	2473.48 ✓
M BONNET COMPANY SIGN re	1.00	77.91	00.00	77.91 ✓
M BONNET HOOK X	2.00	33.17	00.00	66.34 x
M BONNET SAFETY HOOK X } m	1.00	79.10	00.00	79.10 x
M BONNET CATCH X	2.00	34.34	00.00	68.68 x
M BONNET STOP BUFFER re	2.00	10.71	00.00	21.42 ✓
M RADIATOR GRILLE MOULDING cm	1.00	354.79	00.00	354.79 ✓
M RADIATOR GRILLE cm	1.00	193.89	00.00	193.89 ✓
M RADIATOR GRILLE BEAM	1.00	183.05	00.00	183.05 x
M LH/ TOP RADIATOR GRILLE MOULDING ? } x m	1.00	40.12	00.00	40.12 x
M RH/ TOP RADIATOR GRILLE MOULDING ?	1.00	40.12	00.00	40.12 x
M LH/ BOTTOM RADIATOR GRILLE MOULDING ?	1.00	40.12	00.00	40.12 x

Confirmed &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany