



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJP1336Y

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No 40512
Reg No/Reg Date SJP1336Y / 15/09/2015
Date In/Mileage / 0
Chassis No WDD2120342B195312
Engine No 27492030425411
Make/Model MB/E 200 2.0 SEDAN (W212) "A"
Colour/Trim 025 585 Covelline B/ 042 258 Basalt Grey

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WL001605	Credit	09/01/2020/ 17:34	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : DHOM120045731900 // 09/01/2020								
DRIVE IN/TP VEHICLE NO : 09/01/2020 // XD1043P - LONPAC								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								
STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES								
RESPRAY BONNET & FRONT BUMPER								
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
IDENTIFICATION STANDARD. NETT								
A BPILAB								
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT								
M FRONT BUMPER	cut				1.00	1481.83	00.00	1481.83 ✓
M LH/ FRONT BUMPER RAIL	?				1.00	17.62	00.00	17.62 x
M FRONT BUMPER SEAL	?				1.00	56.92	00.00	56.92 x
M LH/ BASIC MOUNTING FOR BUMPER	?				1.00	85.35	00.00	85.35 x
M BONNET	bf				1.00	2473.48	00.00	2473.48 ✓
M BONNET COMPANY SIGN	new				1.00	77.91	00.00	77.91 ✓
M BONNET HOOK	X				2.00	33.17	00.00	66.34 x
M BONNET SAFETY HOOK	X				1.00	79.10	00.00	79.10 x
M BONNET CATCH	X				2.00	34.34	00.00	68.68 x
M BONNET STOP BUFFER	new				2.00	10.71	00.00	21.42 ✓
M RADIATOR GRILLE MOULDING	cm				1.00	354.79	00.00	354.79 ✓
M RADIATOR GRILLE	cm				1.00	193.89	00.00	193.89 ✓
M RADIATOR GRILLE BEAM	?				1.00	183.05	00.00	183.05 x
M LH/ TOP RADIATOR GRILLE MOULDING	?				1.00	40.12	00.00	40.12 x
M RH/ TOP RADIATOR GRILLE MOULDING	?				1.00	40.12	00.00	40.12 x
M LH/ BOTTOM RADIATOR GRILLE MOULDING	?				1.00	40.12	00.00	40.12 x

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJP1336Y

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information
WIP No 40512
Reg No/Reg Date SJP1336Y / 15/09/2015
Date In/Mileage / 0
Chassis No WDD2120342B195312
Engine No 27492030425411
Make/Model MB/E 200 2.0 SEDAN (W212) "A"
Colour/Trim 025 585 Covelline B/ 042 258 Basalt Grey

Account No	Terms	Date/Time Printed	CSE	Operator				
WL001605	Credit	09/01/2020/ 17:34	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	RH/ BOTTOM RADIATOR GRILLE MOULDING				1.00	40.12	00.00	40.12
M	MERCEDES STAR				1.00	136.49	00.00	136.49
M	MERCEDES STAR BEAM				1.00	77.44	00.00	77.44
M	MERCEDES STAR BEAM				1.00	264.00	00.00	264.00
M	FRONT STIFFENING				1.00	162.28	00.00	162.28
M	FRAME FOR HEADLAMP UNIT				1.00	275.81	00.00	275.81
M	LH/ HEADLAMP UNIT				1.00	5167.48	00.00	5167.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten notes:
Hp 900/0068
4 days
03/02/2020
Repair before print

Confirmed & accepted by

7% GST on **Nett 17,544.36**
1228.11
Total Payable 18,772.47

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany