



# 南方摩哆

Business Reg. No: 234147/00L  
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762  
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

10<sup>th</sup> January 2020  
AIG Asia Pacific Insurance Pte Ltd  
78 Shanton Way #07-16  
AIG Building  
Singapore (079120)

Dear Sirs,

**RE: Cost of repair to Honda CBR150 – FBH677G**

1pc of Clutch Lever <i>scr</i> ✓	S\$	38.00
1pc of Handle Bar <i>bt</i> ✓		145.00
1pc of Handle Grip <i>scr</i> ✓		35.00
1pc of Brake Lever <i>x nn</i>		38.00
1pc of Gear Lever <i>scr</i> ✓		95.00
1pc of Lower Cowing <i>scr</i> ✓		385.00
1pc of Megneto Cover <i>scr</i> ✓		165.00
1pc of Centre Fairing <i>scr</i> ✓		430.00
1pc of Tail Cover <i>scr</i> ✓		285.00
1pc of Body Slider <i>scr</i> ✓		120.00
1pc of Front Signal <i>ca</i> ✓		58.00
1pc of Exhaust Pipe Cover <i>x nn</i>		165.00
		<hr/>
		1,959.00
	Less 10%	195.90
	Nett	<hr/>
		1,763.10
	Transport	40.00 <i>receipt x nn</i>
	Jack Fork	85.00 <i>x nn</i>
	Engine Oil	20.00 <i>scr</i> ✓
	Gasket	15.00 <i>scr</i> ✓
	Alignment Front Sport Rim	60.00 <i>x nn</i>
	Labor	250.00 <i>150</i>
		<hr/>
		<u>\$2,233.10</u>

*Rasul*  
*Hp 9000068*  
*3 days*  
*4s*  
*13/01/2020*  
*@ 1200*

*Renewing after repair*

Yours Faithfully,  
Southern Motor

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: