

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20000802/ADA3Q2

**Date:** 16/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800147388

**Claimant**  
**Vehicle No :** SLF9358K **Insured Vehicle No :** SMG2837Z

Date of Loss: 13/01/2020 Nature of Claim: TP Claim No: 5815403288SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF9358K		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN017094
Reg. Date:	15/09/2016 (Man. Year: 2016)	Chassis No:	WAUZZZF45HA020890
Colour:	Bronze	Odometer:	49757 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,106.00	1,657.60	3,448.40	67.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,602.00	1,602.00	2,000.00	55.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>8,708.00</b>	<b>3,259.60</b>	<b>5,448.40</b>	<b>62.57</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	609.56	228.17	381.39	62.57
<b>Nett Amount (\$\$)</b>	<b>9,317.56</b>	<b>3,487.77</b>	<b>5,829.79</b>	<b>62.57</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (\$\$)</b>		180.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>3,669.77</b>		

### INSPECTION

Date of Assignment: 15/01/2020

Date Inspected: 15/01/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)  
55 UBI ROAD 1  
Singapore 408699

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,015.00 FS	*1,612.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	66.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	203.00 FS	*- FS
4	1		*REAR BUMPER SPOILER -LH	Not Necessary	227.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR -RH	Necessary	38.00 FS	*29.68 FS
6	1		*REAR BUMPER CARRIER	Not Necessary	819.00 FS	*- FS
7	2		*REAR BUMPER SEAL	Not Necessary	25.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION -RH	Not Necessary	41.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION -LH/RH	O/S Damaged	40.00 FS	*15.92 FS
10	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	462.00 FS	*- FS
11	4		*REAR PARKING AIR SEAL RING	Not Necessary	12.00 FS	*- FS
12	1		*LED TAIL LIGHT -RH OUTER	Not Necessary	931.00 FS	*- FS
13	1		*TAIL LIGHT TRIM -RH OUTER	Not Necessary	27.00 FS	*- FS
14	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **5,106.00**    **1,657.60**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTAL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,602.00</b>	<b>1,602.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >