

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26132

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0049/2020/NS
Date	:	14-Jan-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SMG 2837 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Lim Chee Beng
Address	:	33 Amber Road #18-12 Singapore 439944
Telephone	:	(HP) +65 97587731
Type of Claim	:	Third Party Claims
Policy No.	:	10704051
Vehicle No	:	SLF 9358 K
Model Code	:	A4 Sedan 1.4 TFSI S
Model / Year	:	15/9/2016
Engine No	:	CVN 017094
Chassis No	:	WAUZZZF45HA020890
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	13-Jan-20
Place of Accident	:	Slip Road Of Yishun Ave 8 And 7

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLF 9358 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00	
3	To respray rear bumper and rhs rear fender.	\$ 2,000.00	
4	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 3,602.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 9358 K

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	REAR BUMPER	\$ 2,015.00	
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPER SECURING STRIP	\$ 203.00	
4	REAR BUMPER SPOILER - LH	\$ 227.00	
5	REAR LIGHT REFLECTOR - RH	\$ 38.00	
6	REAR BUMPER CARRIER	\$ 819.00	
7	REAR BUMPER SEAL	2 \$ 25.00	
8	REAR BUMPER GUIDE SECTION - RH	\$ 41.00	
9	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 40.00	
10	REAR PARKING AID SENSOR - INNER / OUTER	2 \$ 462.00	
11	REAR PARKING AID SEAL RING	4 \$ 12.00	
12	LED TAIL LIGHT - RH OUTER	\$ 931.00	
13	TAIL LIGHT TRIM - RH OUTER	\$ 27.00	
14	SUNDRIES	\$ 200.00	

TOTAL SPARE PARTS CHARGES : \$ 5,106.00

TOTAL LABOUR CHARGES : \$ 3,602.00

GRAND TOTAL : \$ 8,708.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant