

FIRST AUTOWORKS

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 10/1/2020

Reference: SLG 5245Z
Make: Chevrolet Cruze

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLG 5245Z
CHASSIS NO.: KL1JA6961BK175363
ENGINE NO.: F16D39382831

TP Budget Direct.
Shirley.

Name of insured :Jia Yi Leasing Pte Ltd
Date of accident.: 07/01/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

<u>Parts</u>				<u>Price (SGD)</u>
<u>No.</u>	<u>Qty.</u>	<u>Description</u>		
1	1	Boot lid	3 new	1901.00 *
2	1	Boot lid Emblem		71.00 +
3	1	Boot lid lettering 'CHEVROLET'	2	65.00 *
4	1	Boot lid lettering 'CRUZE'		45.00 +
5	1	Boot lid Lettering 'LS'		25.00 *
6	1	Boot lid lettering 'Turbo'		52.00 *
7	1	Rear Bootlid Handle (plastic)	new	343.00 +
8	1	Rear Bootlid Inner Trim		250.00 +
9	1	Boot lid lock mechanism		310.00 *
10	1	Boot lid striker		42.00 +
11	1	Boot lid weatherstrip		189.00 +
12	1	Rear bumper	Distorted	1791.00 ✓
13	1	Rear bumper tow hook cover	new	50.00 *
14	1	Centre Bumper Guide		75.00 +
15	1	RHRC Bumper Guide		55.00 +
16	1	LHRC Bumper Guide		55.00 +
17	1	RHR Bumper Guide		65.00 ✓
18	1	LHR Bumper Guide		65.00 *
19	1	Rear bumper reinforcement	Best	736.00 ✓
20	1	Rear end panel	Reps	906.00 +
21	1	Rear end panel trim	new	159.00 +
Parts Total:				7250.00
Less 10%:			16%	2900.00
Total :				4350.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,000.00	550
2	Carry out spray painting on accident affected area	\$ 1,440.00	450
3	To conduct anti rust of under carriage tuff coat	\$ 250.00	+
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 80.00	30
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 250.00	+
6	To remove and refix reverse sensor and conduct test	\$ 80.00	50
7	To conduct transfer of parts from old bootlid to new bootlid	\$ 80.00	+
8	To conduct water leakage test after repairs of vehicle	\$ 80.00	+
9	Remove and replace reverse camera (Labour)	\$ 80.00	+
10	Remove and replace reverse sensor (Labour)	\$ 80.00	+
1080		Labour Total :	4,420.00

Others

No.	Qty	Other Description	Price (SGD)	
1	1	Rear Number plate & bracket	\$ 45.00	+
2	10	Rear bumper clip (set)	\$ 65.00	30
3	4	Rear Bootlid Handle clips	\$ 26.00	+
4	11	Inner bootlid Trim Clips	\$ 71.50	+
5	5	Rear end panel top granish clip (set)	\$ 32.50	+
6	1	Rear end panel insulation seal	\$ 120.00	+
7	1	Rear floor panel insulation seal	\$ 100.00	+
8	1	Reverse camera	\$ 280.00	+
9	1	Reverse sensor(1 set)	\$ 592.00	200
230		Other Total:	1332.00	

TOTAL: \$ 10,102.00
GST 7 %: \$ 707.14
GRAND TOTAL: \$ 10,809.14

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Executive

Ronnie Tan

HP : 8298 8933 Fax: 6844 5185

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 358430
h/s 2850
15/01/20
03 Rys