



彭陳汽車維修中心 PANG & TAN VEHICLE SERVICE CENTRE

160 Sin Ming Drive #04-03 Sin Ming AutoCity Singapore 575722
Tel: 6255 5811 Admin: 6255 5711 Fax: 6255 5700
Co. Reg. No.: 52851972K GST Reg. No.: M9-0364735-P

CHINA TAIFING INSURANCE (S) PTE LTD
3 ANSON ROAD #15-00
SPRINGLEAF TOWER SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62222366 Fax No. : 62247478

Estimate : ES000168

Date : 14/01/2020
Vehicle Num : SL5530U
Make/Model : BMW 730LI F01/02
Chassis/Eng# :
Accident Date : 14/01/2020
Claim No. :
Reference :
Policy No. : 8-V0021328-MVA

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1PC	FRONT BONNET ASSY. / CRU		2,997.00 /
2.	1PC	FRONT BONNET INSULATION X ruc / Nec		332.00 300
3.	20PCS	FRONT BONNET INSULATOR CLIP X ruc / Nec	3.00	60.00 30
4.	1PC	FRONT BONNET LOGO / Nec		97.00 70
5.	1PC	FRONT FENDER X / CRU		1,236.00 /
6.	3PCS	FRONT BONNET LOGO BUSH / Nec	4.00	12.00 /
Nett Total S\$:				4,734.00 4,645

LABOUR :
TO DISMANTLE & REPLACE DAMAGED PARTS
TO RESPRAY PAINT ON AFFECTED PORTION

Labour Total S\$:

480.00 406
500.00 406
980.00 800

[Signature]
16/1/2020

Repair day - 3 days
P/P Lump Sum Repair.
before ~~After~~ part photo.

4,645
- 10%
P = 4,180.5
L = 800
\$ 4,980.50
P/P 3 days

Sun Pm (Lkic)
15/01/2020

E & O E
TP without prejudice

Total S\$: 5,714.00



for PANG & TAN VEHICLE SERVICE CENTRE

LKIC Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: