

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ong Li Li

Date: 15 Jan 2020

**Preliminary Advice**

Vehicle No	: SJY5484D	Accident Date	: 09/01/2020
Make	: DAIHATSU TERIOS	Policy No.	: Z19VP05022517
Assignment Date	: 14/01/2020	Excess	: S\$500.00
Date of Inspection	: 14/01/2020	Est. Duration of Repair	: 4.00
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,200.50
Revised Amount	:S\$	4,880.25
Check Items (Estimated)	:S\$	690.00
Total	:S\$	5,570.25

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	17,000.00
COE / PARF Rebate	:S\$	13,325.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,675.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer able to repair at Not Exceeding Nett Value \$3,675.00