

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5523P**AAD2001-040***NOT AUTHORIZED
1/10/2018 \$3900/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

13 JAN 2020

SHC 5523P

VF1ABL15AUC278863

RENAULT

LATITUDE

6.1.2020

AIG

15-08-14

PART		LIST	
1	DOOR PANEL REAR LH	\$	758.70
1	DOOR GUIDE REAR LH	\$	136.40
1	DOOR WHEATHESTRIIP REAR LH	\$	240.50
1	DOOR MOULDING REAR LH	\$	100.50
1	DOOR FINISHER REAR LH	\$	230.30
1	DOOR REGULATOR REAR LH L70Y	\$	657.10
1	DOOR REGULATOR MOTOR REAR LH L70Y	\$	450.60
1	DOOR WAIST SEAL OUTER REAR LH L70Y	\$	169.60
1	DOOR HANDLE OUTER REAR LH L70Y	\$	42.10
1	DOOR HANDLE CAP REAR LH L70Y	\$	57.90
1	DOOR HANDLE MODULE REAR LH L70Y	\$	133.40
1	DOOR PANEL FRT LH	\$	2,844.66
1	DOOR HINGE UPPER LH	\$	274.50
1	DOOR HINGE LOWER LH	\$	300.55
1	DOOR CHECK FRT LH	\$	90.90
1	DOOR LOCK FRT LH	\$	453.80
1	DOOR REGULATOR FRT LH	\$	758.10
1	DOOR REGULATOR MOTOR FRT LH	\$	501.40
1	DOOR REGULATOR GUIDE FRT LH	\$	69.00
1	DOOR MOULDING FRONT LH	\$	100.50
1	DOOR FINISHER FRONT LH	\$	258.90
1	DOOR WHEATHESTRIIP FRONT LH	\$	316.00
1	DOOR SEAL FRONT LH	\$	69.60
1	DOOR SEAL LOWER FRONT LH	\$	93.90
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	332.00
1	DOOR WAIST SEAL OUTER FRONT LH	\$	92.20
1	DOOR HANDLE OUTER FRONT LH	\$	169.50
1	DOOR HANDLE CAP FRONT LH	\$	17.30

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5523P**AAD2001-040**

1	DOOR HANDLE MODULE FRT LH L70Y	\$	P _h 133.40	}	X
1	DOOR MIRROR ASSY LH	\$	S _h 727.90		
1	DOOR HARNESS WIRE LH	\$	S _h 2,670.00		
1	ROCKER PANEL INNER GARNISH LH	\$	S _h 466.51		
1	ROCKER PANEL INNER LH	\$	N 1,024.79		
1	ROCKER PANEL OUTER LH	\$	N 1,184.99	}	
1	ROCKER PANEL CENTER LH	\$	B 990.25		
1	FENDER PANEL FRT LH	\$	N 414.40	}	X
1	WHEELARCH FRT LH	\$	S _h 112.30		
1	FENDER BRACKET LOWER LH	\$	S _h 11.80		
1	FENDER INSULATOR LH	\$	S _h 65.50		
1	FENDER BRACKET FRT LH	\$	S _h 38.90		
1	BUMPER COVER FRT	\$	S _h 747.20		
1	BUMPER RETAINER FRT LH	\$	S _h 101.40		
1	BUMPER SUPPORT FRT	\$	S _h 10.70		
1	BUMPER SPOILER FRT	\$	S _h 344.70		
1	BUMPER ABSORBER FRT	\$	P _h 394.68		
1	BUMPER UNDERTRAY FRT	\$	S _h 292.50		
1	BUMPER GRILLE LOWER FRT	\$	S _h 147.00		
1	BUMPER FOG LAMP GRILLE LH	\$	S _h 207.21		
1	BUMPER BEAM FRT	\$	P _h 663.70		
1	HEADLAMP LH	\$	S _h 743.60		
1	HEADLAMP PANEL FRT LH	\$	N 127.70		
1	RADIATOR GRILLE	\$	S _h 969.90		
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	S _h 225.36		
1	RADIATOR GRILLE FRAME	\$	S _h 686.00		
1	FRAME FULL SUPPORT PANEL	\$	P _h 592.70		
1	FRAME FULL SUPPORT BRACKET	\$	S _h 41.60		
1	LOWER ARM LH L70Y	\$	S _h 192.70		
1	KNUCKLE ARM LH L70Y	\$	S _h 481.50		
1	ABSORBER FRT LH L70Y	\$	S _h 274.10		
1	DRIVESHAFT LH	\$	S _h 1,355.70		
1	BONNET	\$	N 1,312.70		
1	BONNET STRUT LH	\$	S _h 53.30		
1	BONNET HINGE LH	\$	N 236.50		
1	BONNET LOCK	\$	N 152.80		
1	BONNET CABLE	\$	S _h 55.20		

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5523P**AAD2001-040**

1	BONNET INSULATOR	\$	294.30	} <i>SVLX</i>
1	BONNET SEAL OUTER	\$	83.20	
1	BONNET CABLE COVER	\$	80.60	
1	BUMPER COVER REAR	\$	561.70	
1	BUMPER LOWER REAR	\$	411.90	
1	BUMPER BRACKET SIDE LH REAR	\$	80.80	
1	BUMPER RETAINER LH REAR	\$	54.20	
1	BUMPER REFLECTOR LH	\$	16.60	

TOTAL	\$	29,554.40
10%	\$	2,955.44
	\$	26,598.96

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	<i>na</i> 100.00	<i>X</i>
1	FRONT DOOR STICKER 'Trans-Cab'	\$	<i>na</i> 80.00	<i>60.50</i>
1	FRONT DOOR STICKER 'Classic'	\$	<i>na</i> 80.00	<i>15.50</i>
1	DOOR CHECK BOLT	\$	<i>na</i> 22.69	} <i>X</i>
1	DOOR GUIDE SCREW	\$	<i>na</i> 10.85	
1	DOOR HINGE BOLT	\$	<i>na</i> 10.85	
1	DOOR HINGE NUT LH	\$	<i>na</i> 14.60	
1	DOOR CHECK BOLT	\$	<i>na</i> 22.69	
1	DOOR CHECK NUT	\$	<i>na</i> 3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>na</i> 6.12	
1	REAR LEFT TYRE	\$	<i>sn</i> 330.00	} <i>X</i>
1	REAR LEFT TYRE RIM	\$	<i>sn</i> 380.00	
1	FRONT LEFT TYRE	\$	<i>sn</i> 330.00	
1	FRONT LEFT TYRE RIM	\$	<i>sn</i> 380.00	
1	WHEELARCH CLIP FRT LH	\$	<i>na</i> 30.50	
1SET	BUMPER CLIP FRT	\$	<i>na</i> 66.00	
1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i> 12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i> 10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i> 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>sn</i> 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>sn</i> 30.00	
1SET	Front licence plate with holder	\$	<i>sn</i> 80.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5523P**AAD2001-040**

1SET RADIATOR GRILLE SCREW	\$	nn	16.00	}	X
1SET RADIATOR GRILLE FRAME CLIP	\$	nn	52.00		
6 BONNET INSULATOR CLIP L70Y	\$	nn	7.30		
2 BONNET CABLE CLIP L70Y	\$	nn	6.31		
2 BONNET CABLE COVER SCREW L70Y	\$	nn	10.85		
1SET PARKING AID	\$	nn	700.00		
1SET REAR BUMPER CLIP	\$	nn	66.00		
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00		
1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00		
1SET BUMPER LOWER REAR RIVET	\$	nn	22.00		
1SET BUMPER LOWER REAR CLIP	\$	nn	66.00		
TOTAL	\$		3,136.04		
TOTAL PARTS	\$		29,735.00		

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		7,500.00	600
Putty and spray painting of the affected portion.	\$		7,500.00	600
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	h	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	h	380.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	h	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5523P**AAD2001-040**

To transfer of Front Fender fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of Front Bumper fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of Front Door fittings, attachment and perform water seepage test.	\$		170.00	601
To Check Electrical Lighting Concerned.	\$		170.00	201
To rust-proofing of the affected areas.	\$		170.00	301
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn	380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	4	380.00	X
To transfer of Front Bonnet fittings, attachment and perform water seepage test.	\$	4	170.00	X
To reinstall rear bumper parking sensor.	\$	4	170.00	X
To transfer of Rear Bumper fittings, attachment and perform water seepage test.	\$	4	170.00	X

TOTAL \$ 18,440.00**Over All Total \$ 48,175.00**

LKK Auto Consultants hence notify the Repairer of the following.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LUMP SUM (REPAIR DAY)**25 DAYS****4 days**