

Surveyor:

Marcus

DOI:

14/1/2020

Date / Time:

14/1/2020

Registered in Merimen:

14/1/2020

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLC 4692T

Claim No.:

Name of Insured:

Nor Rashidi Bin Mohamad

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A:

30/11/19

Place of Accident:

Is driver the owner?

(YES) NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) YES / NO

OI GIA REPORT YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

FBH 2317H



INSRS:

WSP: Hua Ho

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

FBH 2317H : X ; SLC 4692T : X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

1W. W

(\$25 x 4

days)

Loss of Income (LOI):

S\$

(\$

x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Hua Ho Trading

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

S\$500.00

COPY SENT
23/3/2020

02/11/15 wet
ASS. REC. BY: Marcus

REF:

FWD / 16/2/15/3

ASSIGNMENT

From: Date:
Estimated Cost:
OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBH 2317H
at Workshop m/s hws hws

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 3800

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

LTA 614

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBH 2317H Yr Regn: 4, 13
Type: M.Car / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Yanche Jupiter C.C. 134

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 82391 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MH3555 002CK 101857

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90-17

R: 80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Swallow

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. mm L/Bal. mm

D.O.A. 30/1/19 D.O.I. 14/1/20

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

O/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/1/20 next 3/86
confirmed 4/5 @ 1050 with Repair

(Reel # 1194/ 534.)

Date/Time. File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time. File Return to?

Transportation:

2)

Add Fee:

☐ : Site Insp (\$

) \$ + RS \$

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

HUA HO TRADING

Dear Sir,

Items	Price	
Front Fender	\$86	Cut ✓
Under Bracket	\$68	See α
Front Fork	\$560	n x
Foot Rest Bar	\$38	31 ✓
Rear Brake Paddle	\$46	21 ✓
Front Side Light Left	\$36	Can ✓
Front Side Light Right	\$36	Can ✓
Front Number Plate	\$14	Reed 10 S.N
Rear Number Plate	\$28	Reed 10 S.N
Rear Muggard	\$86	To go ✓
Brake Lever	\$16	Cut ✓
Rear Box	\$200	Cut 150 S.N
Exhaust Pipe Protector	\$60	n x
Right Side Panel	\$48	Cut ✓
Headlight Cover	\$65	Cut ✓
Headlight	\$158	Cut ✓
Mirror 1 Set	\$70	Cut ✓
Handle Bar End (Boltmeter)	\$85	See ✓
Handle Bar	\$88	Reed ✓
Central Bracket	\$30	31 ✓
Front Signal Light Panel	\$48	Can ✓
Foot Rest Rubber	\$28	To go ✓
Towing Fee	\$50	+ 35
Labor Charge	\$300	✓ 250
Total	\$2244	

$$\begin{array}{r} 964 \\ 107 \\ \hline 867.60 \\ 13226 \\ 1058. \end{array}$$

not about
you

d/s \$ 1050 |
Kings Park After regon.
Hahn.
18/1/20
Tel. 6286356/

[> Back to OneMotoring](#)

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.

FBH2317H

Make / Model

YAMAHA / JUPITER 135 MANUAL

Vehicle Type :

P00 - Passenger

Motorcycle/Autocycle/Moped

Vehicle Attachment 1 :

No Attachment

Vehicle Scheme :

Normal

Chassis No. :

MH355S002CK101957

Propellant :

Petrol

Engine No. :

55S101949

Motor No. :

-

Engine Capacity :

134 cc

Power Rating :

-

Maximum Power Output :

-

Maximum Laden Weight :

217 kg

Unladen Weight :

111 kg

Year Of Manufacture :

2012

Original Registration Date :

12 Apr 2013

Lifespan Expiry Date :

-

COE Category :

D - Motorcycle

Quota Premium :

\$1,895.00

COE Expiry Date :

11 Apr 2023



(/listing/usedbike/yamaha-yamaha-jupiter-mx135/15332/)

SGD\$3200

Reg : 03/09/2012

Type: Cubs

134cc

1 Owner. Posted Overseas, Good And Cheap.

Posted on : 17/12/2019

★ PAID AD ★ DEALER AD

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-JUPITER-MX135/15332/) ■ COMPARE

Yamaha Jupiter MX135 (/listing/usedbike/yamaha-yamaha-jupiter-mx135/15662/)



(/listing/usedbike/yamaha-yamaha-jupiter-mx135/15662/)

Reg : 19/02/2013

Type: Cubs

134cc

Many Other Brand New And Used Motorcycles Available. Come Visit Us At Ban Hon Brothers (Agencies) Pte Ltd.
Block 5022, Ang Mo Kio Industrial Park 2 #01-19 Singapore 569525.

1 Owner. See To Believe. Very Well Maintained.

Posted on : 11/01/2020

★ PAID AD ★ DEALER AD

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-JUPITER-MX135/15662/) ■ COMPARE

Yamaha Jupiter MX135 (/listing/usedbike/yamaha-yamaha-jupiter-mx135/15645/)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	182Z
Vehicle Details	
Vehicle No.:	FBH2317H
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2020
Vehicle Make:	YAMAHA
Vehicle Model:	JUPITER 135 MANUAL
Primary Colour:	Black
Secondary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	55S101949
Chassis No.:	MH355S002CK101957
Maximum Power Output:	-
Open Market Value:	\$1,679.00
Original Registration Date:	12 Apr 2013
First Registration Date:	12 Apr 2013
Transfer Count:	2
Actual ARF Paid:	\$252.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Apr 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,895.00
COE Rebate Amount:	\$614.00
Total Rebate Amount:	\$614.00

The information contained herein is correct as at 15 Jan 2020

OK

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Tuesday, 14 January 2020 9:26 AM
To: 'admin-d@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: motorclaims.sg@fwd.com; josey.loh@fwd.com
Subject: Accident between FBH2317H & SLC4692T ON 30.11.2019 CLAIM REF: 1201900037629

Sur: March 5

P: Mdm Thing

T: 100.m 14.1.2020

V: In

G: ✓

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Kindly upload all correspondence emails/documents sent to you into Merimen.


Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Venessa Chan - SGUser
Sent: Tuesday, January 14, 2020 9:25 AM
To: 'huaho trading'
Cc: Motor Claims SG - SG Common
Subject: Accident between FBH2317H & SLC4692T ON 30.11.2019 CLAIM REF: 1201900037629

Hi Sir/Madam,

Thank you for your selection of LKK Auto Consultants.
We will proceed to assign survey.

Thank you.

Best Regards,

Venessa Chan




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: huaho trading [<mailto:huahotrading@yahoo.com.sg>]

Sent: Monday, January 13, 2020 9:52 AM

To: Venessa Chan - SGUser

Subject: Re: Accident between FBH2317H & SLC4692T ON 30.11.2019 CLAIM REF: 1201900037629

Dear Sir/Mdm,

We have chosen LKK.

Thank you!

Best Regards
Hua Ho Trading

On Friday, 10 January 2020, 05:30:52 PM SGT, venessa.chan@fwd.com <venessa.chan@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Sir/Madam,

Refer to your email dated on 10.01.2020 of the PRI Notice of your client's vehicle FBH2317H;

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.

Best Regards,

Venessa Chan
Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: huaho trading [<mailto:huahotrading@yahoo.com.sg>]
Sent: Friday, 10 January 2020 4:48 PM
To: Claims SG - SG Common
Subject: Accident between FBH2317H & SLC4692T

Dear Sir/Mdm,

Attached is the accident report between FBH2317H & SLC4692T, Kindly send over a surveyor to the b/m address.

Hua Ho Trading

Blk 6 Defu Lane 10

#01-540 SE 539187

Tel No:62844487 Fax No: 6289 8180

Thank you!



Best Regards

Hua Ho Trading

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments. Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments. Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Claim Audit

AUDIT TRAIL					
No.	On	Audit	Remarks	By	
1	14 Jan 2020 15:22	Cim Dtl Modified	Claimant's Name: -> -.	[A] Lee Su Li	
2	14 Jan 2020 15:22	Cim Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	[A] Lee Su Li	
3	14 Jan 2020 15:22	Cim Created	Reg No: FBH2317H, Acct Date: 2019/11/30, Claim Type: TP, Insurer: FWD Singapore Pte. Ltd. (HQ), Wor kshop: Hua Ho Trading (HQ)	[A] Lee Su Li	
4	14 Jan 2020 15:22	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lee Su Li	
5	14 Jan 2020 15:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/01/23	[A] Lee Su Li	
6	14 Jan 2020 15:22	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Lee Su Li	
7	14 Jan 2020 15:22	Label Added	(20005):Direct Settlement .	[A] Lee Su Li	
8	14 Jan 2020 15:22	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lee Su Li	
9	14 Jan 2020 15:59	Cim Registration Modified	Pol No:->PNPV2017-00003602-02.	[I] Venessa Chan	
10	14 Jan 2020 15:59	Cim Registration Modified	Excess: -> 500.00.	[I] Venessa Chan	
11	14 Jan 2020 15:59	Cim Registration Modified	Acct Time:00:00:00->15:00:00, Pol No:PNPV2017-00003602-02->PNPV2017-00003602.	[I] Venessa Chan	
12	17 Jan 2020 08:48	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/01/23	[A] CHEW HSIAO TONG	
13	22 Jan 2020 16:47	Cim Veh Model Changed	(206086) -> (204563) YAMAHA JUPITER LC135 135cc.	[A] SHIAU CHAN	
14	22 Jan 2020 16:50	Adj Rpt Initiated		[A] SHIAU CHAN	
15	22 Jan 2020 16:50	Cim Dtl Modified	Claim Conclusion: -> 3.	[A] SHIAU CHAN	
16	22 Jan 2020 16:50	Cim Dtl Modified	JPJ Reg, Date: -> 2013/04/12.	[A] SHIAU CHAN	
17	22 Jan 2020 16:50	Cim Details Notified		[A] SHIAU CHAN	
18	11 Feb 2020 15:59	Adj Mandate Request	Cur.Reg:1150.00;LIABILITY: 100%(BOLA 15) QUANTUM: (a) COR: \$1,050.00 + (b) LOU: \$100.00 (4day s x \$25) Total: a+b = \$1,150.00 *VEH MODEL: Yamaha Jupitor (134cc), FOR YOUR APPROVAL/INSTRUC TION.	[A] CHEW HSIAO TONG	

Date FromDate ToAudit Type

None

Go

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Ref no	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2406675	14 Jan 2020 15:59:19	TP Case (Insurer)	Motor	FWD Singapore Pte. Ltd. (HQ)	FWD Singapore Pte. Ltd. (HQ)	FBH2317H	NOR RASHIDI BIN MOHAMAD	xx.xx
2410100	17 Jan 2020 08:48:42	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	FBH2317H	SLC4692T	11.77

Print Received Message

This mail is associated with :

***FBH2317H (1201900037629)**

[SLC4692T]

TP

TAN CHIN KEE

Nov 30 2019 3:00PM

[NOR RASHIDI BIN MOHAMAD]

Hua Ho Trading

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 24/02/2020 13:20 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1150.00) - FBH2317H - Claim Handler: Josey Loh

Approved:1150.00.

Hsiao Tong (LKKAUTO)

From: huaho trading <huahotrading@yahoo.com.sg>
Sent: Thursday, 19 March 2020 2:24 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: Your Ref: FBH2317H // Our Ref: CC4/FWD20000862/Ups3 [ACCIDENT INVOLVING SLC 4692T(FWD) AND FBH 2317H ON 30/11/2019]
Attachments: doc03182120200319141237.pdf

Dear Sir/Mdm,

Attached as per requested. Kindly send over the cheque

Thank you!

On Sunday, 8 March 2020, 03:46:07 PM SGT, Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Your Ref: **FBH2317H**

Our Ref: CC4/FWD20000862/Ups3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SLC 4692T(FWD) AND FBH 2317H ON 30/11/2019

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 1,050.00
2. Loss of Use (4days x \$25.00)	\$ 100.00
Total	\$ 1,150.00

If our offer is acceptable by your client, please duly sign the documents enclosed and return to us (LKK) for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)
Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Dec 2019 <a>Edit Reg		14 Jan 2020 00:00 <a>Edit Adj Rpt	S\$1,050.00 <a>Edit Estimates	S\$1,050.00 <a>View Rpt		Pending for Survey Report <a>Cancel Case

Main

Reference

Claims Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

NOR RASHIDI BIN MOHAMAD, ID: S7423899H

Main Claimant:

TAN CHIN KEE, ID: S2655182Z

Vehicle Reg. No.:

FBH2317H

Date of Loss:

30/11/2019 15:00 - :59
[79 Months and 18 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 1201900037629

Policy/Cover Note No.:

PNPV2017-00003602 (Comprehensive)
Coverage: 16/05/2019 - 15/05/2020

Vehicle Reg. No. (Insured):

SLC4692T

Policy No. (Claimant):

Excess:

S\$500.00

Repairer:

Hua Ho Trading (HQ) Blk 6 Defu Lane 10, #01-540 Defu Industrial Estate Park C, 539187 Defu Lane - Tel: 62844487

Handling Insurer:

FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/01/2020]

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

• FWD_5G (24/02/2020): Alert - Adj Mandate Approved (S\$1150.00) - FBH2317H - Claim Handler: Josey Loh

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

Claim Documents

*FBH2317H (1201900037629)
[SLC4692T]
TP
TAN CHIN KEE
Nov 30 2019 3:00PM
[NOR RASHIDI BIN MOHAMAD]
Hua Ho Trading

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit

Assessment Reports

































1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/20 08:48	Adjuster Immediate Advice		Load HTM

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/20 18:05	Odometer Reading		Load JPG
2	14/01/20 18:07	General View		Load JPG
3	14/01/20 18:07	General View		Load JPG
4	14/01/20 18:07	General View		Load JPG
5	14/01/20 18:07	General View		Load JPG
6	14/01/20 18:07	General View		Load JPG
7	14/01/20 18:07	General View		Load JPG
8	14/01/20 18:07	General View		Load JPG
9	14/01/20 18:07	General View		Load JPG
10	14/01/20 18:07	General View		Load JPG
11	14/01/20 18:07	General View		Load JPG
12	14/01/20 18:07	General View		Load JPG
13	14/01/20 18:07	General View		Load JPG
14	14/01/20 18:07	General View		Load JPG
15	14/01/20 18:07	General View		Load JPG
16	14/01/20 18:07	General View		Load JPG
17	14/01/20 18:07	General View		Load JPG
18	14/01/20 18:07	General View		Load JPG
19	14/01/20 18:07	General View		Load JPG
20	14/01/20 18:07	General View		Load JPG
21	14/01/20 18:08	General View		Load JPG
22	14/01/20 18:08	General View		Load JPG
23	14/01/20 18:08	General View		Load JPG
24	14/01/20 18:08	General View		Load JPG
25	14/01/20 18:08	General View		Load JPG
26	14/01/20 18:08	General View		Load JPG
27	14/01/20 18:08	General View		Load JPG
28	14/01/20 18:08	General View		Load JPG
29	14/01/20 18:08	General View		Load JPG
30	14/01/20 18:08	General View		Load JPG
31	14/01/20 18:08	General View		Load JPG
32	14/01/20 18:08	General View		Load JPG
33	14/01/20 18:08	General View		Load JPG
34	14/01/20 18:08	General View		Load JPG
35	14/01/20 18:08	General View		Load JPG
36	14/01/20 18:08	General View		Load JPG

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
49	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
50	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
51	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
52	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
53	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
54	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
55	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
56	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
57	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
58	14/01/20 18:08	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/20 15:22	EMAIL FROM FWD DD14012020	 Load PDF	
2	14/01/20 15:22	EMAIL FROM FWD TO OI DD14012020	 Load PDF	
3	15/01/20 14:32	TP ESTIMATE-MARKED	 Load PDF	
4	15/01/20 14:32	TP GIA REPORT	 Load PDF	
5	05/02/20 15:32	WORKSHOP INVOICE	 Load PDF	
6	11/02/20 15:50	Authorisation to Act	 Load PDF	
7	26/03/20 11:15	Release Voucher	 Load PDF	
8	26/03/20 11:15	LOD	 Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	14/01/20 16:00	SLC4692T OI GIA	 Load PDF	
2	14/01/20 16:00	FBH2317H TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SLC4692T (Insd veh)	Model:	YAMAHA JUPITER LC135
	FBH2317H (TP veh)		135CC
Date of Accident:	30/11/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	2,244.00
Final Repair Cost	:	\$	1,050.00
Loss of Use	:	\$	100.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,150.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability <u>100</u> (%)			
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hua Ho Trading	:	\$ 1,150.00
2)		:	\$

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

26 Mar
2020
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20000862/UPS3Q2

Date: 26/03/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00003602

Claimant Vehicle No : FBH2317H Insured Vehicle No : SLC4692T

Date of Loss: 30/11/2019 Nature of Claim: TP Claim No: 1201900037629

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBH2317H
 Make & Model: YAMAHA JUPITER LC135, 135cc Engine No: 55S101949
 Reg. Date: 12/04/2013 (Man. Year: 2012) Chassis No: MH355S002CK101957
 Colour: Black Odometer: 82391 km
 Engine Capacity: 134 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 80/90-17
 Front Left Side: Swallow 6 mm Rear Left Side: Swallow 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,894.00	1,037.60	856.40	45.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	285.00	65.00	18.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,244.00	1,322.60	921.40	41.06
Approved Total (Overridden) (S\$)		1,050.00		
Nett Amount (S\$)	2,244.00	1,050.00	1,194.00	53.21
+ Loss of Use (4.0 x S\$25.00/day) (S\$)		100.00		
Nett Liability (S\$)		1,150.00		

INSPECTION

Date of Assignment: 14/01/2020

Date Inspected: 14/01/2020 Inspected At:

Hua Ho Trading (HQ)
 Blk 6 Defu Lane 10, #01-540 Defu
 Industrial Estate Park C
 Singapore 539187

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Jan 2020)	
Parts:	N/A	YAMAHA JUPITER LC135 135cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH2317H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	86.00 F	*86.00 FL
2	1		*UNDER BRACKET	Serviceable	68.00 F	*. FL
3	1		*FRONT FORK	Repair	560.00 F	*. FL
4	1		*FOOT REST BAR	Bent	38.00 F	*38.00 FL
5	1		*REAR BRAKE PADDLE	Bent	46.00 F	*46.00 FL
6	1		*FRONT SIDE LIGHT LEFT	Cracked	36.00 F	*36.00 FL
7	1		*FRONT SIDE LIGHT RIGHT	Cracked	36.00 F	*36.00 FL
8	1		*REAR MUGGARD	Torn	86.00 F	*86.00 FL
9	1		*BRAKE LEVER	Cut	16.00 F	*16.00 FL
10	1		*EXHAUST PIPE PROTECTOR	Repair	60.00 F	*. FL
11	1		*RIGHT SIDE PANEL	Cut	48.00 F	*48.00 FL
12	1		*HEADLIGHT COVER	Cut	65.00 F	*65.00 FL
13	1		*HEADLIGHT	Cut	158.00 F	*158.00 FL
14	1		*SET MIRROR	Cut	70.00 F	*70.00 FL
15	1		*HANDLE BAR END (BOLTMETER)	Scratched	85.00 F	*85.00 FL
16	1		*HANDLE BAR	Bent	88.00 F	*88.00 FL
17	1		*CENTRAL BRACKET	Bent	30.00 F	*30.00 FL
18	1		*FRONT SIGNAL LIGHT PANEL	Cracked	48.00 F	*48.00 FL
19	1		*FOOT REST RUBBER	Torn	28.00 F	*28.00 FL
20	1		*FRONT NUMBER PLATE	Bent	14.00 FS	*10.00 FS
21	1		*REAR NUMBER PLATE	Bent	28.00 FS	*10.00 FS
22	1		*REAR BOX	Cut	200.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,894.00	1,134.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	96.40
Total Parts (S\$)	1,894.00	1,037.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE.	New	50.00	35.00
2	LABOUR CHARGE.	New	300.00	250.00
Gross Labour Cost (\$\$)			350.00	285.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >