

和 好 貿 易

HUA HO TRADING

新加坡德福工業區C德福十巷大牌6號門牌#01-540

Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,

Singapore 539187, Tel: 62844487 Fax: 62898180

Dear Sir,

Estimate cost repair for the accident motorcycle Vehicle No: Fbh23174

Items	Price
Front Fender	\$86 <i>cut ✓</i>
Under Bracket	\$68 <i>cut ✓</i>
Front Fork	\$560 <i>cut ✓</i>
Foot Rest Bar	\$38 <i>cut ✓</i>
Rear Brake Paddle	\$46 <i>cut ✓</i>
Front Side Light Left	\$36 <i>cut ✓</i>
Front Side Light Right	\$36 <i>cut ✓</i>
Front Number Plate	\$14 <i>cut 10 S.N</i>
Rear Number Plate	\$28 <i>cut 10 S.N</i>
Rear Muggard	\$86 <i>cut ✓</i>
Brake Lever	\$16 <i>cut ✓</i>
Rear Box	\$200 <i>cut 150 S.N</i>
Exhaust Pipe Protector	\$60 <i>cut ✓</i>
Right Side Panel	\$48 <i>cut ✓</i>
Headlight Cover	\$65 <i>cut ✓</i>
Headlight	\$158 <i>cut ✓</i>
Mirror 1 Set	\$70 <i>cut ✓</i>
Handle Bar End (Boltmeter)	\$85 <i>cut ✓</i>
Handle Bar	\$88 <i>cut ✓</i>
Central Bracket	\$30 <i>cut ✓</i>
Front Signal Light Panel	\$48 <i>cut ✓</i>
Foot Rest Rubber	\$28 <i>cut ✓</i>
Towing Fee	\$50 <i>+</i> <i>35</i>
Labor Charge	\$300 <i>✓</i> <i>250</i>
Total	\$2244

(102)

*964
107
867.60
13226
1058.*

Not Acknowledged

*1050
d/s
Whip lobs After repair*

*18/1/20
Tel. 62863561*

HUA HO TRADING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: