

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

20-Jan-20

## ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHC 6791 A

1 pc	o/s mirror assy <i>cra</i>		\$	911.60
		Less 20%	\$	182.32
			\$	729.28
	Sundry <i>Xnr</i>		\$	50.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.		\$	150.00 <i>\$80</i>
	To putty and spray painting on o/s side mirror		\$	150.00 <i>\$80</i>
			\$	1,079.28

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Rqm (LKK)*  
*3/02/2020 1130hrs*  
*ParaSuran @ LKKauto.com*  
*88622778* *(P/P)*  
*1 repair day*  
*Bel paint photo*