

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

To: Sangh, Jan

20-Jan-20

## ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHC 6791 A

1 pc	o/s mirror assy		\$	911.60
		Less 20%	\$	182.32
			\$	729.28

Sundry		\$	50.00
--------	--	----	-------

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.

\$	150.00	\$80
----	--------	------

To putty and spray painting on o/s side mirror

\$	150.00	\$80
\$	1,079.28	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Ram (LKK)  
3/02/2020 1130hrs  
Parasuram @ LKKauto.com  
88622778 P/P  
1 Repair day  
BEL paint photo  
P/P : \$889.28  
1 Repair day