



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

GBH 3379 Y

Not Authorized

Parts	(a) Cost / List Price Items	
	Plus/Less	
	Total of Cost / List	
	(b) Nett Price Items	\$ 3,367.20
	Less 10%	\$ 336.72
	Total of Nett Item	\$ 3,030.48
	(c) Special Nett Items	\$ 45.00
Total Parts Cost		\$ 3,075.48
Labour		\$ 2,080.00
Total		\$ 5,155.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	<u>Kennerly</u>
Company	:	<u>LKK</u>
Survey conducted on	:	<u>14/1/2020</u> at <u>11.35am</u>
<u>Remarks By Surveyor</u>		
(a)	The repair of this vehicle is <u>not</u> authorized / is not authorized until further notice.	
(b)	Recommended Days of Repair	: <u>03</u> day(s)
(c)	Resurvey	: Required / <u>Not</u> Required
(d)	Excess	:\$ _____
(e)	Signature of surveyor	: <u>Le</u> Date: <u>14/1/2020</u>



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE L

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com

Spare Parts

Vehicle No. : **GBH 3379 Y**
Make & Model : **NISSAN NV200**
Chassis No : **VSKYBAM20Z0157204**

Submit By : _____
Year Manufacture : _____
Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price
1	Front number plate <i>h</i>	1	\$45.00	S.N X
2	Bonnet <i>h</i>	1	\$782.90	N X
3	Bonnet lock <i>h</i>	1	\$65.50	N X
4	Bonnet hinge LH <i>h</i>	1	\$55.50	N X
5	Bonnet hinge RH <i>h</i>	1	\$55.50	N X
6	Headlamp LH	1	\$363.80	N 7
7	Headlamp RH	1	\$363.80	N 7
8	Front support panel (complete) <i>h</i>	1	\$623.80	N X
9	Front bumper	1	\$536.60	N 7
10	Front bumper clip	10	\$55.00	N 7
11	Front bumper side retainer LH <i>h</i>	1	\$30.90	N X
12	Front bumper side retainer RH <i>h</i>	1	\$30.90	N X
13	Front bumper grille <i>h</i>	1	\$338.00	N X
14	Front bumper lower chrome	1	N/A	
15	Front emblem <i>h</i>	1	\$65.00	N X
16				
17				
18				
19				
20				
21				
22				
23				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

