

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26086

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0046/2020/NS
Date : 13-Jan-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

*7 days exclude 1 Sunday - ok
jb 9 Mar 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Seow Yen Choon Kelvin
Address : 84 St Patrick's Road
#01-39
Singapore 424183
Telephone : HP +65 83687687
Type of Claim : Own Damage Claims
Policy No. : 1800098325-01
Vehicle No : **SKE 6183 J**
Model Code : Audi A6 1.8 TFSI S -Tronic
Model / Year : 8/17/2018
Engine No : CYG 023275
Chassis No : WAUZZZ4G3JN036761
Mileage : 25712
Date In : 13-Jan-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jan-20
Place of Accident : ECP Slip Road Onto MCE Entrance

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 6183 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow vehicle from accident scene.	S/N \$ 280.00	
2	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
3	To remove and renew aircond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,400.00	\$ 1,400.00
4	To dismantle and renew front bumper, both headlights and bonnet. Renew front lock csrrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 5,600.00	\$ 2,750.00
SUB TOTAL LABOUR CHARGES		: \$ 7,760.00	\$ 4,630.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 6183 J

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
		<i>c/f</i>		\$ 4,630.00
5	To respray front bumper, front bumper lower spoiler, hinges, both front fender and bonnet.	\$	5,300.00	\$ 2,200.00
6	To renew and configure both front bumper and radar sensor.	S/N \$	280.00	\$ 280.00
7	<i>Added labour - see attached</i>	\$	2,000.00	\$ 500.00
8	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 15,532.00</u>	<u>\$ 7,802.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 6183 J

S/N	Parts Description		<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remarks</u>
1	FRONT BUMPER		\$ 2,787.00	\$ 2,229.60
2	FRONT BUMPER FIXING PARTS		\$ 491.00	
3	FRONT BUMPER GRILLE - LOWER CENTRE		\$ 116.00	
4	LOCKING CLIP	14	\$ 51.00	\$ 40.32
5	FRONT BUMPER ADAPTER - LH / RH	2	\$ 68.00	
6	FRONT BUMPER CLOSING ELEMENT		\$ 199.00	
7	FRONT BUMPER SPOLER		\$ 227.00	
8	FRONT BUMPER SPOILER TRIM		\$ 860.00	
9	RADIATOR GRILLE		\$ 1,766.00	\$ 1,412.80
10	RADIATOR GRILLE COVER		\$ 33.00	\$ 26.08
11	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRON	2	\$ 122.00	\$ 96.96
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 1,034.00	
13	AIR GUIDE GRILLE COVER - LH / RH	2	\$ 92.00	
14	FRONT WHEEL SPOILER - LH / RH	2	\$ 484.00	
15	HEADLIGHT COVER CAP - LH / RH	2	\$ 104.00	
16	FRONT BUMPER SIDE REINFORCEMENT BEAM		\$ 754.00	\$ 602.80
17	FRONT BUMPER FOAM FILLER PIECE		\$ 215.00	\$ 172.00
18	FRONT BUMPER BRACKET HOLDER - LH / RH	2	\$ 474.00	\$ 378.40
19	FRONT BUMPER COVER		\$ 112.00	\$ 89.20
20	FRONT BUMPER SUPPORT	2	\$ 23.00	\$ 17.92
SUB TOTAL SPARE PARTS		:	<u>\$ 10,012.00</u>	<u>\$ 5,066.08</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 6183 J

S/N	Parts Description		<u>Damaged Parts & Prices</u>		
			S/Nett	Remarks	
		<i>c/f</i>		\$	5,066.08
21	AIRCON STICKER	NEC	\$ 18.00	\$	14.00
22	CAUTION SIGN STICKER	NEC	\$ 13.00	\$	9.76
23	FRONT PARKING AID SENSOR - INNER	2	\$ 419.00		
24	FRONT PARKING AID SENSOR - OUTER	2	\$ 462.00		
25	FRONT BUMPER WIRING SET		\$ 532.00		
26	SIGNAL HORN - LH LOW TONE		\$ 262.00		
27	SIGNAL HORN - RH HIGH TONE		\$ 215.00		
28	SPRING SHACKLE - LH / RH	2	\$ 86.00		
29	BONNET		\$ 4,965.00	\$	3,972.00
30	BONNET ATTACHMENT PARTS		\$ 161.00		
31	BONNET LID HINGE - LH / RH	2	\$ 292.00		
32	BONNET GAS FILLED STRUT	2	\$ 217.00		
33	BONNET CATCH HOOK		\$ 127.00		
34	BONNET LOCK BAR	2	\$ 90.00		
35	BONNET CATCH HOOK		\$ 16.00		
36	BONNET LID LOCK	2	\$ 391.00		
37	HOOD MICRO SWITCH	2	\$ 133.00		
38	BONNET BOWDEN CABLE - CENTRE		\$ 53.00		
39	BONNET LID LOCK CABLE		\$ 67.00		
40	HEADLIGHT MOUNTING - LH / RH	2	\$ 214.00	\$	171.20
SUB TOTAL SPARE PARTS		:	\$ 8,733.00	\$	9,233.04

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 6183 J

S/N	Parts Description			<u>Damaged Parts & Prices</u>	
				<u>S/Nett</u>	<u>Remarks</u>
		<i>c/f</i>			\$ 9,233.04
41	LED HEADLIGHT - LH / RH	2	\$	17,214.00	\$ 13,771.20
42	DIPPED BEAM POWER MODULE		\$	508.00	
43	DAY DRIVING LIGHTS POWER MODULE		\$	520.00	\$ 415.60
44	HEADLAMP FANS - RH		\$	363.00	
45	HEADLAMP REPAIR KIT - RH		\$	31.00	
46	HEADLAMP ASSEMBLY SPACER	2	\$	77.00	
47	HEADLAMP ASSEMBLY ADJUSTER		\$	42.00	
48	HEADLAMP HOSE		\$	38.00	
49	HEADLAMP BRACKET		\$	26.00	
50	LIFT CYLINDER - LH / RH	2	\$	432.00	
51	HEADLIGHT HOSE		\$	426.00	
52	LOCK CARRIER		\$	1,140.00	\$ 912.00
53	COOLANT REGULATOR SUPPORT	2	\$	67.00	
54	EXTERNAL TEMPERATURE SENSOR		\$	57.00	
55	ETEMPERATURE SENSOR BRACKET		\$	21.00	
56	AIRCON CONDENSER		\$	689.00	\$ 551.20
57	HIGH PRESSURE SAFETY SWITCH VALVE		\$	48.00	
58	PRESSURE SENDER		\$	175.00	
59	RADIATOR		\$	775.00	\$ 632.80
60	RADIATOR RUBBER BUSH - UPPER	2	\$	12.00	\$ 9.92
SUB TOTAL SPARE PARTS		:	\$	22,661.00	\$ 25,525.76

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 6183 J

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remarks
		<i>c/f</i>			\$ 25,525.76
61	RADIATOR RUBBER BUSH - CENTRE	2	\$	18.00	\$ 14.56
62	RADIATOR RUBBER BUSH - LOWER	2	\$	24.00	\$ 19.36
63	READY MIX COOLANT	4	\$	84.00	\$ 67.20
64	CHARGE AIR COOLER		\$	513.00	
65	PRESSURE HOSE - RH		\$	320.00	
66	PRESSURE HOSE - LH		\$	150.00	
67	RADIATOR TWIN FAN RING		\$	237.00	
68	RADIATOR FAN		\$	811.00	
69	RADIATOR FAN		\$	700.00	
70	RADIATOR AIR GUIDE - LH / RH	2	\$	50.00	\$ 41.28
71	RADIATOR COVER - UPPER CENTRE		\$	27.00	
72	RADIATOR SEALING STRIP		\$	21.00	
73	RADIATOR AIR GUIDE - RH FRONT		\$	24.00	\$ 18.64
74	RADIATOR INTAKE AIR DUCT - RH FRONT		\$	79.00	
75	RADIATOR AIR FILTER		\$	266.00	
76	RADIATOR AIR INTAKE HOSE		\$	150.00	
77	RADAR SENSOR COVER FRAME - RH		\$	12.00	
78	RADAR SENSOR COVERFRAME - LH		\$	12.00	
79	DISTANCE REGULATION CONTROL UNIT - RH		\$	6,177.00	
80	DISTANCE REGULATION CONTROL UNIT - LH		\$	5,432.00	
81	FENDER STONE GUARD FILM - LH / RH	2	\$	220.00	\$ 176.00
82	FRONT NO PLATE	S/N	\$	40.00	\$ 40.00
83	Added parts - see attached		\$	1,310.00	\$ 1,048.00
84	SUNDRIES		\$	500.00	\$ 20.08
TOTAL SPARE PARTS			:	\$ 58,583.00	\$ 26,970.88
TOTAL LABOUR CHARGES			:	\$ 15,532.00	\$ 7,802.00
GRAND TOTAL			:	\$ 74,115.00	\$ 34,772.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0046/2020/NS 21-Jan-20 Glory Tan 1 of 1 SKE 6183 J Audi A6 1.8 TFSI S -Tronic
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Rhs front fender	\$ 1,310.00	\$ 1,048.00
		\$ 1,310.00	\$ 1,048.00
<u>Labours</u> 1	To remove and renew rhs front fender.	\$ 1,200.00	\$ 500.00
2	To repair lhs front fender.	\$ 800.00	
	Labour total	\$ 2,000.00	\$ 500.00
	Part total	\$ 1,310.00	\$ 1,048.00
	TOTAL	\$ 3,310.00	\$ 1,548.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant