

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: **S8017684H**
Name: **SEOW YEN CHOON KELVIN**
(XIAO YUANJUN KELVIN)

Birth Date: **03 Jun 1980**
Issue Date: **02 Jan 2003**

 000076310D




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

PASS DATE

18 Jan 2001

NP 428A





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder	: SEOW YEN CHOON KELVIN (XIAO YUANJUN KELVIN	Vehicle No.	: SKE6183J
Period of Insurance	: 17 Aug 2019 To 16 Aug 2020	Policy No.	: 1800098325-01
Engine No.	: CYG 023275	Endorsement No.	:
Chassis No.	: WAUZZZ4G3JN036761	Issued Date	: 16 Jul 2019

ABOUT THE COVER

Make/Model	: AUDI A6 1.8 TFSI ULTRA		
Engine Capacity/Tonnage	: 1,798.00 CC	Sum Insured	: Market Value
Driver Restriction	: NA	Off Peak Car	: No
First Year of Registration	: 2018		
Insuring with COE/PAF	: Yes		

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

SEOW YEN CHOON KELVIN (XIAO YUANJUN KELVIN) - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125207

PREMIUM LEASING - SLEE

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

Manile

1002398707AC4

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26086

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0046/2020/NS
Date : 13-Jan-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Seow Yen Choon Kelvin
Address : 84 St Patrick's Road
#01-39
Singapore 424183
Telephone : HP +65 83687687
Type of Claim : Own Damage Claims
Policy No. : 1800098325-01
Vehicle No : **SKE 6183 J**
Model Code : Audi A6 1.8 TFSI S -Tronic
Model / Year : 17/8/2018
Engine No : CYG 023275
Chassis No : WAUZZZ4G3JN036761
Mileage : 25712
Date In : 13-Jan-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jan-20
Place of Accident : ECP Slip Road Onto MCE Entrance

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 6183 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow vehicle from accident scene.	S/N \$ 280.00	X
2	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
3	To remove and renew aircond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,400.00	✓
4	To dismantle and renew front bumper, both headlights and bonnet. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 5,600.00	1500 (Without Lock Carrier) ✓ 2750 (With Lock Carrier)
SUB TOTAL LABOUR CHARGES		: \$ 7,760.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 6183 I

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To respray front bumper, front bumper lower spoiler, hinges, both front fender and bonnet. X X X X	\$ 5,300.00	1100 2200
6	To renew and configure both front bumper and radar sensor.	S/N \$ 280.00	✓
7	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 13,532.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 61831

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
1	FRONT BUMPER <i>distilled</i>	\$	2,787.00	✓ 2229.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	491.00	+
3	FRONT BUMPER GRILLE - LOWER CENTRE <i>not new</i>	\$	116.00	+
4	LOCKING CLIP <i>new</i>	14 \$	51.00	? ✓ 40.32
5	FRONT BUMPER ADAPTER - LH / RH <i>new</i>	2 \$	68.00	? X
6	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$	199.00	? X
7	FRONT BUMPER SPOLER <i>new</i>	\$	227.00	+
8	FRONT BUMPER SPOILER TRIM <i>new</i>	\$	860.00	+
9	RADIATOR GRILLE <i>new</i>	\$	1,766.00	✓ 1412.80
10	RADIATOR GRILLE COVER <i>new</i>	\$	33.00	✓ 26.08
11	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT <i>new</i>	2 \$	122.00	? ✓ 96.96
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 \$	1,034.00	+
13	AIR GUIDE GRILLE COVER - LH / RH <i>new</i>	2 \$	92.00	+
14	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2 \$	484.00	+
15	HEADLIGHT COVER CAP - LH / RH <i>new</i>	2 \$	104.00	+
16	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>new</i>	\$	754.00	✓ 602.80
17	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$	215.00	✓ 172.00
18	FRONT BUMPER BRACKET HOLDER - LH / RH <i>new</i>	2 \$	474.00	? ✓ 373.40
19	FRONT BUMPER COVER <i>new</i>	\$	112.00	✓ 89.20
20	FRONT BUMPER SUPPORT <i>new</i>	2 \$	23.00	? ✓ 17.92
SUB TOTAL SPARE PARTS		:	\$ 10,012.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 61831

S/N	Parts Description		Damaged Parts & Prices		Remarks
			S/Nett		
21	AIRCON STICKER	NEC	\$	18.00	✓ 14.00
22	CAUTION SIGN STICKER	NEC	\$	13.00	✓ 9.76
23	FRONT PARKING AID SENSOR - INNER	2	\$	419.00	+
24	FRONT PARKING AID SENSOR - OUTER	2	\$	462.00	+
25	FRONT BUMPER WIRING SET		\$	532.00	+
26	SIGNAL HORN - LH LOW TONE		\$	262.00	? X
27	SIGNAL HORN - RH HIGH TONE		\$	215.00	? X
28	SPRING SHACKLE - LH / RH	2	\$	86.00	? X
29	BONNET		\$	4,965.00	✓ 3972.00
30	BONNET ATTACHMENT PARTS		\$	161.00	? X
31	BONNET LID HINGE - LH / RH	2	\$	292.00	+
32	BONNET GAS FILLED STRUT	2	\$	217.00	+
33	BONNET CATCH HOOK		\$	127.00	+
34	BONNET LOCK BAR	2	\$	90.00	+
35	BONNET CATCH HOOK		\$	16.00	+
36	BONNET LID LOCK	2	\$	391.00	+
37	HOOD MICRO SWITCH	2	\$	133.00	+
38	BONNET BOWDEN CABLE - CENTRE		\$	53.00	+
39	BONNET LID LOCK CABLE		\$	67.00	+
40	HEADLIGHT MOUNTING - LH / RH	2	\$	214.00	✓ 171.20
SUB TOTAL SPARE PARTS			:	\$	8,733.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 61831

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remarks
41	LED HEADLIGHT - LH / RH	Cracked	2	\$ 17,214.00	✓ 13,771.20
42	DIPPED BEAM POWER MODULE	Not new		\$ 508.00	+
43	DAY DRIVING LIGHTS POWER MODULE	Damaged.		\$ 520.00	✓ 415.60
44	HEADLAMP FANS - RH	Not new		\$ 363.00	+
45	HEADLAMP REPAIR KIT - RH	Not new		\$ 31.00	? X
46	HEADLAMP ASSEMBLY SPACER	Not new	2	\$ 77.00	? X
47	HEADLAMP ASSEMBLY ADJUSTER	Not new		\$ 42.00	? X
48	HEADLAMP HOSE	Not new		\$ 38.00	+
49	HEADLAMP BRACKET	Not new		\$ 26.00	? X
50	LIFT CYLINDER - LH / RH	Not new	2	\$ 432.00	+
51	HEADLIGHT HOSE	Not new		\$ 426.00	+
52	LOCK CARRIER	Cracked.		\$ 1,140.00	? ✓ 912.00
53	COOLANT REGULATOR SUPPORT	Not new	2	\$ 67.00	? X
54	EXTERNAL TEMPERATURE SENSOR	Not new		\$ 57.00	? X
55	TEMPERATURE SENSOR BRACKET	Not new		\$ 21.00	? X
56	AIRCON CONDENSER	Dented		\$ 689.00	✓ 551.20
57	HIGH PRESSURE SAFETY SWITCH VALVE	Not new		\$ 48.00	? X
58	PRESSURE SENDER	Not new		\$ 175.00	? X
59	RADIATOR	Bent.		\$ 775.00	? ✓ 632.80
60	RADIATOR RUBBER BUSH - UPPER	Not new	2	\$ 12.00	? ✓ 9.92
SUB TOTAL SPARE PARTS			:	\$ 22,661.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 6183 J

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remarks
61	RADIATOR RUBBER BUSH - CENTRE <i>Neu</i>	2	\$	18.00 ?	✓ 14.56
62	RADIATOR RUBBER BUSH - LOWER <i>Neu</i>	2	\$	24.00 ?	✓ 19.36
63	READY MIX COOLANT <i>Neu</i>	4	\$	84.00 ?	✓ 67.20
64	CHARGE AIR COOLER <i>Neu</i>		\$	513.00 ?	X
65	PRESSURE HOSE - RH <i>Neu</i>		\$	320.00 +	
66	PRESSURE HOSE - LH <i>Neu</i>		\$	150.00 +	
67	RADIATOR TWIN FAN RING <i>Neu</i>		\$	237.00 ?	X
68	RADIATOR FAN <i>Neu</i>		\$	811.00 ?	X
69	RADIATOR FAN <i>Neu</i>		\$	700.00 ?	X
70	RADIATOR AIR GUIDE - LH / RH <i>incl.</i>	2	\$	50.00 ?	✓ 41.28
71	RADIATOR COVER - UPPER CENTRE <i>Neu</i>		\$	27.00 ?	X
72	RADIATOR SEALING STRIP <i>Neu</i>		\$	21.00 ?	X
73	RADIATOR AIR GUIDE - RH FRONT <i>incl.</i>		\$	24.00 ?	✓ 18.64
74	RADIATOR INTAKE AIR DUCT - RH FRONT <i>Neu</i>		\$	79.00 +	
75	RADIATOR AIR FILTER <i>Neu</i>		\$	266.00 +	
76	RADIATOR AIR INTAKE HOSE <i>Neu</i>		\$	150.00 +	
77	RADAR SENSOR COVER FRAME - RH <i>Neu</i>		\$	12.00 ?	X
78	RADAR SENSOR COVERFRAME - LH <i>Neu</i>		\$	12.00 ?	X
79	DISTANCE REGULATION CONTROL UNIT - RH <i>Neu</i>		\$	6,177.00 ?	X
80	DISTANCE REGULATION CONTROL UNIT - LH <i>Neu</i>		\$	5,432.00 ?	X
81	FENDER STONE GUARD FILM - LH / RH <i>Neu</i>	2	\$	220.00 +	✓ 176.00
82	FRONT NO PLATE <i>Perfed</i>	S/N	\$	40.00 ✓	
83	SUNDRIES <i>Neu</i>		\$	500.00 ?	✓ 20.08

TOTAL SPARE PARTS

: \$ 57,273.00

TOTAL LABOUR CHARGES

: \$ 13,532.00

GRAND TOTAL

: \$ 70,805.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

74,115.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lim

Surveyed Date

: 14/01/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 07 Days (Without Lock Certier)
10 Days (With Lock Certier)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No: 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0046/2020/NS

Date

21-Jan-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SKE 6183 J

Model No

Audi A6 1.8 TFSI S-Tronic

Quantity Description

Unit Price

Amount

Parts

1 Rhs front fender *Buckled*

\$ 1,310.00 ✓ 1048.00

\$ 1,310.00

Labours

1 To remove and renew rhs front fender.

\$ ~~1,200.00~~ 500

2 To repair lhs front fender.

\$ 800.00 X

Labour total

\$ 2,000.00

Part total

\$ 1,310.00

TOTAL

\$ 3,310.00

For Premium Automobiles Pte Ltd

Adrian
LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12/01/20

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26086

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0046/2020/NS
Date : 13-Jan-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Seow Yen Choon Kelvin
Address : 84 St Patrick's Road
#01-39
Singapore 424183
Telephone : HP +65 83687687
Type of Claim : Own Damage Claims
Policy No. : 1800098325-01
Vehicle No : **SKE 6183 J**
Model Code : Audi A6 1.8 TFSI S-Tronic
Model / Year : 17/8/2018
Engine No : CYG 023275
Chassis No : WAUZZZ4G3JN036761
Mileage : 25712
Date In : 13-Jan-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jan-20
Place of Accident : ECP Slip Road Onto MCE Entrance

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 6183 I

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow vehicle from accident scene.	S/N \$ 280.00	X.
2	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
3	To remove and renew aircond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,400.00	? ✓
4	To dismantle and renew front bumper, both headlights and bonnet. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 5,600.00	1500 (Without Lock Carrier) 2750 (With Lock Carrier)
SUB TOTAL LABOUR CHARGES		: <u>\$ 7,760.00</u>	+ RH fender change.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKE 61831

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To respray front bumper, front bumper lower spoiler, hinges, both front fender and bonnet. X X X X	\$ 5,300.00	1100 + Spray 2 fender
6	To renew and configure both front bumper and radar sensor.	S/N \$ 280.00	?
7	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 13,532.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 61831

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>distorted</i>	\$ 2,787.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 491.00	+
3	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	\$ 116.00	+
4	LOCKING CLIP ?	14 \$ 51.00	?
5	FRONT BUMPER ADAPTER - LH / RH ?	2 \$ 68.00	?
6	FRONT BUMPER CLOSING ELEMENT ?	\$ 199.00	?
7	FRONT BUMPER SPOILER <i>new</i>	\$ 227.00	+
8	FRONT BUMPER SPOILER TRIM <i>new</i>	\$ 860.00	+
9	RADIATOR GRILLE <i>crushed</i>	\$ 1,766.00	✓
10	RADIATOR GRILLE COVER <i>crushed</i>	\$ 33.00	✓
11	RADIATOR GRILLE SENSOR SUPPORT <i>LH/RH FRONT</i> <i>new</i>	2 \$ 122.00	?
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 \$ 1,034.00	+
13	AIR GUIDE GRILLE COVER - LH / RH <i>new</i>	2 \$ 92.00	+
14	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2 \$ 484.00	+
15	HEADLIGHT COVER CAP - LH / RH <i>new</i>	2 \$ 104.00	+
16	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Best</i>	\$ 754.00	✓
17	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	\$ 215.00	✓
18	FRONT BUMPER BRACKET HOLDER <i>LH/RH</i> <i>new</i>	2 \$ 474.00	?
19	FRONT BUMPER COVER <i>crushed</i>	\$ 112.00	✓
20	FRONT BUMPER SUPPORT <i>new</i>	2 \$ 23.00	?

SUB TOTAL SPARE PARTS

: \$ 10,012.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 61831

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	AIRCON STICKER	NEC \$	18.00	✓
22	CAUTION SIGN STICKER	NEC \$	13.00	✓
23	FRONT PARKING AID SENSOR - INNER	2 \$	419.00	+
24	FRONT PARKING AID SENSOR - OUTER	2 \$	462.00	+
25	FRONT BUMPER WIRING SET	\$	532.00	+
26	SIGNAL HORN - LH LOW TONE	\$	262.00	?
27	SIGNAL HORN - RH HIGH TONE	\$	215.00	?
28	SPRING SHACKLE - LH / RH	2 \$	86.00	?
29	BONNET	\$	4,965.00	✓
30	BONNET ATTACHMENT PARTS	\$	161.00	?
31	BONNET LID HINGE - LH / RH	2 \$	292.00	+
32	BONNET GAS FILLED STRUT	2 \$	217.00	+
33	BONNET CATCH HOOK	\$	127.00	+
34	BONNET LOCK BAR	2 \$	90.00	+
35	BONNET CATCH HOOK	\$	16.00	+
36	BONNET LID LOCK	2 \$	391.00	+
37	HOOD MICRO SWITCH	2 \$	133.00	+
38	BONNET BOWDEN CABLE - CENTRE	\$	53.00	+
39	BONNET LID LOCK CABLE	\$	67.00	+
40	HEADLIGHT MOUNTING (LH / RH)	2 \$	214.00	?
SUB TOTAL SPARE PARTS		:	\$ 8,733.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 6183 I

S/N Parts Description		Damaged Parts & Prices		Remarks
S/N	Parts Description	S/	Nett	
41	LED HEADLIGHT - LH / RH <i>cracked</i>	2	\$ 17,214.00	✓
42	DIPPED BEAM POWER MODULE		\$ 508.00	+
43	DAY DRIVING LIGHTS POWER MODULE		\$ 520.00	+
44	HEADLAMP FANS - RH		\$ 363.00	+
45	HEADLAMP REPAIR KIT - RH		\$ 31.00	?
46	HEADLAMP ASSEMBLY SPACER	2	\$ 77.00	?
47	HEADLAMP ASSEMBLY ADJUSTER		\$ 42.00	?
48	HEADLAMP HOSE <i>new</i>		\$ 38.00	+
49	HEADLAMP BRACKET		\$ 26.00	?
50	LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 432.00	+
51	HEADLIGHT HOSE <i>new</i>		\$ 426.00	+
52	LOCK CARRIER <i>? over</i>		\$ 1,140.00	?
53	COOLANT REGULATOR SUPPORT	2	\$ 67.00	?
54	EXTERNAL TEMPERATURE SENSOR		\$ 57.00	?
55	TEMPERATURE SENSOR BRACKET		\$ 21.00	?
56	AIRCON CONDENSER <i>Dented</i>		\$ 689.00	✓
57	HIGH PRESSURE SAFETY SWITCH VALVE		\$ 48.00	?
58	PRESSURE SENDER		\$ 175.00	?
59	RADIATOR <i>photo. Boat</i>		\$ 775.00	?
60	RADIATOR RUBBER BUSH - UPPER <i>photo.</i>	2	\$ 12.00	?
SUB TOTAL SPARE PARTS		:	\$ 22,661.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 61831

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
61	RADIATOR RUBBER BUSH - CENTRE <i>photo to</i>	2	\$ 18.00	?
62	RADIATOR RUBBER BUSH - LOWER <i>photo</i>	2	\$ 24.00	?
63	READY MIX COOLANT	4	\$ 84.00	?
64	CHARGE AIR COOLER		\$ 513.00	?
65	PRESSURE HOSE - RH <i>men</i>		\$ 320.00	+
66	PRESSURE HOSE - LH		\$ 150.00	+
67	RADIATOR TWIN FAN RING		\$ 237.00	?
68	RADIATOR FAN		\$ 811.00	?
69	RADIATOR FAN		\$ 700.00	?
70	RADIATOR AIR GUIDE <i>LH RH</i> <i>de</i>	2	\$ 50.00	?
71	RADIATOR COVER - UPPER CENTRE		\$ 27.00	?
72	RADIATOR SEALING STRIP		\$ 21.00	?
73	RADIATOR AIR GUIDE - RH FRONT		\$ 24.00	?
74	RADIATOR INTAKE AIR DUCT - RH FRONT <i>men</i>		\$ 79.00	+
75	RADIATOR AIR FILTER <i>men</i>		\$ 266.00	+
76	RADIATOR AIR INTAKE HOSE <i>men</i>		\$ 150.00	+
77	RADAR SENSOR COVER FRAME - RH		\$ 12.00	?
78	RADAR SENSOR COVERFRAME - LH		\$ 12.00	?
79	DISTANCE REGULATION CONTROL UNIT - RH		\$ 6,177.00	?
80	DISTANCE REGULATION CONTROL UNIT - LH		\$ 5,432.00	?
81	FENDER STONE GUARD FILM - LH / RH <i>at the</i>	2	\$ 220.00	+
82	FRONT NO PLATE <i>perfed</i>	S/N	\$ 40.00	✓
83	SUNDRIES		\$ 500.00	?

TOTAL SPARE PARTS

: \$ 57,273.00

TOTAL LABOUR CHARGES

: \$ 13,532.00

GRAND TOTAL

: \$ 70,805.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.